

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A**AAD2001-214***Not Notified
Resurvey Blueprint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

29 JAN 2020

SHD 9231A

JTDKB3FU403083400

TOYOTA

PRIUS

25.1.2020

AIG

30/8/2019

PART		LIST	
1	FRONT BUMPER	\$	Bu 516.00 ✓
1	FRONT BUMPER SIDE RETAINER RH	\$	Dr 80.10 ✓
1	REINFORCEMENT, FRONT BUMPER	\$	n Bu 716.60 X
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	n 246.10 X
1	ABSORBER, FRONT BUMPER, LOWER	\$	Sn 132.70 X
1	ABSORBER, FRONT BUMPER ENERGY	\$	Sn 79.60 X
1	COVER SUB-ASSY, ENGINE, NO.1	\$	Sn 472.40 X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	Sn 241.90 X
1	EXTENSION, FRONT BUMPER, RH	\$	Sn 120.10 X
1	FRONT LED LAMP (LOWER) RH	\$	• 951.40 ?
1	FRONT HEADLAMP RH	\$	2,637.60 ?
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	Sn 960.50 X
1	MOTOR, HEADLAMP LEVELING, RH	\$	Sn 487.50 X
1	FRONT FENDER RH	\$	Bu 977.80 ✓
1	LINER, FRONT FENDER, RH	\$	Dr 206.70 —
1	FRONT FENDER EMBLEM RH	\$	n 54.60 —
1	FRONT BONNET	\$	n 983.10
1	HINGE ASSY, HOOD, RH	\$	n 58.90
1	GRILLE SUB-ASSY, RADIATOR	\$	Sn 346.00
1	EMBLEM ASSY, RADIATOR GRILLE	\$	Sn 90.80
1	GRILLE, RADIATOR, LOWER NO.1	\$	Sn 170.10
1	JAR ASSY, WINDSHIELD WASHER	\$	Sn 219.10
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	Sn 292.40
1	INLET SUB-ASSY, WASHER	\$	Sn 67.00
TOTAL		\$	11,109.00
25%		\$	2,777.25
		\$	8,331.75

Special Nett**Trans-cab Auto Services Pte Ltd****AAD2001-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

1 FRONT WHEEL RIM	\$	<i>PL</i> 1,879.40	X
1 FRONT WHEEL RIM COVER	\$	<i>CM</i> 211.50	✓
1 FRONT TYRE 195/65/15	\$	<i>PL</i> 350.00	X
1SET CLIP, FRONT FENDER LINER	\$	<i>NE</i> 35.00	✓
1 FRONT NUMBER PLATE WITH MOULDING	\$	<i>PL</i> 200.00	X
1SET BUMPER CLIP FRT	\$	<i>NE</i> 66.00	✓
1SET FRONT BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	✓
TOTAL	\$	2,776.90	

TOTAL PARTS	\$	11,108.65
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	6,000.00	<i>4001</i>
----	----------	-------------

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	<i>nn</i> 380.00	X
----	------------------	---

To transfer of Fender fittings, attachments and perform water seepage test.

\$	<i>h</i> 170.00	X
----	-----------------	---

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$	<i>h</i> 170.00	X
----	-----------------	---

To transfer of Bonnet fittings, attachments and perform water seepage test.

\$	<i>h</i> 170.00	X
----	-----------------	---

To check steering geometry and computer wheel alignment

\$	220.00	<i>601</i>
----	--------	------------

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	<i>h</i> 380.00	X
----	-----------------	---

Putty And Spray Painting Of The Affected Portion.

\$	6,000.00	<i>4401</i>
----	----------	-------------

Trans-cab Auto Services Pte Ltd**AAD2001-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2cl
To Rust-Proofing Of The Affected Areas.	\$	170.00	3cl
TOTAL	\$	14,000.00	
Over All Total	\$	25,108.65	

(PART-BY-PART) Repair Days~~20 days~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: