Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

P/P = \$2,673.90

Not Norhanhi Resurry Bepaint

AAD2001-214

	1 /1	$- \psi Z, 075.50$					
	Vehicle No.:		SHD	9231A			
	Chassis No.:	200	JTDK	B3FU4	03083	3400	
	Vehicle Make:	2 9 JAN 2020	TOY	ATC			
	Vehicle Model:		PRIU	S			
	Date of Accident :		25.1.	2020			
	Third Party Insurer :		AIG				
	Date of Registration :		30/8	/2019			
	PART				ST		
1	FRONT BUMPER		\$		n	516.00	
1	FRONT BUMPER SIDE RETAINER RH		\$		Diy	80.10	-
1	REINFORCEMENT, FRONT BUMPER		\$	n.	3-0	716.60	X
1	REINFORCEMENT, FRONT BUMPER, NO	.2	\$		n	246.10	
1	ABSORBER, FRONT BUMPER, LOWER		\$		5~	132.70	×
1	ABSORBER, FRONT BUMPER ENERGY		\$		Sa	79.60	×
1	COVER SUB-ASSY, ENGINE, NO.1		\$			472.40	
1	COVER SUB-ASSY, ENGINE UNDER, NO.	2	\$			241.90	
1	EXTENSION, FRONT BUMPER, RH		\$		Sh	120.10	
1	FRONT LED LAMP (LOWER) RH		\$		•	951.40	XSVC
1	FRONT HEADLAMP RH		\$,637.60	X svc
1	COMPUTER SUB-ASSY, HEADLAMP, RH	NO.1	\$		re-	960.50	
1	MOTOR, HEADLAMP LEVELING, RH		\$		Sz.	487.50	X
1	FRONT FENDER RH		\$		13	977.80	
1	LINER, FRONT FENDER, RH		\$		Dri	206.70	_
1	FRONT FENDER EMBLEM RH		\$		na	54.60	
1	FRONT BONNET		\$		R	983.10)
1	HINGE ASSY, HOOD, RH		\$		n	58.90	
1	GRILLE SUB-ASSY, RADIATOR		\$		Sa	346.00	1
1	EMBLEM ASSY, RADIATOR GRILLE		\$		Sa	90.80	X
1	GRILLE, RADIATOR, LOWER NO.1		\$		25	170.10	
1	JAR ASSY, WINDSHIELD WASHER		\$		SL	219.10	
1	MOTOR AND PUMP ASSY, WINDSHIELD	WASHER	\$		J.	292.40	(
1	INLET SUB-ASSY, WASHER		\$		Su	67.00)
		TOTAL	- \$		11,	109.00	
		25%			2,	777.25	
			\$		8,	331.75	

5	ne	cial	N	ett
3	μc	Ciai	1.4	ell

Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G SHD 9231A	AAD2001-214
1 FRONT WHEEL RIM	\$ 1,879.40 X
1 FRONT WHEEL RIM COVER	\$ CM 211.50
1 FRONT TYRE 195/65/15	\$ 5° 350.00 €
1SET CLIP, FRONT FENDER LINER	\$ MG 35.00
1 FRONT NUMBER PLATE WITH MOULDING	\$ ∫_ 200.00 X
1SET BUMPER CLIP FRT	\$ nec 66.00 -
1SET FRONT BUMPER RETAINER CLIP	\$ na 35.00
TOTAL	\$ 2,776.90
TOTAL PARTS	\$ 11,108.65
LABOUR	
Panel Beating, Knocking And Straightening The Necessary	
Portion, Remove And Renewal Of Parts, Adjust And Realign The	
Same	\$ 6,000.00 4001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ Na 380.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$ 5 170.00 X
To transfer of Front Bumper fittings, attachments and perform	
water seepage test.	\$ 5 170.00 X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$ △ 170.00 X
To check steering geometry and computer wheel alignment	\$ 220.00 601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ 5 380.00 ⊀
Putty And Spray Painting Of The Affected Portion.	\$ 6,000.00 4401

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

(PART-BY-PART) Repair Days	20 days	
Over All Total	\$ 25,108.65	
TOTAL	\$ 14,000.00	
To Rust-Proofing Of The Affected Areas.	\$ 170.00	301
To Check Electrical Lighting Concerned.	\$ 170.00	201
To transfer of tire, rim and on wheel balancing.	\$ ~ ~ 170.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification spis allowed
- Supplementary leaving must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: