

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5337K**AAD2001-213***Not Authored**11 Sep 8 3150h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

*29 JAN 2020***SHC 5337K**

VF1ABL15AUC279348

RENAULT

LATITUDE

27.1.2020

AIG

15/9/2014

	PART		LIST	
1	BUMPER COVER REAR	\$	<i>Buc</i> 561.70	✓
1	BUMPER LOWER REAR	\$	<i>SL</i> 411.90	X
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10	X
1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10	X
1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80	X
1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60	X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80	X
1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20	X
1	BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60	X
1	BUMPER BEAM REAR	\$	<i>Bz</i> 547.80	✓
1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 114.50	} X
1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 100.90	
1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 745.80	
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>SL</i> 404.56	
1	TAILLAMP RH	\$	<i>SL</i> 313.10	
1	TAILLAMP PANEL RH	\$	<i>N</i> 401.40	} X
1	TAILLAMP LH	\$	<i>SL</i> 401.40	
1	TAILLAMP PANEL LH	\$	<i>N</i> 401.40	
1	BOOT REAR	\$	<i>Bz</i> 1,677.20	✓
1	BOOT FINISHER	\$	<i>SL</i> 344.70	X
1	BOOT WHEATERSTRIP	\$	<i>SL</i> 178.20	X
1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70	X
1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70	X
1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 82.40	—
1	BOOT BADGE	\$	<i>N</i> 95.80	✓

Trans-cab Auto Services Pte Ltd**AAD2001-213**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5337K

1	BOOT STRUT LH	\$	Ph	145.10	}	X
1	BOOT STRUT RH	\$	Sh	145.10		
1	BOOT HINGE LH	\$	N	254.20		
1	BOOT HINGE RH	\$	N	253.80		
2	BOOT RUBBER PLUG	\$	Sh	139.90		
2	LICENCE PLATE LAMP	\$	Sh	26.30		
1	BOOT LOCK LINKAGE	\$	Sh	20.60		
1	BOOT LOCK LINKAGE HOLDER	\$	Sh	99.50		
1	BOOT INNER TRIM BOARD	\$	Sh	611.00		
1	BOOT SWITCH	\$	Sh	113.00		
1	BOOT LOCK	\$	N	246.60		
1	BOOT LOCK CATCH	\$	N	41.70		
1	EXHAUST CAP REAR	\$	Sh	125.40		
1	EXHAUST REAR	\$	N	5,263.60		
1	SPARE WHEEL PANEL	\$	N	1,229.40		
1	SPARE TYRE BOARD	\$	Sh	680.90		
1	SPARE WHEEL PANEL TRIM	\$	Sh	612.21		

TOTAL	\$	17,754.67
10%	\$	1,775.47
	\$	15,979.20

Special Nett

1SET	PARKING AID	\$	Sh	700.00	X
1SET	REAR BUMPER CLIP	\$	N	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00	✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N	10.00	X
1SET	BUMPER RETAINER RH CLIP RR	\$	N	20.00	X
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	N	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	N	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	N	66.00	✓
1	BOOT STICKER "Trans-cab"	\$	N	30.00	✓

Trans-cab Auto Services Pte Ltd**AAD2001-213**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5337K

1	BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	✓
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	80.00	} X
1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
1	BOOT INNER TRIM CLIP	\$	<i>nn</i>	45.00	
1SET	BOOT FINISHER CLIP	\$	<i>nn</i>	24.20	
1	TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	
1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
1	Rear Bumper Protector	\$	<i>nn</i>	100.00	
1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	16.00	
1	EXHAUST BRACKET REAR	\$	<i>nn</i>	24.80	
1SET	Rear licence plate with holder	\$	<i>nn</i>	80.00	}
1	REAR RENAULT TYRE 215/60/16	\$	<i>nn</i>	300.00	
1	REAR RENAULT TYRE RIM	\$	<i>nn</i>	380.00	
1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i>	385.00	
1	SPARE TYRE	\$	<i>nn</i>	330.00	
TOTAL		\$		2,982.00	

TOTAL PARTS \$ 18,961.20**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>601</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-213**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5337K

To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>4000</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To repair and realign rear exhaust pipe.	\$	<i>4</i> 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	X
Putty and spray painting of the affected portion.	\$	7,500.00	<i>4400</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>4</i> 380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>4</i> 170.00	X

TOTAL \$ 18,230.00**Over All Total \$ 37,191.20****LUMP SUM (REPAIR DAY) 25 DAYS***2 1/2 days*

LKK Auto Consultant
the Repairer of the vehicle

- To restrain balance and speed
- To disassemble and replace parts
- Parts to be replaced subject to
- The repair is on a "V"
- The location(s) is
- The repair from(s) must
- The repair must have approval

Accepted by Repairer
Signature