

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 197500270H
YEW CHOON PTE LTD
NO 8 PIONEER SECTOR 1

SINGAPORE 628420
TEL : 68611808 FAX :
PH : 85111816
ATTN :

Term:

ESTIMATE BILL

Number : EB00005405
Date : 23/01/2020
Case No : AD00010931
Vehicle No : SKL9054S
Chassis : JTHBL46F405127385
Year of Mfr : 2013
Policy No :
Model : LEXUS LS460 4.6 (A)

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR DOOR PILLAR CENTER PILLAR LH R	1.0	987.15	10	888.44
2	REAR DOOR LH Body	1.0	1,102.95	10	992.66
3	REAR DOOR TOP HINGE LH n1	1.0	165.10	10	148.59
4	REAR DOOR BOTTOM HINGE LH n1	1.0	666.35	10	599.72
5	REAR DOOR CHECKER LH n1	1.0	240.10	10	216.09
6	REAR DOOR OUTER CHROME LH bent	1.0	166.40	10	149.76
7	REAR DOOR PROTECTOR CHROME LH sel	1.0	570.81	10	513.73
8	REAR DOOR OUTER HANDLE LH SCR	1.0	487.60	10	438.84
9	REAR DOOR OUTER HANDLE SMALL LH cut	1.0	180.51	10	162.46
10	REAR DOOR OUTER HANDLE SENSOR n1	1.0	509.10	10	458.19
11	REAR DOOR INNER BRACKET LH n1	1.0	66.10	10	59.49
12	REAR DOOR HANDLE RUBBER WASHER n1	2.0		10	
13	REAR DOOR TRIMBOARD LH n1	1.0	2,870.86	10	2,583.77
14	REAR DOOR LOCK LH twi/gm	1.0	980.51	10	882.46
15	REAR DOOR GLASS PILLAR Garnish CR 655.10	1.0	587.69	10	528.92
16	REAR DOOR GLASS CHAMBER LH n1	1.0	420.51	10	378.46
17	REAR DOOR OUTER STAND GARNISH LH n1	1.0	166.15	10	149.54
18	REAR DOOR GLASS LH n1	1.0	987.60	10	888.84
19	REAR DOOR QUARTER GLASS n1	1.0	681.90	10	613.71
20	ROCKER PANEL LH R	1.0	1,487.96	10	1,339.16
21	ROCKER GARNISH LH cut	1.0	727.15	10	654.44
22	REAR DOOR STEP GARNISH LH n1	1.0	215.10	10	193.59
23	REAR DOOR RUBBER LH nel 311.10	1.0	599.15	10	539.24
24	REAR DOOR PILLAR RUBBER LH n1	1.0	687.90	10	619.11
25	REAR DOOR REGULATOR GEAR LH sel 399.10	1.0	599.45	10	539.51
26	REAR DOOR REGULATOR MOTOR LH gm 725.10	1.0	877.21	10	789.49
27	REAR BRAKE DISC ROTOR LH n1	1.0	808.15	10	727.34
28	REAR WHEEL BEARING LH n1	1.0	758.10	10	682.29
29	REAR BRAKE DISC PAD LH n1	1.0	399.10	10	359.19
30	REAR FENDER LH Body 1459.50	1.0	1,870.56	10	1,683.50
31	REAR FENDER INNER SHIELD LH n1	1.0	395.40	10	355.86
32	REAR WINDSCREEN GLASS MOULDING nel 188.10	1.0	299.10	10	269.19
33	REAR BUMPER cut	1.0	922.30	10	830.07
34	REAR BUMPER RETAINER LH n1	1.0	145.10	10	130.59

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: 197500270H

YEW CHOON PTE LTD
NO 8 PIONEER SECTOR 1

SINGAPORE 628420
TEL: 68611808 FAX:
PH: 85111816
ATTN:

ESTIMATE BILL

Number: EB00005405
Date: 23/01/2020
Case No: AD00010931
Vehicle No: SKL9054S
Chassis: JTHBL46F405127385
Year of Mfr: 2013
Policy No:
Model: LEXUS LS460 4.6 (A)

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
35	REAR CONTROL ARM LH <i>Set 488.20</i>	3.0	699.15	10	1,887.71
36	REAR UPPER ARM LH <i>Set 525.30</i>	1.0	758.00	10	682.20
37	REAR LOWER ARM LH <i>Set 845.20</i>	1.0	899.53	10	809.58
38	REAR SHOCK ABSORBER LH <i>11</i>	1.0	2,870.51	10	2,583.46
39	REAR DRIVE SHAFT LH <i>11</i>	1.0	1,988.40	10	1,789.56
40	REAR AXLE <i>11</i>	1.0	6,977.15	10	6,279.44
41	FRONT BUMPER <i>CU7</i>	1.0	808.45	10	727.61
42	FRONT BUMPER RETAINER LH <i>11</i>	1.0	166.10	10	149.49
43	FRONT BUMPER RETAINER RH <i>11</i>	1.0	166.10	10	149.49
44	FRONT GRILLE WITH CHROME <i>CHE 1005.10</i>	1.0	1,870.76	10	1,683.68
45	FRONT GRILLE EMBLEM <i>11</i>	1.0	650.45	10	585.41
46	FRONT BUMPER NUMBER GARNISH <i>11</i>	1.0	603.10	10	542.79
47	FRONT ENGINE LOWER DUST COVER <i>To. 366.50</i>	1.0	560.15	10	504.14
48	FRONT BUMPER LOWER GRILLE <i>11</i>	1.0	666.15	10	599.54
List Price - Parts Sub Total					39,340.34
49	FRONT DOOR LH - REPAIR <i>11</i>	1.0			
50	REAR WHEEL RIM LH <i>20/24</i>	1.0	1,500.00	0	1,500.00
51	REAR WHEEL RIM RH <i>20/24</i>	1.0	1,500.00	0	1,500.00
52	REAR TYRE LH <i>CU7 LP 280 50%</i>	1.0	800.00	0	800.00
53	REAR TYRE RH <i>CU7 LP 280 50%</i>	1.0	800.00	0	800.00
54	FRONT NUMBER PLATE <i>2nd</i>	1.0	30.00	0	30.00
55	FRONT NUMBER PLATE HOLDER <i>Set</i>	1.0	30.00	0	30.00
56	WINDSCREEN SEALANT <i>11</i>	2.0	24.00	0	48.00
Special Nett Price - Parts Sub Total					4,708.00
Parts Total					44,048.34
57	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,800.00	0	1,800.00
58	SPRAY PAINT ON THE AFFECTED AREAS	1.0	2,500.00	0	2,500.00
59	ANTI-RUST COATING	1.0	800.00	0	800.00
60	COMPUTERISED SETTING	1.0	400.00	0	400.00
61	TO REMOVE & REFIT UNDERCARRIAGE	1.0	600.00	0	600.00
62	TO REMOVE & REFIT WINDSCREEN <i>Ren</i>	1.0	280.00	0	280.00
63	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	500.00	0	500.00
64	TO REMOVE & REFIT FUEL TANK	1.0	350.00	0	350.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

12617.56

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 197500270H
YEW CHOON PTE LTD
NO 8 PIONEER SECTOR 1

SINGAPORE 628420
TEL : 68611808 FAX :
PH : 85111816
ATTN :

ESTIMATE BILL

Number : EB00005405
Date : 23/01/2020
Case No : AD00010931
Vehicle No : SKL9054S
Chassis: JTHBL46F405127385
Year of Mfr 2013
Policy No
Model : LEXUS LS460 4.6 (A)

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
65	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
66	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
	Labour 1 Sub Total				7,560.00
SINGAPORE DOLLARS : FIFTY-FIVE THOUSAND TWO HUNDRED TWENTY AND CENTS NINETY-TWO ONLY				Less Excess	0.00
				SUBTOTAL	51,608.34
				GST 7.00%	3,612.58
				TOTAL	55,220.92

Date of accident : 21/01/2020 12:30 PM. Place : CRANWELL ROAD INFRONT CHANGI COVE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

54,735.03#

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

supp

TO : 197500270H
YEW CHOON PTE LTD
NO 8 PIONEER SECTOR 1

SINGAPORE 628420
TEL : 68611808 FAX :
PH : 85111816
ATTN :

ESTIMATE BILL

Number : EB00005410
Date : 05/02/2020
Case No : AD00010931
Vehicle No : SKL9054S
Chassis : JTHBL46F405127385
Year of Mfr : 2013
Policy No :
Model : LEXUS LS460 4.6 (A)

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT FENDER INNER SHIELD LH <i>RM X</i>	1.0		10	
2	UNDER COVER REAR FLOOR SIDE GARNISH RH <i>RM ✓</i>	1.0	681.10	10	
3	UNDER COVER REAR FLOOR SIDE GARNISH LH <i>RM ✓</i>	1.0	681.10	10	
4	UNDER SPARE TYRE COVER <i>RM ✓</i>	1.0	366.50	10	
5	EXHAUST PIPE CENTER <i>RM ✓</i>	1.0	1220.10	10	
6	REAR CONTROL ARM RH <i>Bent ✓</i>	1.0	525.30	10	
7	UNDER SEAL FRONT FENDER MAIN LH <i>RM X</i>	1.0		X 10	
8	UNDER SEAL FRONT FENDER MAIN RH <i>RM X</i>	1.0		X 10	
List Price - Parts Sub Total					0.00
Parts Total					0.00
SINGAPORE DOLLARS : ZERO AND CENTS ZERO ONLY					
Less Excess					0.00
SUBTOTAL					0.00
GST 7.00%					0.00
TOTAL					0.00

Date of accident : 21/01/2020 12:30 PM. Place : CRANWELL ROAD INFRONT CHANGI COVE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE