

ASS. REC. BY:

REF: CS/CTI 2000/649/Kd3^{N2} Special Instruction:Assigner: Kenneth

Munier

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTIDate/Time: 30/01/2020 @ 5:20pm

Estimated Cost: _____ Bill to: _____

OD: TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: SLH 3781AInsured: SGY 3627Hat Workshop m/s Hui Yang MotorTel: 64515752of 176 Sin Ming Drive # 04-02Policy No: DMPCSN16640019033Claim No: SNM 20D200539C02

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)D.O.A. 24/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 1034 on 31/1/2020Person Contacted: BelVehicle IN/OUT OUT

Date/Time	Action/Instruction	Estimated
	Estimated ☒	
	SLH 3781A - CVI/VAL19007616/UT	D.O.A. 13/03/2019
	SGY 3627H - X	
1913	1050h 11 Lms & P er email Cred: 3154.63% (75%)	

ASS. REC. BY:

REF:

CT21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLH 378A

Yr Regn:

10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS X-Trail

c.c

1897

Colour

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

143263

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNITANT 328 0002819

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

4

mm

L/Bal.

6

mm

L/Bal.

4

mm

D.O.A.

24/1/20

D.O.I.

3/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 MAR 2020

Date/Time, File Pass to?

1) 20/3/2021

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$

TP

1050/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2020		30 Jan 2020 16:52 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SPERWIN DESIGN PTE LTD, Co. Reg. No.: 200710814N		
Main Claimant:	HYMS CAR LEASING PTE LTD		
Vehicle Reg. No.:	SLH3781A	Date of Loss:	24/01/2020 16:00 - :59
Claim Type:	TP / SNM20D200539C02	Policy/Cover Note No.:	DMPCSN16640019033
Vehicle Reg. No. (Insured):	SGY3627H	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 30 January 2020 4:45 PM
To: Hui Yang Motor; 'assignments'
Subject: RE: OUR REF:SNM20D00539/SGY3627H/TKL & YOUR REF: SLH3781A -TO CONDUCT PRS
Attachments: SKM_C28720013013260.pdf

WITHOUT PREJUDICE

Dear Bel,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Thursday, January 30, 2020 4:28 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF:SNM20D00539/SGY3627H/TKL & YOUR REF: SLH3781A -TO CONDUCT PRS
Importance: High

Hi Kah Leong,

Our Choice of Surveyor os Kenneth Kong.

Thank you & Regards,
Bel

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Sent: Thursday, January 30, 2020 3:19 PM

To: hui_yang_motor@hotmail.com <hui_yang_motor@hotmail.com>

Subject: RE: OUR REF:SNM20D00539/SGY3627H/TKL & YOUR REF: SLH3781A -TO CONDUCT PRS

Without Prejudice

Dear Bel,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, January 30, 2020 3:15 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; hui_yang_motor@hotmail.com

Subject: OUR REF:SNM20D00539/SGY3627H/TKL & YOUR REF: SLH3781A -TO CONDUCT PRS

Importance: High

Dear Kah Leong,

Please conduct PRS-SLH3781A soonest possible and our Insured has not filed SAS Report.

Officer In Charge- Tan Kah Leong-DID : 6389 6193.

Dear Bel,

*** kindly quote our reference number when replying.***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hui Yang Motor <hui_yang_motor@hotmail.com>

Sent: Thursday, January 30, 2020 1:35 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Accident involving SLH3781A & SGY3627H on 24/01/2020.

Importance: High

Hi Sir,

Please refer to attached and let us know when can we arrange for surveyor.

Thank you & Regards,

Bel

Tel: 64515752

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

china
LKIC
03/02/20
Mr.

24/01/2020

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR NISSAN X-TRAIL - SLH3781A

1pc rear bumper *893.00*
1pc rear bumper sponc
1pc rear bumper reinforcement
1pc rear bumper diffused
1pc rear bumper diffused cover
2pcs rear bumper side retainer @\$68.50
2pcs rear bumper parking sensor @\$210.50
1pc rear end panel

Bu \$ 1,850.25 ✓
su \$ 133.80 X
n \$ 620.50 X
nsp \$ 650.80 X
su \$ 185.20 X
su \$ 137.00 X
shot/cm \$ 421.00 ✓
n \$ 841.00 X

Less 30%

\$ 4,839.55
\$ 2,554.92
\$ 2,284.63

wiring
tuffkote
spray painting
labour charges
Total

\$ 60.00 *15%*
na \$ 60.00 X
\$ 900.00 *22%*
\$ 900.00 *20%*
\$ 4,204.63

5307.68

Not Not hair
11 Rmg @ 1050 1050
Recovery After Paint
2 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001649/KTD3N2

Date: 27/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMPCSN16640019033

Claimant Vehicle No: SLH3781A

Insured Vehicle No: SGY3627H

Date of Loss: 24/01/2020

Nature of Claim: TP

Claim No: SNM20D200539C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH3781A

Make & Model: NISSAN X-TRAIL, 2.0 (A)

Engine No: MR20906677B

Reg. Date: 31/10/2016 (Man. Year: 2016)

Chassis No: JN1JANT32Z0002619

Colour: Metallic Silver

Odometer: 143263 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R18

Rear Tyre Size: 235/55R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,387.68	919.80	2,467.88	72.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	435.00	1,485.00	77.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,307.68	1,354.80	3,952.88	74.47
Approved Total (Overridden) (\$\$)		1,050.00		
(\$\$)	5,307.68	1,050.00	4,257.68	80.22
+ GST 7.00/7.00% (\$\$)	371.54	73.50	298.04	80.22
Nett Amount (\$\$)	5,679.22	1,123.50	4,555.72	80.22

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 03/02/2020 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2020)
Parts:	M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH3781A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,850.25 FL	*893.00 FL
2	1		*REAR BUMPER SPONGE	Serviceable	133.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	620.50 FL	*- FL
4	1		*REAR BUMPER DIFFUSED	No such part	650.80 FL	*- FL
5	1		*REAR BUMPER DIFFUSED COVER	Serviceable	185.20 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER	Serviceable	137.00 FL	*- FL
7	2		*REAR BUMPER PARKING SENSOR	Shorted/Cracked	421.00 FL	*421.00 FL
8	1		*REAR END PANEL	Repair	841.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,839.55	1,314.00
- List Item Discount on L Items 30.00/30.00% (S\$)	1,451.87	394.20
Total Parts (S\$)	3,387.68	919.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	60.00	15.00
2	TUFFKOTE	New	60.00	0.00
3	SPRAY PAINTING	New	900.00	220.00
4	LABOUR CHARGES	New	900.00	200.00
Gross Labour Cost (S\$)			1,920.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >