

# TwinCar AUTOMOTIVE PTE LTD

Liok Adrian

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MS.LEOW LAY KENG (LIAO LIQING)  
BLK 111 RIVERVALE WALK #09-13  
SINGAPORE 540111

## ESTIMATE

TP Budget Direct  
Xiao Chen

Repair Code : CLM14854

Date in : 23/01/2020

Vehicle Num. : SMQ1066K

Model : TOYOTA COROLLA ALTIS 1.6 CVT

Chassis/Eng# : MR053REH104556965/1ZRY328827

Contact : 92261183 , 97990392

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>new</i>	1	1289.00	<del>1,289.00</del>
FRONT BONNET <i>Dented.</i>	1	1140.40	1,140.40
FRONT BONNET HINGES L/R <i>new</i>	2	135.10	<del>270.20</del>
FRONT BONNET MECHANISM LOCK <i>new</i>	1	271.85	<del>271.85</del>
FRONT BONNET TOP RUBBER MOULDING <i>new</i>	1	40.00	<del>40.00</del>
FRONT BRACE PANEL <i>Best.</i>	1	182.10	182.10
FRONT BUMPER <i>Deformed.</i>	1	581.45	581.45
FRONT BUMPER LOWER GRILLE <i>new</i>	1	191.40	191.40
FRONT BUMPER REINFORCEMENT <i>Best.</i>	1	374.45	374.45
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	132.10	264.20
FRONT BUMPER SPONGE <i>cracked.</i>	1	186.10	186.10
FRONT GRILLE <i>cracked.</i>	1	595.90	<del>398.40</del> 595.90
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	65.45	65.45
FRONT GRILLE TOP GARNISH <i>new</i>	1	92.00	92.00
FRONT GRILLE TOP RUBBER MOULDING <i>new</i>	1	181.90	181.90
FRONT HEADLAMP (L.E.D) L/R <i>cracked</i>	2	2816.00	5,632.00
FRONT HEADLAMP LOWER BRACKET L/R <i>new</i>	2	132.10	<del>264.20</del>
FRONT SUPPORT PANEL <i>Buckled</i>	1	2121.40	<del>2,121.40</del> 989

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# WinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MS.LEOW LAY KENG (LIAO LIQING)  
BLK 111 RIVERVALE WALK #09-13  
SINGAPORE 540111

Contact : 92261183 , 97990392

## ESTIMATE

Repair Code : CLM14854

Date in : 23/01/2020

Vehicle Num. : SMQ1066K

Model : TOYOTA COROLLA ALTIS 1.6 CVT

Chassis/Eng# : MR053REH104556965/1ZRY328827

RADIATOR (AUTO)	1	2142.30	X	2,142.30
RADIATOR FAN BLADE	1	191.10	X	191.10
RADIATOR FAN COWLING	1	244.50	X	244.50
RADIATOR FAN MOTOR	1	394.40	X	394.40
RADIATOR TOP BRACKET	1	174.40	✓	174.40
REAR AXLE	1	2713.80	X	2,713.80
REAR BODY EXTENSION LH	1	479.30	✓	479.30
REAR BOOTLID	1	781.10	✓	781.10
REAR BOOTLID 'ALTIS' EMBLEM	1	54.10	✓	54.10
REAR BOOTLID 'COROLLA' EMBLEM	1	50.20	✓	50.20
REAR BOOTLID 'LOGO' EMBLEM	1	58.50	✓	58.50
REAR BOOTLID HINGES L/R	2	79.60	✓	159.20
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	2	17.00	X	34.00
REAR BOOTLID INNER TRIM BOARD	1	181.85	✓	181.85
REAR BOOTLID LOCK STRIKER	1	85.00	X	85.00
REAR BOOTLID MECHANISM LOCK	1	379.20	✓	379.20
REAR BOOTLID WEATHER STRIP	1	271.45	✓	271.45
REAR BUMPER	1	581.90	✓	581.90

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

MS. LEOW LAY KENG (LIAO LIQING)  
 BLK 111 RIVERVALE WALK #09-13  
 SINGAPORE 540111

Contact : 92261183 , 97990392

## ESTIMATE

Repair Code : CLM14854  
 Date in : 23/01/2020  
 Vehicle Num. : SMQ1066K  
 Model : TOYOTA COROLLA ALTIS 1.6 CVT  
 Chassis/Eng# : MR053REH104556965/1ZRY328827

REAR BUMPER REFLECTOR L/R	<i>cracked</i>	2	88	<del>141.45</del>	176	<del>282.90</del>
REAR BUMPER REINFORCEMENT	<i>Bent</i>	1		398.70		398.70
REAR BUMPER REINFORCEMENT BRACKET L/R	<i>Bent</i>	2		165.00		330.00
REAR BUMPER REVERSE SENSOR	<i>Damaged</i>	2		265.30		530.60
REAR BUMPER REVERSE SENSOR HOLDER	<i>scr</i>	2		121.10		242.20
REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>None</i>	1		250.00	X	250.00
REAR BUMPER SIDE RETAINER L/R	<i>scr</i>	2		65.00		130.00
REAR END PANEL	<i>Distorted</i>	1		781.90		781.90
REAR END PANEL ANTENNA SENSOR	<i>cracked</i>	1		175.00		175.00
REAR END PANEL INNER TOP GARNISH	<i>Distorted</i>	1		185.99		185.99
REAR EXHAUST GASKET		1		63.20	X	63.20
REAR EXHAUST RUBBER MOUNTING	<i>2 x 1/2 Nec</i>	2		63.90	X	127.80
REAR EXHAUST SILENCER BOX		1		1255.00	X	1,255.00
REAR FENDER INNER SHIELD L/R	<i>LH Deformed</i>	2		231.50	231.50	<del>463.00</del>
REAR FENDER INNER TRIM L/R	<i>LH Crumpled, RH not mtr</i>	2		338.00	338	<del>676.00</del>
REAR FENDER L/R	<i>LH Distorted, RH Repair</i>	2		656.00	656	<del>1,312.00</del>
REAR FLOOR PANEL	<i>Distorted</i>	1		974.45		974.45
REAR FLOOR PANEL TOP BOARD COVER	<i>deformed</i>	1		485.10		485.10

295

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MS.LEOW LAY KENG (LIAO LIQING)  
BLK 111 RIVERVALE WALK #09-13  
SINGAPORE 540111

Contact : 92261183 , 97990392

## ESTIMATE

Repair Code : CLM14854

Date in : 23/01/2020

Vehicle Num. : SMQ1066K

Model : TOYOTA COROLLA ALTIS 1.6 CVT

Chassis/Eng# : MR053REH104556965/1ZRY328827

REAR FLOOR SIDE PANEL LH	<i>Distorted</i>	1	348.90	✓	348.90
REAR LH DOOR	<i>Repair</i>	1	958.70	X	958.70
REAR LH DOOR MECHANISM LOCK	<i>Jamed</i>	1	431.60	✓	431.60
REAR LH FENDER INNER PANEL	<i>Distorted</i>	1	389.90	✓	389.90
REAR LH FENDER INNER WHEEL HOUSING	<i>Distorted</i>	1	450.30	✓	450.30
REAR LH FENDER PETROL LID	<i>ntc new</i>	1	109.70	X	109.70
REAR LH FENDER PETROL LID RIVET	<i>new</i>	2	8.00	✓	16.00
REAR LH FENDER PETROL PIPE	<i>ntc new</i>	1	215.80	X	215.80
REAR LH FENDER PETROL PIPE RUBBER	<i>deformed</i>	1	128.30	✓	128.30
REAR LH SHOCK ABSORBER	<i>new</i>	1	296.70	✓	296.70
REAR SPARE TYRE SCREW LOCK	<i>dryd</i>	1	95.70	✓	95.70
REAR TAILLAMP INNER BACK RUBBER GASKET L/R	<i>new</i>	2	25.50	✓	51.00
REAR TAILLAMP INNER PANEL L/R	<i>LH distorted</i>	2	374.85		<del>374.85</del> 749.70
REAR TAILLAMP L/R	<i>LH smashed, RH could</i>	2	391.90	✓	783.80
REAR TAILLAMP LOWER BRACKET L/R	<i>RH could</i>	2	58 88.70	✓	58 177.40
Rear Bootlid Lamp	<i>could</i>	2	339	✓	678
*** This is a computer-generated document which requires no signature.***					
Rear Bootlid Chrome Moulding	<i>could</i>	1	280.80	✓	280.80

page 4

22609.24

16956.93

# WinCar AUTOMOTIVE PTE LTD

2 Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MS.LEOW LAY KENG (LIAO LIQING)  
BLK 111 RIVERVALE WALK #09-13  
SINGAPORE 540111

Contact : 92261183 , 97990392

## ESTIMATE

Repair Code : CLM14854

Date in : 23/01/2020

Vehicle Num. : SMQ1066K

Model : TOYOTA COROLLA ALTIS 1.6 CVT

Chassis/Eng# : MR053REH104556965/1ZRY328827

		Subtotal before discount	36,587.64
Percentage discount 25%			9,146.91
		<b>Sub-total 1</b>	<b>27,440.73</b>
FRONT BUMPER CLIPS - SET	<i>new</i>	1 80.00	<del>30 80.00</del>
FRONT BUMPER NUMBER PLATE	<i>used</i>	1 25.00	✓ 25.00
FRONT BUMPER NUMBER PLATE HOLDER	<i>used</i>	1 50.00	<del>30 50.00</del>
FRONT GRILLE CLIPS - SET	<i>new</i>	1 40.00	<del>20 40.00</del>
RADIATOR COOLANT	<i>new</i>	1 80.00	<del>40 80.00</del>
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>new</i>	1 50.00	<del>30 50.00</del>
REAR BOOTLID NUMBER PLATE	<i>used</i>	1 25.00	✓ 25.00
REAR BOOTLID NUMBER PLATE HOLDER		1 50.00	<del>30 50.00</del>
REAR BUMPER CLIPS - SET	<i>new</i>	1 80.00	<del>30 80.00</del>
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>new</i>	1 30.00	<del>10 30.00</del>
REAR FENDER INNER SHIELD CLIPS L/R - SET	<i>new</i>	2 50.00	<del>20 100.00</del>
REAR FENDER INNER TRIM CLIPS L/R - SET	<i>new</i>	2 50.00	<del>30 100.00</del>
REAR FLOOR PANEL INSULATOR MAT	<i>new</i>	1 300.00	<del>20 300.00</del>
REAR LH TYRE	<i>new</i>	1 380.00	✓ 380.00
REAR TAILLAMP CLIPS L/R - SET	<i>new</i>	2 20.00	<del>20 40.00</del>
REAR WINDSCREEN SEAL	<i>new</i>	1 140.00	<del>40 140.00</del>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# WINCAR AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

MS.LEOW LAY KENG (LIAO LIQING)  
 BLK 111 RIVERVALE WALK #09-13  
 SINGAPORE 540111

Contact : 92261183 , 97990392

## ESTIMATE

Repair Code : CLM14854  
 Date in : 23/01/2020  
 Vehicle Num. : SMQ1066K  
 Model : TOYOTA COROLLA ALTIS 1.6 CVT  
 Chassis/Eng# : MR053REH104556965/1ZRY328827

REAR WINDSCREEN SEALANT	<i>MC</i>	1	80.00	<del>50</del> 80.00
				<i>630</i>
				Subtotal before discount
				1,650.00
	Percentage discount	0%		0.00
				<b>Sub-total 2</b>
				1,650.00
				<b>Parts-total</b>
				<b>29,090.73</b>

## LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector				<del>60</del> 80.00
To remove, change air con parts, vacuums, refill air con gas.				<del>120</del> 140.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)				<del>30</del> 80.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.				<del>80</del> 100.00
To remove, reinstall windscreen (REAR)				<del>120</del> 150.00
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.				<del>280</del> 380.00
To road test driving, check and resetting wheel alignments system				<del>80</del> 140.00
To remove, reinstall petrol tank. (to FR)				<del>✓</del> 80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim panish, trim liner carpet. (to FR)				<del>150</del> 180.00
To <i>panel beat</i> bodyparts, repair portion, and where consistent to the accident.				<del>2400</del> 3,600.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.				<del>1400</del> 1,600.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.				<del>600</del> 1,100.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.				<del>80</del> 100.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MS.LEOW LAY KENG (LIAO LIQING)  
BLK 111 RIVERVALE WALK #09-13  
SINGAPORE 540111

Contact : 92261183 , 97990392

## ESTIMATE

Repair Code : CLM14854  
Date in : 23/01/2020  
Vehicle Num. : SMQ1066K  
Model : TOYOTA COROLLA ALTIS 1.6 CVT  
Chassis/Eng# : MR053REH104556965/1ZRY328827

To apply anti-rust chemical on repaired and replaced panel.

500

	120	<del>160.00</del>
<b>Labour Total</b>		<b>7,890.00</b>
<b>Parts &amp; Labour Total</b>		<b>36,980.73</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

total: 23186.93  
H/S: 17K (Nett Value)  
21 Days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: