

ASS. REC. BY:

REF: CS/AGI 20001656/Asd3n2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Ivy Retilla

of

AGIDate/Time: 31/01/2020 @ 10:05am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8ME5673U

Insured:

SLU 105D

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

2 Kaki Bukit Ave 2 #01-18 Autohub

Policy No:

Claim No:

C10005337

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/01/2020

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:33am @ 31/1/2020

Person Contacted:

Melody

Vehicle

IN/OUT

Date/Time

Action/Instruction

Island (✓)SME 5673U-XSLU 105D-X

ASS. REC. BY:

REF: A9I

ASSIGNMENT

From: _____ Date: 31/01/2020
 Estimated Cost: _____
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV
 To Inspect Vehicle No: SME 5673U
 at Workshop m/s N-SI Automotive
 of 2 kaki Bukit Ave 2 # 01-18 Autobus
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS ^{wp}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME5673U Yr Regn: 2018 Oct
 Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or
 Make: Toyota Sienta C.C. 1496
 Colour: Bronze A/C: Insured / Std / NI / NA
 Sp. Reading: 24261 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MHF228H3700056696
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: 195/50R16
 R: 195/50R16

☒ BS ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>31/01/20</u>
Survey held at <u>N-SI Twiner</u>	

Des. of Damages: Frnt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct

Adrian Confirmed LIS \$5,900/- @ 6 days with Boss
 (\$6,583.29 Red - 53%)

RECEIVED 05 MAR 2020

Date/Time, File Pass to?

05/03/20

1)

Typ: sp

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: West end (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Other

TOTAL

350

Report Format:

Lump Sum / L.B.I: \$ 5,900/- LIS

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Friday, 31 January 2020 10:05 AM
To: Nivitha (LKK Auto)
Cc: 'SUR'; Loganathan Agoram
Subject: FW: SME5673U & SLU105D - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS || C10005337
Attachments: 5673.pdf; SLU105D.pdf; SME5673U.pdf

Hi Team,

We would like to arrange TP PRS for SME5673U. TP workshop has chosen Mr. Adrian Ling to survey the vehicle.

Kindly see attached file for reference.

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg

**Budget
Direct**
insurance

Gold
Trusted
Service
Award
★★★★★
2019 feelo™

Platinum
Trusted
Service
Award
★★★★★
2020 feelo™

Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Ziting <ziting@n51.com.sg>

Sent: Thursday, 30 January 2020 6:32 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Cc: Claims <claims@budgetdirect.com.sg>; Loganathan Agoram <loganathan.a@budgetdirect.com.sg>

Subject: Re: SME5673U & SLU105D - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS || C10005337

Dear Sir / Madam,

We appoint your surveyor Mr Adrian Ling from LKK Auto Consultants Pte Ltd.

Please see attached.

Thank you

Regards,

Zi Ting

N-51 Automotive Pte Ltd

TwinCar Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg

From: Ziting <ziting@n51.com.sg>

Sent: Thursday, 30 January 2020 2:46 PM

To: Claims <claims@budgetdirect.com.sg>

Subject: SME5673U & SLU105D - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer to attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,

Zi Ting


N-51 Automotive Pte Ltd

TwinCar Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 11:27
Date Of Accident	18/01/2020 12:45
Exact Location Of Accident	SERANGOON RD TO CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME5673U
Insured/Policyholder	
Name Of Registered Owner	LIM KEE ENG
NRIC No	SXXXX008D
Email Address	KEEENGLIM@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98341080
Alternative Phone No	OFFICE-98341080

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA502134
Cover Note Number	

Driver

Name of Driver	LIM CHIEW HAR
NRIC No	SXXXX516Z
Date Of Birth	09/10/1977
Occupation	INDOOR
Date Of Driving Pass	31/05/2006
Driving Experience	13 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90660525
Fax Number	
Contact Number	
Email Address	CATLIMCAT.LK@GMAIL.COM

Address	470C UPPER SERANGOON CRESCENT #15-348
Postcode	533470
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : KOK EN HUI DELICIA GENDER: : FEMALE
Passenger 2	NAME: : KOK JING XUAN VACARIE GENDER: : FEMALE
Passenger 3	NAME: : NAN AYE AYE THAN GENDER: : FEMALE
Passenger 4	NAME: : THAE SU WAI GENDER: : FEMALE
Passenger 5	NAME: : HERANI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU105D
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR

DENISE PHILIP

SXXXX221C

91806370

31 ELIAS RD #16-22

AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan


A A B


Describe Circumstances of the Accident

FROM SERANGOON RD TOWARDS CTE.
 Before REACHING CTE EXIT, THE CAR INFRONT OF
 ME BRAKED SUDDENLY. I MANAGE TO BRAKE BUT THE
 CAR BEHIND ME HIT US ON THE BACK.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date &
 Time


 Driver's Signature (if driver is not the policyholder) / Date
 & Time


 Witnessed by Reporting Centre
 Personnel

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM KEE ENG
BLK 256 SIMEI STREET 1 #06-525
SINGAPORE 520256

TP Budget Direct
Shirley

ESTIMATE

Repair Code : CLM14835

Date in : 30/01/2020

Vehicle Num. : SME5673U

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : 2NRX363464/MHFZ28H3700056696

Contact : 98341080 , 90660525

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>del</i>	1	750.00	495 ✓ 750.00
REAR BUMPER CENTER LAMP <i>del</i>	1	274.75	✓ 274.75
REAR BUMPER CENTER PROTECTOR GARNISH <i>del</i>	1	207.00	✓ 207.00
REAR BUMPER REFLECTOR L/R <i>del</i>	2	85.00	✓ 170.00
REAR BUMPER REVERSE SENSOR <i>del</i>	2	275.00	✓ 550.00
REAR BUMPER REVERSE SENSOR COVER <i>del</i>	2	68.00	✓ 136.00
REAR BUMPER SIDE PROTECTOR GARNISH L/R <i>del</i>	2	151.00	✓ 302.00
REAR BUMPER SIDE RETAINER L/R <i>del</i>	2	90.00	✓ 180.00
REAR BUMPER TOW HOOK COVER <i>del</i>	1	25.00	✓ 25.00
REAR END PANEL 'INNER' <i>del</i>	1	607.00	✓ 607.00
REAR END PANEL 'OUTER' <i>del</i>	1	599.00	✓ 599.00
REAR END PANEL KEY ANTENNA SENSOR <i>del</i>	1	127.00	✓ 127.00
REAR END PANEL TOP GARNISH <i>del</i>	1	207.00	✓ 207.00
REAR FENDER INNER TRIM BOARD L/R <i>del</i>	2	709.00	651.20 ✓ 1,418.00
REAR SPARE TYRE RETAINER LOCK <i>del</i>	1	121.00	94 ✓ 121.00
REAR SPARE WHEEL TOOL BOX <i>del</i>	1	519.00	295 ✓ 519.00
REAR SPARE WHEEL TOOL BOX TRIM BOARD <i>del</i>	1	589.00	✓ 589.00
REAR TAILGATE <i>del</i>	1	1785.00	1180 ✓ 1,785.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM KEE ENG
BLK 256 SIMEI STREET 1 #06-525
SINGAPORE 520256

Contact : 98341080 , 90660525

ESTIMATE

Repair Code : CLM14835

Date in : 30/01/2020

Vehicle Num. : SME5673U

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : 2NRX363464/MHFZ28H3700056696

REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	110.00	<i>65</i> 110.00
REAR TAILGATE 'SIENTA' EMBLEM <i>new</i>	1	110.00	<i>85</i> 110.00
REAR TAILGATE 'V' EMBLEM <i>new</i>	1	81.10	<i>64</i> 81.10
REAR TAILGATE HINGES L/R <i>new</i>	2	78.00	X 156.00
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	48.00	X 48.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	19.00	X 38.00
REAR TAILGATE INNER TRIM BOARD new <i>new</i>	1	455.00	X 455.00
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	265.00	X 265.00
REAR TAILGATE WEATHER STRIP <i>nt</i>	1	385.00	X 385.00
REAR TAILGATE WINDSCREEN MOULDING L/R <i>new</i>	2	45.00	X 90.00
REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) <i>new</i>	2	45.00	X 90.00
REAR TAILLAMP L/R <i>lt cancelled</i>	2	425.00	<i>425</i> 850.00
REAR TAILLAMP LOWER BRACKET L/R <i>cancel</i>	2	83.10	X 166.20

Subtotal before discount

11,411.05

Percentage discount 25%

2,852.76

Sub-total 1

8,558.29

REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i> 80.00
REAR END PANEL TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>10</i> 40.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM KEE ENG
BLK 256 SIMEI STREET 1 #06-525
SINGAPORE 520256

Contact : 98341080 , 90660525

ESTIMATE

Repair Code : CLM14835

Date in : 30/01/2020

Vehicle Num. : SME5673U

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : 2NRX363464/MHFZ28H3700056696

REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	60.00	<i>30</i>	120.00
REAR SPARE WHEEL INSULATOR MAT <i>new</i>	1	300.00	<i>x</i>	300.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	<i>x</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	<i>x</i>	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>x</i>	50.00
REAR TAILGATE REFLECTOR CLIPS L/R - SET <i>new</i>	2	40.00	<i>x</i>	80.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	<i>60</i>	80.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	<i>10</i>	60.00
Subtotal before discount				935.00
Percentage discount 0%				0.00
Sub-total 2				935.00
Parts-total				9,493.29

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

80 ~~100.00~~

120 ~~150.00~~

60 ~~140.00~~

800 ~~1,200.00~~

800 ~~1,200.00~~

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM KEE ENG
BLK 256 SIMEI STREET 1 #06-525
SINGAPORE 520256

Contact : 98341080 , 90660525

ESTIMATE

Repair Code : CLM14835

Date in : 30/01/2020

Vehicle Num. : SME5673U

Model : TOYOTA SIENTA ELEGANCE (AUTO)

Chassis/Eng# : 2NRX363464/MHFZ28H3700056696

To apply anti-rust chemical on repaired and replaced panel.

2000

60 120.00

To remove, reinstall tailgate mechanism and check for function

✓ 80.00

Labour Total

2,990.00

Parts & Labour Total

12,483.29

*** This is a computer-generated document which requires no signature.***

page 4

Admin King

1/3 04/02/20

06 Days.

total: 7445.21

L/S: S.SK ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI20001656/Asd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 06-03-2020 Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 105D	Veh. Inspected	SME 5673U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10005337	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	31/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MHFZ28H3700056696	Colour	BRONZE	
Odometer	24261	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/01/2020	Inspection Date	31/01/2020	
Survey held at	2 KAKI BUKIT AVE 2 #01-18 AUTOHUB			
Repairer	TWINCAR AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 5673U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	750.00	495.00
1	REAR BUMPER CENTER LAMP	CRACKED	274.75	274.75
1	REAR BUMPER CENTER PROTECTOR GARNISH	CRACKED	207.00	207.00
2	REAR BUMPER REFLECTOR L/R @\$85.00	CRACKED	170.00	170.00
2	REAR BUMPER REVERSE SENSOR @\$275.00	DAMAGED	550.00	550.00
2	REAR BUMPER REVERSE SENSOR COVER @\$68.00	NOT NECESSARY	136.00	-
2	REAR BUMPER SIDE PROTECTOR GARNISH L/R @\$151.00	DEFORMED	302.00	302.00
2	REAR BUMPER SIDE RETAINER L/R @\$90.00	NECESSARY	180.00	180.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	25.00	-
1	REAR END PANEL "INNER"	TO REPAIR SEE LABOUR	607.00	-
1	REAR END PANEL "OUTER"	DENTED	599.00	599.00
1	REAR END PANEL KEY ANTENNA SENSOR	CRACKED	127.00	127.00
1	REAR END PANEL TOP GARNISH	DEFORMED	207.00	207.00
2	REAR FENDER INNER TRIM BOARD L/R @\$709.00	N/S DEFORMED	1,418.00	651.00
1	REAR SPARE TYRE RETAINER LOCK	CUT	121.00	94.00
1	REAR SPARE WHEEL TOOL BOX	DEFORMED	519.00	295.00
1	REAR SPARE WHEEL TOOL BOX TRIM BOARD	NOT NECESSARY	589.00	-
1	REAR TAILGATE	DENTED	1,785.00	1,180.00
1	REAR TAILGATE "LOGO" EMBLEM	NECESSARY	110.00	65.00
1	REAR TAILGATE "SIENTA" EMBLEM	NECESSARY	110.00	85.00
1	REAR TAILGATE "V" EMBLEM	NECESSARY	81.10	64.00
2	REAR TAILGATE HINGES L/R @\$78.00	NOT NECESSARY	156.00	-
1	REAR TAILGATE INNER PULL HANDLE	NOT NECESSARY	48.00	-
2	REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R @\$19.00	NOT NECESSARY	38.00	-
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	455.00	-
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	265.00	265.00
1	REAR TAILGATE WEATHER STRIP	CUT	385.00	385.00
2	REAR TAILGATE WINDSCREEN MOULDING L/R @\$45.00	NECESSARY	90.00	90.00
2	REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) @\$45.00	NECESSARY	90.00	90.00
2	REAR TAILLAMP L/R @\$425.00	N/S CRACKED	850.00	425.00
2	REAR TAILLAMP LOWER BRACKET L/R @\$83.10	CRACKED	166.20	166.20

Report Ref No. CS/AGI20001656/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,852.76	-1,741.74
			8,558.29	5,225.21
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R @\$60.00 (SN)	NECESSARY	120.00	30.00
1	REAR SPARE WHEEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
2	SET REAR TAILGATE REFLECTOR CLIPS L/R @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
2	REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	10.00
			935.00	170.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	80.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,200.00	800.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE.BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR END PANEL "INNER".		1,200.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR ,FUNCTION.		80.00	80.00
			2,990.00	2,000.00
	GRAND TOTAL		12,483.29	7,395.21

Report Ref No. CS/AGI20001656/Asd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00
---	--	--	----------

Report Ref No. CS/AGI20001656/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.