

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 28.01.20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJJ7727U**
 MODEL : **TOYOTA PREVIA**
 DATE OF ACCIDENT : 25.01.20
 TIME OF ACCIDENT : 13:20HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / <i>DD</i>	1	\$ 1,609.00	\$ 1,609.00
2	REAR BUMPER SPONGE / <i>BR</i>	2	\$ 165.00	\$ 330.00
3	REAR BUMPER TOW HOOK COVER X	2	\$ 30.00	\$ 60.00
4	REAR BUMPER REFLECTOR 2 / <i>BR</i>	2	\$ 65.00	\$ 130.00
5	REAR BUMPER SIDE RETAINER (FRONT) / <i>BR</i>	2	\$ 78.10	\$ 156.20
6	REAR BUMPER SIDE RETAINER (REAR) / <i>BR</i>	2	\$ 80.00	\$ 160.00
7	REVERSE SENSOR / <i>SM</i>	2	\$ 269.00	\$ 538.00
8	REVERSE SENSOR HOLDER / <i>MC</i>	2	\$ 48.00	\$ 96.00
9	REVERSE SENSOR WIREHARNES X	1	\$ 388.00	\$ 388.00
10	TAILGATE / <i>DD</i>	1	\$ 1,854.00	\$ 1,854.00
11	TAILGATE OUTER GARNISH X	1	\$ 230.00	\$ 230.00
12	TAILGATE CENTER REFLECTOR X	1	\$ 270.00	\$ 270.00
13	TAILGATE SIDE REFLECTOR LH X	1	\$ 345.00	\$ 345.00
14	TAIL GATE LOGO / <i>MC</i>	1	\$ 75.00	\$ 75.00
15	TAIL GATE EMBLEM 'TOYOTA' / <i>MC</i>	1	\$ 72.00	\$ 72.00
16	TAIL GATE EMBLEM 'PREVIA' / <i>MC</i>	1	\$ 78.00	\$ 78.00
17	TAGILGATE EMBLEM 'GL' / <i>MC</i>	1	\$ 62.00	\$ 62.00
18	TAILGATE INNER HOLDER X	1	\$ 85.00	\$ 85.00
19	TAILGATE WINDSCREEN MOULDING (SET) / <i>MC</i>	1	\$ 160.00	\$ 160.00
20	TAILGATE STOPPER / <i>MS</i>	<i>21</i>	\$ 19.00	\$ 19.00
21	TAILGATE DAMPER X	2	\$ 140.00	\$ 280.00
22	TAILGATE TOP LOCK / <i>DT</i>	1	\$ 768.00	\$ 768.00
23	TAILGATE LOWER LOCK X	1	\$ 35.00	\$ 35.00
24	TAILGATE INNER TRIM / <i>CR4</i>	1	\$ 480.00	\$ 480.00
25	TAILGATE WEATHER STRIP / <i>TN</i>	1	\$ 360.00	\$ 360.00
26	TAIL LAMP LH X	1	\$ 370.00	\$ 370.00
27	REAR FENDER INNER TRIM / <i>BR</i>	2	\$ 680.00	\$ 1,360.00
28	REAR FENDER COWLING X	2	\$ 95.00	\$ 190.00

VEHICLE NO : **SJJ7727U**
 MODEL : **TOYOTA PREVIA**
 DATE OF ACCIDENT : 25.01.20
 TIME OF ACCIDENT : 13:20HRS

30	REAR END PANEL TOP GARNISH ✓ CRW	1	\$ 280.00	\$ 280.00
31	REAR FLOOR PANEL MAT ✓ TN	1	\$ 690.00	\$ 690.00
32	REAR FLOOR PANEL ✓ DN	1	\$ 989.00	\$ 989.00
33	REAR FLOOR PANEL TOP BOARD ✓ CRW	1	\$ 1,150.00	\$ 1,150.00
34	REAR SPARE TYRE TOP COVER ✓ TN	1	\$ 420.00	\$ 420.00

TOTAL PRICE \$ 14,759.20
 LESS 25% \$ 3,689.80
SUB TOTAL PRICE \$ 11,069.40

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE X	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET) ✓ MK	1	\$ 80.00	\$ 80.00
3	TAILGATE SEALANT X	1	\$ 120.00	\$ 120.00
4	TAILGATE OUTER GARNISH CLIP (SET) X	1	\$ 30.00	\$ 30.00
5	TAILGATE INNER TRIM BOARD CLIP (SET) X	1	\$ 50.00	\$ 50.00
6	TAILGATE WINDSCREEN SEALANT ✓ MK	1	\$ 80.00	\$ 80.00
7	TAILGATE WINDSCREEN INNER SEAL X	1	\$ 60.00	\$ 60.00
8	TAIL LAMP CLIP (SET) X	1	\$ 40.00	\$ 40.00
9	REAR FENDER INNER TRIM CLIP (SET) ✓ MK	1	\$ 50.00	\$ 50.00
10	REAR FENDER INNER COWLING CLIP (SET) ✓ MK	1	\$ 50.00	\$ 50.00
11	REAR END PANEL INSULATION SEAL ✓ MK	1	\$ 150.00	\$ 150.00
12	REAR END PANEL TOP GARNISH CLIPS (SET) ✓ MK	1	\$ 30.00	\$ 30.00
13	REAR FLOOR PANEL SEALANT ✓ MK	1	\$ 350.00	\$ 350.00
14	REAR FLOOR PANEL MAT CLIP (SET) ✓ MK	1	\$ 80.00	\$ 80.00
15	REVERSE CAMERA X	1	\$ 450.00	\$ 450.00
16	REAR SPARE TYRE X	1	\$ 350.00	\$ 350.00

TOTAL \$ 2,020.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	1200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	50
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	50

VEHICLE NO : SJJ7727U
MODEL : TOYOTA PREVIA
DATE OF ACCIDENT : 25.01.20
TIME OF ACCIDENT : 13:20HRS

5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	30
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	X
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	50
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	30
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	30

TOTAL \$4,890.00

TOTAL PARTS COST : \$ 13,089.40
TOTAL LABOUR COST : \$ 4,890.00
TOTAL REPAIR COST : \$ 17,979.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY (HP : 9856 4815)

Steve (LKK)
8322 8813
Stevechn@lkkau.com

WHL ML
28/1/20, 3-30pm
L/S
By AL SJ
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer