

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JOURNEY MOTORS
BLK 603 HOUGANG AVE 4 #04-227
SINGAPORE 530603

Contact : 98575910 , 93366733

TP 1st Cap.
Vic

ESTIMATE

Repair Code : CLM15994

Date in : 20/01/2020

Vehicle Num. : SJW7831H

Model : KIA CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR

Chassis/Eng# : KNAFU411MA5200352/G4FCAH362993

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR RH DOOR <i>vented</i>	1	1017.00	✓ 1,017.00
REAR RH DOOR BLACK TAPE (HORIZONTAL) <i>3 per</i>	1	18.00	✓ 18.00
REAR RH DOOR BLACK TAPE (VERTICAL)	1	18.00	✓ 18.00
REAR RH DOOR GLASS REGULATOR <i>new</i>	1	467.00	+ 467.00
REAR RH DOOR INNER TRIM BOARD <i>changed</i>	1	698.70	✓ 698.70
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	309.00	+ 309.00
REAR RH DOOR WEATHER STRIP <i>cut</i>	1	85.00	✓ 85.00
Subtotal before discount			2,612.70
Percentage discount 10%			261.27
Sub-total 1			2,351.43
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	30 50.00
ROCKER GARNISH CLIPS RH - SET <i>new</i>	1	60.00	X 60.00
ROCKER GARNISH RH <i>new</i>	1	550.00	+ 550.00
Subtotal before discount			660.00
Percentage discount 0%			0.00
Sub-total 2			660.00
Parts-total			3,011.43

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JOURNEY MOTORS
BLK 603 HOUGANG AVE 4 #04-227
SINGAPORE 530603

Contact : 98575910 , 93366733

ESTIMATE

Repair Code : CLM15994

Date in : 20/01/2020

Vehicle Num. : SJW7831H

Model : KIA CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR

Chassis/Eng# : KNAFU411MA5200352/G4FCAH362993

LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

80.00

600 800.00

300 500.00

80.00

1,460.00

4,471.43

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 12/02/20

04 Days

\$1k (Nett Value)
S/S.

total: 2663.03

L/S: 1k (Nett Value)