

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : AIG INSURANCE**Estimate No: EST0001097**

Date: 30 Jan 2020

Veh Reg No: **SMN2365G**

Make/Model: TOYOTA NOAH

Chassis No: ZWR800395483

Engine No: 2ZR0D98603

Reg. Date: 29/01/20

ATTN: Motor Claim Department

Your Ref No: SMN2365G

Claim Type: Third Party

Accident Date: 30.01.20

Estimate Repair Cost to Vehicle No :SMN2365G

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Rear Boot	Body 20	1 PC	1,406.40	✓
2 Rear Boot Lock	20/2m	1 PC	509.10	✓
3 Rear Boot Lock Catch	11	1 PC	114.20	X
4 Rear Boot Emblem	85.80 neu	1 PC	110.40	✓
5 Rear Boot Rubber	7~1	1 PC	399.90	✓
6 Rear Boot Inner Cover Board	20/2m	1 PC	606.40	✓
7 Rear Compartment Panel	11	1 PC	726.40	X
8 Rear Compartment Panel Top Cover Board	neu	1 PC	606.40	✓
9 Rear End Panel	655.10 Body 20	1 PC	706.10	✓
10 Rear End Panel Garnish	20/2m	1 PC	292.20	✓
11 Rear Fender Inner trims	20/2m	2 PC	1,552.40	✓
12 Rear Coner Garnish - LH	11	1 PCS	453.20	X
13 Rear Coner Garnish Clipse - LH	11	1 PCS	110.10	X
14 Rear Bumper	20/2m	1 PC	897.20	✓
15 Rear Bumper Side Retainer	11	2 PC	220.40	X
16 Rear Bumper Towing Cover	20/2m	1 PC	65.10	✓
17 Rear Bumper Sensor	315 x 20630	2 PC	1,018.20	630
18 Rear Bumper Sensor Cover	11	2 PC	58.20	X
19 Rear Bumper Lower Clipse	6.00 neu	5 PC	64.50	30.00
			9,916.80	
Less 25%			2,479.20	7,437.63 p-7736
Special Net				
20 Rear Boot Sticker	11	1 PC	100.00	X
21 Rear Bumper Top Protector Rubber	100 20/2m	1 PCS	200.00	100
22 Rear Windscreen Gum	neu	1 PC	80.00	40
			380.00	380.00

not Authorized
date
31/1/20
2/5 @ 6500
5.00

new parts replaced

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : AIG INSURANCE

ATTN: Motor Claim Department
Your Ref No: SMN2365G
Claim Type: Third Party
Accident Date: 30.01.20

Estimate No: EST0001097
Date: 30 Jan 2020
Veh Reg No: SMN2365G
Make/Model: TOYOTA NOAH
Chassis No: ZWR800395483
Engine No: 2ZR0D98603
Reg. Date: 29/01/20

Estimate Repair Cost to Vehicle No :SMN2365G

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
23 Panel Beating	1,300.00	1 PC	1,300.00	600
24 Check Wiring	60.00	1 PC	60.00	20
25 Rust Proofing	60.00	1 PC	60.00	✓
26 To Remove & Refit Rear Seat And Up-holestery	160.00	1 PC	160.00	80
27 To Remove & Refit Rear Windscreen	160.00	1 PC	160.00	120
28 To Remove & Replace Bumper Sensor	80.00	1 PC	80.00	50
29 To Spray Painting	950.00	1 PC	950.00	800
			2,770.00	2,770.00
			Total	S\$ 10,587.63

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED EIGHTY SEVEN
AND CENTS SIXTY THREE ONLY 1730

For FOCUS AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE

P-7736
257
P-5802.00
A-140.00
A-1730.00
7672