

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

1 pc	Boot lid	\$	1,119.00	XR
1 pc	Boot lid lock	\$	99.00	XSVL
1 pc	Bootlid lock cable	\$	35.00	? XSVL
1 pc	Bootlid striker	\$	21.00	XSVL
1 pc	Bootlid emblem	\$	27.00	/NE
1 pc	Bootlid CRDi	\$	29.00	/NE
1 pc	Boot lid rubber weatherstrip	\$	96.00	/DBF
1 pc	Boot lid lower garnish	\$	290.00	? /CRK
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	? XSVL
1 pc	Bootlid inner trim	\$	190.00	? XSVL
2 pcs	Rear license plate lamps @ \$30.00	\$	60.00	XSVL
1 pc	End panel	\$	250.00	/BT
1 pc	End panel inner garnish	\$	74.00	? /CRK
2 pcs	Rear o/s & n/s fender inner shield @ \$120.00	\$	240.00	? RH XSVL
1 pc	Rear bumper	\$	696.00	/CRK
1 pc	Rear bumper lower cover	\$	206.00	/CRK
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	? XSVL
1 pc	Rear bumper inner sponge	\$	114.00	? /CRK
1 pc	Rear bumper reinforcement	\$	607.00	? /BT
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	? /BT
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	? /CRK
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	? XSVL
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	/SVL
2 pcs	n/s & o/s tail lamp @ \$421.00	\$	842.00	? RH XSVL
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00	? LH XSVL
2 pcs	n/s & o/s tail lamp panel @ \$215.00	\$	430.00	? XSVL
1 pc	Exhaust pipe hanger	\$	28.00	? XSVL
1 pc	Floorboard panel trim	\$	205.00	? XSVL
1 pc	Exhaust pipe	\$	1,009.00	/DBF
		\$	7,829.00	
		\$	782.90	
		\$	7,046.10	

Less 10%

4,072.50

29-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

S/NETT		PARTS \$4,525			
		LESS 10%	\$4,072.50		
1 set	Rear bumper clips		\$ 178	\$	48.00 / NEC
1 set	End panel inner garnish clips	NETT		\$	30.00 ? X JV
1 set	Bootlid inner trim clips	LABOUR	\$1,680	\$	52.00 ? X JV
1 set	Bootlid lower garnish clips	TOTAL	\$5,930.50	\$	60.00 ? X JV
1 set	Bootlid stickers	LESS LIS 20%	\$4,744.40	\$	100.00 / NEC
1 set	Reverse sensor			\$	280.00 X SV
1 pc	Rear bumper top protector	LIS TOTAL	\$4,750.00 / 60 DAYS	\$	80.00 X no swa sh
1 set	Floorboard compartment insulating paddings			\$	120.00 ? X NN
1 pc	Rear no. plate with casing			\$	50.00 X SV
1 set	Sealant			\$	50.00 X NN
1 pc	CH fender rear shaker			\$	30 / NEC
	Sundry			\$	50.00 X NN
	Towing fee			\$	50.00 ? shw
	To dismantle & refit the exhaust pipe			\$	150.00 60
	To dismantle / replace reverse sensor to new bumper and reset to the same			\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear o/s fender, n/s & o/s taillamp panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc			\$	1400.00 540 720 540
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s tail lamp panel, rear o/s tail lamp panel.			\$	1400.00 900
	To apply rustproofing on the repaired and replaced panels.			\$	300.00 100
			1,680	\$	11,566.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK 30/1/2020 1730
LIS
6 DAYS
CHECK ITEM PHOTOS
APRIL REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

4,744.4
= 4,750