

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

1 pc	Boot lid	\$	1,119.00	XR
1 pc	Boot lid lock	\$	99.00	XSVL
1 pc	Bootlid lock cable	\$	35.00	?
1 pc	Bootlid striker	\$	21.00	XSVL
1 pc	Bootlid emblem	\$	27.00	NE
1 pc	Bootlid CRDi	\$	29.00	NE
1 pc	Boot lid rubber weatherstrip	\$	96.00	DEF
1 pc	Boot lid lower garnish	\$	290.00	?
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	?
1 pc	Bootlid inner trim	\$	190.00	?
2 pcs	Rear license plate lamps @ \$30.00	\$	60.00	XSVL
1 pc	End panel	\$	250.00	BT
1 pc	End panel inner garnish	\$	74.00	?
2 pcs	Rear o/s & n/s fender inner shield @\$120.00	\$	240.00	✓ RH ✓ LHX JV
1 pc	Rear bumper	\$	696.00	CRK
1 pc	Rear bumper lower cover	\$	206.00	CRK
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	?
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	✓ SCR
2 pcs	n/s & o/s tail lamp @ \$421.00	\$	842.00	✓ RH ✓ LHX SVL
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00	✓ RH ✓ LHX SVL
2 pcs	n/s & o/s tail lamp panel @ \$215.00	\$	430.00	?
1 pc	Exhaust pipe hanger	\$	28.00	?
1 pc	Floorboard panel trim	\$	205.00	✓ XSVL
1 pc	Exhaust pipe	\$	1,009.00	DEF
		\$	7,829.00	
Less 10%		\$	782.90	
		\$	7,046.10	

29-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

S/NETT

1 set	Rear bumper clips	\$	48.00	/NEC
1 set	End panel inner garnish clips	\$	30.00	?
1 set	Bootlid inner trim clips	\$	52.00	?
1 set	Bootlid lower garnish clips	\$	60.00	?
1 set	Bootlid stickers	\$	100.00	/NEC
1 set	Reverse sensor	\$	280.00	XSVL
1 pc	Rear bumper top protector	\$	80.00	Xno such item
1 set	Floorboard compartment insulating paddings	\$	120.00	?
1 pc	Rear no. plate with casing	\$	50.00	XSVL
1 set	Sealant	\$	50.00	XNN
1 pc	RH fender rear shaker	\$	30	/NEC
	Sundry	\$	50.00	XNN
	Towing fee	\$	50.00	? slw
	To dismantle & refit the exhaust pipe	\$	150.00	60
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear o/s fender, n/s & o/s taillamp panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	1,400.00	540 720 540
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s tail lamp panel, rear o/s tail lamp panel,	\$	1,400.00	900
	To apply rustproofing on the repaired and replaced panels.	\$	300.00	100
		\$	11,566.10	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK 30/1/2020 1930
LCS

6 DAYS
CHECK ITEM PHOTOS
APPROPRIATE PHOTOS

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~CASH SALE/WORK ORDER~~

No: AM 0786



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 27/1/20

寶號

Messrs:

Premier

車號

Vehicle No:

SHC6856Y

車型

Model No:

KIT

由

From:

Tanah meroh Rd

到

To:

Omega level 1

其他

Remark:

時間

Time:

07:15-08:15-08:45

AMOUNT: \$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

Sadg/4363

收貨人

Received by:

Lee