



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006149
INV Date 08/09/2020
Reference CC4/FCI20001672/Hka3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLE 5616Y
Insured Veh. SHC 3819A
Claim No. D20000561MFSH/1
Policy No. D-20094922MFSH
Accident Date 18/01/2020
Inspection Date 31/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20001672/Hka3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-09-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3819A	Veh. Inspected	SLE 5616Y
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20000561MFSH/1	Excess (\$)	0.00
	Assign From	JASON TEA	Assign Date	31/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SYLPHY	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MNTBBAB17Z0027425	Colour	RED
	Odometer	58200	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	HANKOOK	6 mm
	L/H Front Tyre	195/60 R16	HANKOOK	6 mm
	R/H Rear Tyre	195/60 R16	HANKOOK	6 mm
	L/H Rear Tyre	195/60 R16	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/01/2020	Inspection Date	31/01/2020
	Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5616Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP RH (N)	SCRATCHED	815.00	815.00
1	FENDER FRONT RH (N)	BENT	752.80	752.80
1	FRT BUMPER SIDE BRKT RH (N)	NECESSARY	20.60	20.60
6	CLIP FRONT BUMPER @\$1.30 (N)	NECESSARY	7.80	7.80
1	FRONT BUMPER FASCIA (N)	DAMAGED	577.90	577.90
	LESS 20% DISCOUNT		-434.82	-434.82
			1,739.28	1,739.28
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	215/60R17 RV YOKOHAMA TYRE (SN)	SERVICEABLE	195.00	-
1	WHEEL RIM FRONT RH (SN)	SCRATCHED	280.00	280.00
			525.00	300.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REPAIR RH FRONT DOOR ,RENEW RH FRONT FENDER AND FRONT BUMPER .		800.00	780.00
	CHARGES TO SPRAY PAINTING SAME.		850.00	750.00
	RENEW DAMAGED HEADLAMP AND FOCUS.		48.00	48.00
	RENEW RH FRONT WHEEL RIM AND TYRE INCLUDE WHEEL BALANCING .		15.00	15.00
	CHECK AND ADJUST WHEEL ALIGNMENT.		95.00	95.00
			1,808.00	1,688.00
GRAND TOTAL			4,072.28	3,727.28
RECOMMENDED COST OF REPAIRS				3,727.28

Report Ref No. CC4/FCI20001672/Hka3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 5616Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 5616Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

