

Date: 30.01.2020
Vehicle No: SKZ399H
Model: MERCEDEZ BENZ GLA180
Chassis: WDC1569422J096849-2015
Reg.Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SFD62D
Date of Accident: 18.01.2020

812794.92

ESTIMATE

Not Authorized
C/Ling B?, I.B.1
6 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		B ₁ \$1,326.76
2	FRONT GRILLE BASE	1		M ₁ \$262.90
3	FRONT GRILLE GARNISH	1		M ₁ \$184.51
4	FRONT GRILLE MOULDING	4	\$62.08	M ₁ \$248.32
5	FRONT GRILLE EMBLEM	1		M ₁ \$134.92
6	FRONT GRILLE CLIPS	8	\$7.20	M ₁ \$57.60
7	FRONT GRILLE INNER RETAINER GUIDE	1		M ₁ \$103.60
8	FRONT BUMPER 1372-80	1		B ₂ \$1,412.55
9	FRONT BUMPER REINFORCEMENT	1		B ₁ \$308.36
10	FRONT BUMPER FOG LAMP LH	1		CM \$285.42
11	FRONT BUMPER FOG LAMP SUPPORT BRACKET LH	1		D ₁ \$45.34
12	FRONT BUMPER GARNISH SIDE COVER LH	1		M ₁ \$45.81
13	FRONT BUMPER LOWER GRILLE	1		M ₁ \$118.34
14	FRONT BUMPER LOWER LIP COVER	1		M ₁ \$581.36
15	FRONT BUMPER LOWER LIP SIDE COVER LH	1		Sn \$80.14
16	FRONT BUMPER SIDE BRACKET LH	1		D ₁ \$17.68
17	FRONT BUMPER SIDE BRACKET RH	1		D ₁ \$17.68
18	FRONT BUMPER UPPER BRACKET LH 99	1		CM \$296.40
19	FRONT BUMPER UPPER BRACKET RH 99	1		CM \$296.40
20	FRONT BUMPER CLIPS	12	\$6.50	M ₁ \$78.00
21	FRONT BUMPER ABSORBER FOAM	1		M ₁ \$102.89
22	FRONT NUMBER PLATE HOLDER SUPPORT	1		M ₁ \$272.80
23	FRONT REINFORCEMENT SUPPORT LOWER BRACKET LH	1		B ₁ \$81.88
24	FRONT HEADLAMP LH	1		M ₁ B ₂ \$927.00
25	FRONT HEADLAMP RH	1		CM \$927.00
26	FRONT SUPPORT PANEL ASSY	1		CM \$595.17
27	FRONT LOWER GUIDE COVER	1		CM \$264.80
28	FRONT AIR CLEANER DUCT	1		Pu \$98.94
29	FRONT TURBO INTER COOLER ASSY ✓	1		Pu \$955.39
30	FRONT AIR CON CONDENSOR	1		BA/Pu \$1,045.40
31	FRONT RADIATOR ✓ 840	1		B ₁ \$856.00
32	FRONT RADIATOR FAN GUARD	1		Sn \$426.25
33	FRONT WIPER TANK	1		Pu \$151.49
34	FRONT ENGINE UNDER COVER	1		M ₁ \$181.69
35	FRONT FENDER EXTENTION COVER LH	1		D ₁ \$194.80
36	FRONT FENDER EXTENTION COVER RH	1		D ₁ \$194.80

\$12421.57

Head office

5 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 30.01.2020
 Vehicle No: SKZ399H
 Model: MERCEDEZ BENZ GLA180
 Chassis: WDC1569422J096849-2015
 Reg.Year: 2015

Third Party Insurer: AIG
 Third Party Veh No: SFD62D
 Date of Accident: 18.01.2020

37	FRONT FENDER INNER LINER LH	170	1	CM	\$191.71	
38	FRONT FENDER INNER LINER RH	170	1	CM	\$191.71	
39	FRONT BONNET LOCK		1	R	\$135.60	
40	FRONT FENDER LH		1		REPAIR	
41	FRONT FENDER RH		1		REPAIR	
SUB TOTAL					\$13,697.41	\$13804.91
LESS 10%					-\$1,369.74	\$12800.45
PARTS TOTAL					\$12,327.67	\$11524.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT NUMBER PLATE	1		MIT	\$40.00
2	FRONT NUMBER PLATE HOLDER	1			\$40.00
3	FRONT RADIATOR COOLANT	1		MC	\$40.00
S/N TOTAL					\$120.00

Finalise: Parts: \$11,524.50
 Nett: \$85
 Labour: \$1630
 \$13239.50 Part by Part & 6 days.

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS & ETC.

\$1,100.00

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM.

\$100.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

\$1,000.00

LABOUR CHARGES TO REMOVE, REPLACE TURBO INTER COOLER, AIR CON CONDENSOR, RADIATOR & ETC.

\$150.00

LABOUR CHARGES TO REFILL AIR CON GAS & VACUUM.

\$100.00

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY.

\$150.00

LABOUR TOTAL \$2,600.00 \$1630

ONG TOTAL \$15,047.67

Head office

6 Kung Cheng Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

