

Date: 30.01.2020
 Vehicle No: SKZ399H
 Model: MERCEDEZ BENZ GLA180
 Chassis: WDC1569422J096849-2015
 Reg.Year: 2015

Third Party Insurer: AIG
 Third Party Veh No: SFD62D
 Date of Accident: 18.01.2020

Not Authorized
6 days
6 days 8? , 1.B.1

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		<i>Ry</i> \$1,326.76
2	FRONT GRILLE BASE	1		<i>my</i> \$262.90
3	FRONT GRILLE GARNISH	1		<i>my</i> \$184.51
4	FRONT GRILLE MOULDING	4	\$62.08	<i>my</i> \$248.32
5	FRONT GRILLE EMBLEM	1		<i>my</i> \$134.92
6	FRONT GRILLE CLIPS	8	\$7.20	<i>my</i> \$57.60
7	FRONT GRILLE INNER RETAINER GUIDE	1		<i>my</i> \$103.60
8	FRONT BUMPER	1		<i>Bro</i> \$1,412.55
9	FRONT BUMPER REINFORCEMENT	1		<i>Ry</i> \$308.36
10	FRONT BUMPER FOG LAMP LH	1		<i>CM</i> \$285.42
11	FRONT BUMPER FOG LAMP SUPPORT BRACKET LH	1		<i>Dit</i> \$45.34
12	FRONT BUMPER GARNISH SIDE COVER LH	1		<i>my</i> \$45.81
13	FRONT BUMPER LOWER GRILLE	1		<i>my</i> \$118.34
14	FRONT BUMPER LOWER LIP COVER	1		<i>my</i> \$581.36
15	FRONT BUMPER LOWER LIP SIDE COVER LH	1		\$80.14
16	FRONT BUMPER SIDE BRACKET LH	1		<i>Dit</i> \$17.68
17	FRONT BUMPER SIDE BRACKET RH	1		<i>Dit</i> \$17.68
18	FRONT BUMPER UPPER BRACKET LH	1		<i>CM</i> \$296.40
19	FRONT BUMPER UPPER BRACKET RH	1		<i>CRA</i> \$296.40
20	FRONT BUMPER CLIPS	12	\$6.50	<i>my</i> \$78.00
21	FRONT BUMPER ABSORBER FOAM	1		<i>my</i> \$102.89
22	FRONT NUMBER PLATE HOLDER SUPPORT	1		<i>my</i> \$272.80
23	FRONT REINFORCEMENT SUPPORT LOWER BRACKET LH	1		<i>Ry</i> \$81.88
24	FRONT HEADLAMP LH	1		<i>my</i> <i>Bro</i> \$927.00
25	FRONT HEADLAMP RH	1		<i>CM</i> \$927.00
26	FRONT SUPPORT PANEL ASSY	1		<i>CM</i> \$595.17
27	FRONT LOWER GUIDE COVER	1		<i>CM</i> \$264.80
28	FRONT AIR CLEANER DUCT	1		<i>Pu</i> \$98.94
29	FRONT TURBO INTER COOLER ASSY	1		\$955.39
30	FRONT AIR CON CONDENSOR	1		<i>BA/Pu</i> \$1,045.40
31	FRONT RADIATOR	1		\$856.00
32	FRONT RADIATOR FAN GUARD	1		\$426.25
33	FRONT WIPER TANK	1		\$151.49
34	FRONT ENGINE UNDER COVER	1		<i>my</i> \$181.69
35	FRONT FENDER EXTENTION COVER LH	1		<i>Dit</i> \$194.80
36	FRONT FENDER EXTENTION COVER RH	1		<i>Dit</i> \$194.80

Date: 30.01.2020
 Vehicle No: SKZ399H
 Model: MERCEDEZ BENZ GLA180
 Chassis: WDC1569422J096849-2015
 Reg.Year: 2015

Third Party Insurer: AIG
 Third Party Veh No: SFD62D
 Date of Accident: 18.01.2020

37	FRONT FENDER INNER LINER LH	1	CM	\$191.71
38	FRONT FENDER INNER LINER RH	1	CM	\$191.71
39	FRONT BONNET LOCK	1		\$135.60
40	FRONT FENDER LH	1		REPAIR
41	FRONT FENDER RH	1		REPAIR
SUB TOTAL				\$13,697.41
LESS 10%				-\$1,369.74
PARTS TOTAL				\$12,327.67

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT NUMBER PLATE	1		MIT \$40.00
2	FRONT NUMBER PLATE HOLDER	1		\$40.00
3	FRONT RADIATOR COOLANT	1		MC \$40.00
S/N TOTAL				\$120.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS & ETC.

600 \$1,100.00

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM.

300 \$100.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

800 \$1,000.00

LABOUR CHARGES TO REMOVE, REPLACE TURBO INTER COOLER, AIR CON CONDENSOR, RADIATOR & ETC.

100 \$150.00

LABOUR CHARGES TO REFILL AIR CON GAS & VACUUM.

\$100.00

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY:

\$150.00

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation is allowed
- Survey report may be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$2,600.00

ONG

TOTAL \$15,047.67

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

