

Section A - Accident Details	
Registration Number	SHB223T
Case Reference Number	TAX/01/20/2110
Registration Date	25/10/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	KOH TIAN SIEW
Type of Accident	Head to Rear
Accident Date and Time	26/1/2020 12:25 PM
Accident Reported Date and Time	28/1/2020 10:40 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105441
Special Instruction to ARC, if any	TP / FRONT PORTION / DROVE IN
Prepared Date and Time	28/1/2020 2:50 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$2,111.92	\$438.61
Total Other Cost	\$240.00	\$50.00
TOTAL COST	\$3,416.92	\$888.61
Lump Sum Total	\$3,400.00	\$900.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / QBE
ARC / Surveyor Sign Off Date	31/01/2020 12:04 PM	30/01/2020 7:30 PM
Signature		
Remarks	SUP = 0 day	L/S repair, take after spray.

