

**Lion City Rentals Pte Ltd**  
**CARROS CENTER**  
**60 JALAN LAM HUAT #04-01 S(737869)**  
**Main +65 62524991**

**Ms AIG Asia Pacific Insurance Pte Ltd**

Date: 30/01/2020

**Attn : MOTOR CLAIMS DEPT**

**ESTIMATE**

VEHICLE NO: SLE6123X

CHASSIS NO : RU31208464

MAKE / MODEL : Honda Vezel Hybrid 1.5X CVT

DATE OF ACCIDENT 27/01/2020

YOUR INSURED VEHICLE NUMBER :SDW818P

MILEAGE : 244307 km

	<b><u>PARTS DESCRIPTION</u></b>	<b><u>QTY</u></b>	<b><u>UNIT PRICE</u></b>	<b><u>LIST PRICE</u></b>
1	Rear tailgate / nb	1PC	\$1,450.00	\$1,450.00
2	Rear tailgate back door trim board / SCH.	1PC	\$580.00	\$580.00
3	Rear tailgate Vezel emblem / Nec	1PC	\$86.80	\$86.80
4	Rear tailgate Honda emblem / Nec	1PC	\$81.30	\$81.30
5	Rear tailgate HYBRID emblem / Nec	1PC	\$84.00	\$84.00
6	Rear tailgate windscreen moulding / Nec	1PC	\$195.00	\$195.00
7	Rear tailgate weatherstrip / cut.	1PC	\$155.00	\$155.00
8	Rear tailgate lock / Jewel	1PC	\$550.00	\$550.00
9	Rear tailgate lock catch / X SUC.	1PC	\$180.00	\$180.00
10	Rear RH tail lamp / CR4	1PC	\$780.00	\$780.00
11	Rear RH taillamp reflector / SCH	1PC	\$480.00	\$480.00
12	Rear LH taillamp / CR4	1PC	\$780.00	\$780.00
13	Rear LH taillamp refelector / SCH	1PC	\$480.00	\$480.00
14	Rear end panel / nb	1PC	\$830.00	\$830.00
15	Rear end panel top garnish / CR4.	1PC	\$155.00	\$155.00
16	Rear bumper / CR4.	1PC	\$955.00	\$955.00
17	Rear bumper RH reflector / X SUC	1PC	\$180.00	\$180.00
18	Rear bumper LH reflector / X SUC	1PC	\$180.00	\$180.00
19	Rear spare tyre tool box / CR4	1PC	\$480.00	\$480.00
20	Rear spare tyre panel / nb	1PC	\$2,000.00	\$2,000.00
LIST TOTAL S\$:				\$10,662.10
20.00% DISCOUNT S\$:				\$2,132.42
Total				\$8,529.68

### SPECIAL NETT

1	Rear bumper clips	1 SET	\$180.00 30
2	End panel top garnish clips	1 SET	\$80.00 X 50
3	Reverse sensor	1PC	\$250.00 200
4	Body sealant	1set	\$300.00 50
5	Windscreen sealant	1PC	\$200.00 40
7	Rear number plate		\$60.00 X 50
Special Nett Total S\$:			\$1,070.00

### LABOUR CHARGES

1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts. Also include cutting out and welding of replacement spare tyre panel, Repair fender.	\$1,200.00 1100
2	To respray rear tailgate, end panel and spare tyre panel	\$800.00 ✓
3	To remove and install rear tailgate glass	\$160.00 120
4	To apply rustproofing on all damaged parts	\$180.00 60
5	Towing fee	
6	To check wiring system	\$100.00 30
7	To conduct a standard of operating procedures post repairs scan test as a requirements upon completion of collision repairs - photo.	\$300.00 2120
8	To deactivate and active high voltage hybrid battery as a safety precautions - photo	\$300.00 240

LABOUR TOTAL S\$:	\$3,040.00
TOTAL S\$:	\$12,639.68
7% GST	\$884.78
GRAND TOTAL S\$:	\$13,524.46

Repair. days - 7 days.

Lump Sum Repair.

After paint photo

Sun Pin (LKK)

30/01/2020

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: