

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20001684/QDA3Q2

**Date:** 11/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLH4570K

**Insured Vehicle No :** SGG3956C

Date of Loss: 21/01/2020

Nature of Claim: TP

Claim No: 0487748452SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH4570K**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB4262936

Reg. Date: 03/11/2016 (Man. Year: 2016)

Chassis No: GP71043183

Colour: White

Odometer: 237563 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Rovelo 5 mm

Rear Left Side:

Rovelo 5 mm

Front Right Side: Rovelo 5 mm

Rear Right Side:

Rovelo 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,515.76	1,205.60	2,310.16	65.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	910.00	1,230.00	57.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,655.76</b>	<b>2,115.60</b>	<b>3,540.16</b>	<b>62.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>(S\$)</b>	5,655.76	1,700.00	3,955.76	69.94
<b>+ GST 7.00/7.00% (S\$)</b>	395.90	119.00	276.90	69.94
<b>Nett Amount (S\$)</b>	<b>6,051.66</b>	<b>1,819.00</b>	<b>4,232.66</b>	<b>69.94</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,121.00</b>		

### INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)

1090 LOWER DELTA ROAD #05-12

Singapore 169201

Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,200.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
3	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	255.00 FL	*- FL
4	1		*REAR TAILGATE HONDA EMBLEM	Necessary	81.30 FL	*56.00 FL
5	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*56.00 FL
6	1		*REAR BUMPER	Repair	1,350.00 FL	*- FL
7	1		*SET REVERSE SENSOR	Serviceable	260.00 FS	*- FS
8	1		*SET BUMPER CLIPS	Serviceable	120.00 FS	*- FS
9	1		*SET END PANEL TO GARNISH CLIPS	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,279.70</b>	<b>1,507.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	763.94	301.40
<b>Total Parts (\$)</b>	<b>3,515.76</b>	<b>1,205.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE REAR TAILGATE ,REAR BUMPER ,END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STRAIGHTEN SPAE TYRE PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS	New	900.00	300.00
2	TO RESPRAY REAR BUMPER ,END PANEL ,SPARE TYRE PANEL AND TAILGATE	New	900.00	400.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
4	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	30.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,140.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >