Lion City Rentals Pte Ltd **CARROS CENTER** 60 JALAN LAM HUAT #04-01 S(737869) Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd

Date 21/1/2020

Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH4570K CHASSIS NO: GP71043183

MAKE / MODEL: Honda Shuttle 1.5 CVT

DATE OF ACCIDENT: 21/01/2020

	JR INSURED VEHICLE NUMBER : SGG3956C				
MIL	EAGE : 237563 km				
	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE	
1	Rear tailgate / P P	1PC	\$1,850.00	\$1,850.00)
2	Rear tailagte windscreen moulding / Nec	1PC	\$195.00	\$195.00	
3	Rear tailgate weatherstrip XSVC	1PC	\$255.00	\$255.00	
4	Rear tailgate Honda emblem > Ntc	1PC	\$81.30	\$81.30	
5	Rear tailgate shuttle emblem	1PC	\$88.40	\$88.40	
6	Rear bumper × R.	1PC	\$1,350.00	\$1,350.00)
			LIST TOTAL S\$:	\$3,819.70	
		20.00%	DISCOUNT S\$:	\$763.94	
				\$3,055.76	
	SPECIAL NETT				
1	Reverse sensor X SVC	1 SET		\$260.00	
2	Bumper clips XSVC	1 SET		\$120.00	
3	End panel to garnish clips X5 v-C.	1 SET		\$80.00	
	7,31		Nett Total S\$:	\$460.00	
	LABOUR CHARGES			\$400.00	
1	TO REMOVE REAR TAILGATE , REAR BUMPER, END PANEL OUT TO				-9E
	FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO				27
	STARIGHTEN SPARE TYRE PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS				
2	TO RESPRAY REAR BUMPER, END PANEL, SPARE T TAILGATE	RAY REAR BUMPER,END PANEL, SPARE TYRE PANEL AND E			401
3	TO REMOVE & INSTALL REAR WINDSCREEN			\$160.00	120
4	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED				
4	PARTS.			\$80.00	30
5	TO TRANSFER TAILGATE MECHANISM		_	\$100.00	60
		LABO	UR TOTAL S\$:	\$2,140.00	
			TOTAL S\$:	\$5,655.76	
	10		7% GST _	\$395.90	_
	Repair. day - 3 days	GRA	ND TOTAL S\$:	\$6,051.66	_
	Lymp Sym Pe				
	After paint photo				
	Sun Pin (LICLE)				
	30/01/2020				
	TP without prefuder				

LKK Au'o Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

400

120

- Third party survey is on a "Without Prejudice" basis
- Nc illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: