

22/03/2002

ASS. REC. BY:

REF:

08/CTI2004685/HSD32

Special Instruction:

Surrender: Hock Ann

ASSIGNMENT (Office)

Member

From (Person): Irene Tay

of

CTI

Date/Time: 31/01/2020 @ 2:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMP13752

Insured:

SJX2297C

at Workshop in/s

Z-One Automotive

Tel: 66342112

of

1 Kaki Bukit Ave 6 # 01-85 Autobay

Policy No: DMPCE N30293519066

Claim No: SNM200200541/SJX2297C/IRENE

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25/1/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 3:45pm @ 31/1/2020

Person Contacted:

syafiah

Vehicle IN/OUT

Date/Time	Action/Instruction	Tolong!
	SMP13752 - X	✓
	SJX2297C - X	

ASS. REC. BY: H. ANW

REF: CTI

**ASSIGNMENT**

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SMP 1375Z  
at Workshop n/s 2-one Automotive  
of 1 Keki Bukit Ave 6 #01-05  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3.Val.: Yes or No

CA / REV / REP. / 24 HRS  
Vehicle: IN / OUT  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMP 1375Z Yr Regn: 12/09/2017  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: H. FIT CVT C.C. 1377  
Colour: Gray A/C: Insured / Std / NI / NA  
Sp. Reading: 7799km T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: GK 3342/831  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 175/70/R14  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front		Rear	
R/Bal. <u>8</u>	<u>Yoko</u> mm	R/Bal. <u>8</u>	<u>Yoko</u> mm
L/Bal. <u>8</u>	mm	L/Bal. <u>8</u>	mm
D.O.A. <u>25/1/2020</u>		D.O.I. <u>31/1/20</u>	

Survey held at 2-one Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Hock Ann,</u>
	<u>PLS see my remarks.</u>
	<u>Hock Ann Confirmed US \$7,550/- @ 10 days with Yvonne</u>
	<u>vis email. ( \$7,349.48 red 49% )</u>
	<u>MV - 62000</u>
	<u>PV - 35328</u>
	<u>NV - 26600</u>

\* Smp 1375Z 1100pm  
have Estimate.

RECEIVED 6 MAR 2020

\* See my remarks.

Date/Time, File Pass to? 26/03/20  
1) Typist  
Date/Time, File Return to?  
2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 10  
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Insp (\$)  
☐ : Weekend (\$)

Survey Fee:  
Transportation: \_\_\_\_\_  
S + PS: \_\_\_\_\_  
Photos: \_\_\_\_\_  
Others: \_\_\_\_\_  
TOTAL: \_\_\_\_\_

Report Format:  
Lump Sum / L.B.R. (\$) \$ 7,550/- 4/5

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2020		31 Jan 2020 15:00 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	<b>SITT WEI HONG LEX</b>		
Vehicle Reg. No.:	<b>SMP1375Z</b>	Date of Loss:	25/01/2020 14:00 - :59
Claim Type:	<b>TP / SNM20D200541C02</b>	Policy/Cover Note No.:	DMPCSN30293519066
Vehicle Reg. No. (Insured):	<b>SJX2297C</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Z-One Automotive Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6634 2112		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 11/02/2020]</b>		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Friday, 31 January 2020 2:57 PM  
**To:** service@z-one.com.sg; enquiry@z-one.com.sg  
**Cc:** assignments; Admin A  
**Subject:** FW: OUR REF: SNM20D200541/SJX2297C/IRENE & YOUR REF: SMP1375Z - (DS) PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING VEHICLES SMP1375Z & SJX2297C ALONG MCE TURNING OUT TO FORD ROAD ON 25/01/2020 AT 1400HRS  
**Attachments:** SMP1375Z- PRS.pdf; SAS2740497.PDF

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with Z-ONE to conduct survey.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F:(65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Thursday, January 30, 2020 4:56 PM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>; service@z-one.com.sg; enquiry@z-one.com.sg  
**Subject:** OUR REF: SNM20D200541/SJX2297C/IRENE & YOUR REF: SMP1375Z - (DS) PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING VEHICLES SMP1375Z & SJX2297C ALONG MCE TURNING OUT TO FORD ROAD ON 25/01/2020 AT 1400HRS

Dear Irene,

Please conduct PRS-SMP1375Z soonest possible.

Officer In Charge- Irene Tay -DID : 6389 6192

Dear Nur,

\*\*\* kindly quote our reference number when replying.\*\*\*

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter

---

**From:** Nur Syafirah <[service@z-one.com.sg](mailto:service@z-one.com.sg)>

**Sent:** Thursday, January 30, 2020 3:27 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** Sya Z1 <[enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)>

**Subject:** (DS) PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING VEHICLES SMP1375Z & SJX2297C ALONG MCE TURNING OUT TO FORD ROAD ON 25/01/2020 AT 1400HRS

Dear Sir /Mdm,

Kindly find the attached PRS Request & GIA Report for your kind attention.

Please do send us the list of your 10 surveyor for us to choose.

Our customer's vehicle is already in our workshop.

Do revert back to us at the soonest.

For any further clarifications, kindly contact Sya @ 66342112.

Best Regards,

Nur Syafirah

Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883

Tel: 66342112 Fax: 6634 2122

## Shirley Hiew (LKK Auto)

---

**From:** Yvonne Yong <service@z-one.com.sg>  
**Sent:** Thursday, 19 March 2020 5:41 pm  
**To:** Hock Ann (LKK Auto)  
**Cc:** Shirley Hiew (LKK Auto); SUR  
**Subject:** Re: SMP 1375Z FINALIZED

Dear Hock Ann,

As the owner of this vehicle is making a PI claim.

Please take note that we will forward the documents to our law firm to issue out the LOD from their end.

Thank you!

Best Regards,

Yvonne Yong  
Z-One Automotive Pte Ltd  
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883  
Tel: 66342112 Fax: 6634 2122

**From:** Yvonne Yong  
**Sent:** Thursday, March 19, 2020 5:10 PM  
**To:** Hock Ann (LKK Auto)  
**Cc:** Shirley Hiew (LKK Auto) ; SUR  
**Subject:** Re: SMP 1375Z FINALIZED

Dear Hock Ann,

We accepted and confirmed Finalise Amount @ \$7,550.00 (before gst) / 10 working days.

Thank you!

Best Regards,  
Yvonne Yong

**Z-One Automotive Pte Ltd**  
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883  
Tel: 66342112 Fax: 6634 2122

**From:** Hock Ann (LKK Auto)  
**Sent:** Thursday, March 19, 2020 5:04 PM  
**To:** Nur Syafirah  
**Cc:** Shirley Hiew (LKK Auto) ; SUR  
**Subject:** RE: SMP 1375Z FINALIZED

Dear ah xiong / nur syafirah ,

Good day, regarding your request for L/SUMP repair cost need \$ 8000 , that have try submit to insurance after other party insurance management didn't approve this amount .

At last other party insurance management offer to your repair cost L/SUMP amount COR \$ 7550 and DOR 10 DAY.

Kindly to take noted, will be base finalized amount COR \$7550 and DOR 10 DAYS to close this case.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to (CHINA TAIPING INSURANCE CLAIM DEPT)

Thanks.

Best Regards,  
Hock Ann | Assistant Automotive Assessor

**LKK Auto Consultants**

Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hock Ann (LKK Auto)  
**Sent:** Wednesday, February 26, 2020 4:05 PM  
**To:** Nur Syafirah <service@z-one.com.sg>  
**Cc:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Subject:** RE: SMP 1375Z FINALIZED

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear ah xiong / nur syafirah,

Good day , Kindly attached refer SMP 1375Z HONDA FIT finalized updated calculate adjustment on 26.2.2020

COR - \$ 7200

DOR – 10 DAYS

Please refer adjustment updated total LUMP/SUMP amount \$ 7200 if agree total LUMP/SUMP amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,  
**Hock Ann** | Assistant Automotive Assessor

**LKK Auto Consultants**

Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/01/2020 10:16
Date Of Accident	25/01/2020 14:00
Exact Location Of Accident	MCE TURNING OUT TO FORT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP1375Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SITT WEI HONG LEX
NRIC No	SXXXX831D
Email Address	LEXSITTWH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82239457
Alternative Phone No	OFFICE-82239457

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29134815 QMX
Cover Note Number	

### Driver

Name of Driver	SITT WEI HONG LEX
NRIC No	SXXXX831D
Date Of Birth	24/10/1988
Occupation	INDOOR
Date Of Driving Pass	09/02/2012
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82239457
Fax Number	
Contact Number	OFFICE-82239457
Email Address	LEXSITTWH@GMAIL.COM

Address	BLK 122 GEYLANG EAST CENTRAL #10-80
Postcode	380122
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX2297C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG KWAN SOEN
NRIC/Passport Number	SXXXX061G
Contact Number	96196231
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	SITT WEI HONG LEX
------	-------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SMP1375Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

BLK 122 GEYLANG EAST CENTRAL #10-80

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 10/28/120

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- I was driving <sup>straight</sup> ~~on~~ MCE <sup>forwards</sup> ~~backwards~~ the Fort Road exit on the lane 3.
- While I was driving, I saw the car bang ~~was~~ at the back of ~~the~~ car.
- Suddenly, there was an impact at the back of my car.

Insurance Co. _____	
Vehicle No. _____	Date of Accident _____
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own-Damage Claim <input checked="" type="checkbox"/> Third Party Claim	

@ other w/s

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 1022hrs

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	831D
<b>Vehicle Details</b>	
Vehicle No.:	SMP1375Z
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3GF CVT
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	L13B3936322
Chassis No.:	GK33421831
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$16,192.00
Original Registration Date:	12 Sep 2019
First Registration Date:	12 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$6,192.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2029
PARF Rebate Amount:	\$4,644.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,917.00
COE Rebate Amount:	\$30,684.00
<b>Total Rebate Amount:</b>	<b>\$35,328.00</b>

The information contained herein is correct as at 31 Jan 2020

OK

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



Honda

Min Price ▼

to

No Max ▼

Depreciation ▼

Vehicle Type ▼

Category ▼



Home » New Cars » New Car Brands » Honda » Honda Fit

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Honda Fit (Parallel Imported)

Select Another Make ▼

Select The Make ▼

Overview

Pricing

Photos

Research

Reviews

Specs

Features

Similar

Accessories

Promo

Add to Shortlist

Submit a Review

Report Error

Share



## Details

Sold by Parallel Importers | 81 dealers

Built in Japan (launched 2013, facelifted Dec-2017)

Variants 3 submodel(s) » Show pricelist

Predecessor Honda Fit (2008-2013)

Promotion **Ready stock available with immediate COE registration now!!**

USER RATINGS:

(7 reviews)

» View 3 promotions for Fit

Add to Shortlist

We have some dealers currently running very good deals on the Honda Fit. Get them to contact you directly with more info.

Name\*

Contact No\*



I'm not a robot

reCAPTCHA  
Privacy - Terms

Submit

## Featured Merchants



## Related Articles



2019's most popular Japanese Parallel Import cars



Honda delivers first Fit EV



Used car dealers posing as owners to sell cars



Compare

## Submodel

1.3 G F-Package (A) ⚙️

1.3 G F-Package Honda Sensing (A)

1.3 LED G F-Package (A)

RRP

\$73,000

Pricelist

\$74,000

Pricelist

\$75,000

Pricelist

ECO

24.6km/L

24.6km/L

24.6km/L

Power

98bhp

98bhp

98bhp

Detailed

Specs | Fei

Specs | Fei

Specs | Fei

✓ Verified Ready Stocks are vehicles that have cleared all LTA paperwork and ready to be registered immediately. This is verified by sgCarMart with the VITAS Approval Code (VAC) issued by LTA. [View all the Honda Fit that are Ready Stock.](#)

Showing 9 out of 81 dealers selling this vehicle

Hua Yang Enterprise

Tel: 67439933 / 86689797

Car Lingual

Tel: 64633777 / 85007770

Leco Prestige

Tel: 64740566 / 97806972

MHG Cars

✓ This Dealer has Ready Stocks

Tel: 65136363 / 86136363

Hoe Beng Auto Trading

Tel: 65523003 / 93680138

Zenith Automobile

Tel: 62479686 / 98197237

Henly Enterprises Co.

Tel: 62828188 / 96351017

Car House

✓ This Dealer has Ready Stocks

Euro Performance

Tel: 90906655





# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE

Company Registration No. 201118055N

## ESTIMATE

Sitt Wei Hong Lex  
122 Geylang East Central #10-80 Singapore  
380122

Contact : 82239457

Code : C101959

Date in : 25/01/2020

Vehicle Num. : SMP1375Z

Model : HONDA FIT 1.3GF CVT

Chassis/Eng# : GK33421831/L13B3936322

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Rear Bumper ✓ BT	1	492.70	492.70 450.30
Rear bumper centre garnish ✓ CRA	1	78.70	78.70 ✓
Rear bumper exhaust garnish ? ✓ CRA	1	12.50	12.50 ✓
Rear bumper inner sponge ? X NS	2	37.05	74.10 X
Rear bumper reflector with garnish RH/LH ? ✓ CRA	2	88.10	176.20 88.60
Rear bumper side retainer RH/LH ✓ new	2	19.30	38.60 ✓
Rear cross member X (svc)	1	891.40	891.40
Rear end panel ✓ BT	1	373.50	373.50
Rear end panel garnish ✓ CRA	1	127.50	127.50
Rear exhaust box ? ✓ BT X R Δ	1	476.60	476.60 ✓ 390.70
Rear exhaust box heat shield ? ✓ BT	1	27.80	27.80 ✓
Rear exhaust mounting ? X SVC	1	12.70	12.70 X
Rear fender inner trim RH/LH ? X R Δ CRA	2	263.30	526.60 ✓ 440.60
Rear fender RH/LH RH ✓ BT 4H X (R)	2	688.80	1,377.60 ✓ 580.30
Rear quarter glass moulding RH/LH RH ✓ new 4H X (svc)	2	19.50	39.00 ✓ 19.50
Rear spare tyre panel ✓ BT	1	864.80	864.80 780.40
Rear spare tyre panel cardboard ✓ CRA	1	302.30	302.30 240.30





# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Rear spare tyre panel side extension RH/LH X (svc)	2	136.60	273.20	
Rear tailgate ✓ int	1	1131.10	1,131.10	900.40
Rear tailgate chrome moulding ? ✓ Crg	1	223.10	223.10	130.80
Rear tailgate damper RH/LH X (svc)	2	146.30	292.60	
Rear tailgate emblem 'FIT' ✓ (un)	1	35.60	35.60	
Rear tailgate emblem 'H' ✓ (un)	1	24.60	24.60	
Rear tailgate emblem 'HYBRID' X (un) Svc	1	68.30	68.30	
Rear tailgate hinge RH/LH X (R)	2	48.40	96.80	
Rear tailgate inner handle ✓ BT	1	15.60	15.60	
Rear tailgate inner trim ? ✓ Crg	1	124.30	124.30	
Rear tailgate lock ✓ Jm	1	204.10	204.10	
Rear tailgate lock keyless smart ? ✓ Crg	1	87.80	87.80	
Rear tailgate lock keylezz buzzer ? ✓ Crg	1	87.80	87.80	
Rear tailgate reflector RH/LH RH ? ✓ Crg 4/4 X (svc)	2	390.90	781.80	280.50
Rear tailgate rubber ✓ Crg	1	109.00	109.00	
Rear taillamp panel housing RH/LH 4/4 X (R) RH ? ✓ BT	2	107.30	214.60	88.70
Rear taillamp RH/LH ✓ 4/4 (R) RH (CRA) ✓	2	522.60	1,045.20	761.60
Rear windscreen moulding ✓ un	1	125.50	125.50	110.50
Subtotal before discount			10,833.60	
Percentage discount 20%			2,166.72	
Sub-total 1			8,666.88	
Rear bumper clips set (SN) X SVC	1	45.00	45.00	



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Rear bumper reverse sensor set (SN) ✓ short	1	280.00	280.00 200
Rear bumper sticker (SN) X (not use) NN	1	250.00	250.00
Rear number plate with casing (SN) X (suc)	1	50.00	50.00
Rear quarter glass sealant (SN) ✓ rec RH only	1	80.00	80.00 30
Rear quarter glass sponge tape RH/SH (SN) ✓ RH only (rec) 2-1	1	20.00	20.00 ✓
Rear windscreen sealant (SN) ✓ rec	1	80.00	80.00 40
Rear windscreen sponge tape (SN) ✓ rec	1	20.00	20.00 ✓
Subtotal before discount			825.00
Percentage discount 0% <del>20%</del>			0.00
Sub-total 2			825.00
Parts-total			9,491.88

## LABOUR

Description	Price
To provide towing charge. (King Trolley)	100 80 200.00 ✓ check? prior
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning. ✓	100.00 30
To remove, refix / renew reverse sensor assy and rectify for proper functioning. ✓	150.00 30
To remove, refix / renew reverse camera assy ✓	50 120.00 50 200
To remove, change rear tailgate windscreen ✓	150.00 120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) ✓	80 150.00 100 80 80
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1350 1,600.00 1300
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	80 150.00 60 ?
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. ✓	1650 2,000.00 1700 ?
To replace rear aluminium tailgate door and align X	120.00 ✓ 100 high

page 3

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE  PERFORMANCE Company Registration No. 201118055N

To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel. ✓

Labour Total  
Parts & Labour Total

150.00 86

4,890.00

14,381.88

14,379.43

page 4



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

## ESTIMATE

Sitt Wei Hong Lex  
122 Geylang East Central  
#10-80  
Singapore 380122

Code : C101959  
Date In: 25/1/2020  
Vehicle Num. : SMP1375Z  
Model : HONDA FIT 1.3GF CVT  
Chassis/ Eng # : GK33421831 / L13B3936322

Contact:

### Supplementary for Estimate Items

Description of part	Qty	Unit Price	Amount
REAR FENDER ARCH <i>R/H only ✓ LRM HAX (2000)</i>	<i>2</i>	58.80 <i>A</i>	<i>117.60 58.80 ✓</i>
SPONGE TOOL BOX <i>✓ CRA</i>	<i>1</i>	198.2 <i>A</i>	<i>198.20 150.20 ✓</i>
REAR SPARE TYRE PANEL LOWER BRACKET <i>center ✓ BF</i>	<i>2</i>	165.60 <i>A</i>	<i>331.20 140.50 ✓</i>
Subtotal			647.00
Percentage discount 20%			129.40
Sub-total			\$ 517.60
Parts total			\$ 517.60

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2020		31 Jan 2020 15:00 <a href="#">Edit Adj Rpt</a>	<b>S\$7,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$7,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>SITT WEI HONG LEX</b>		
Vehicle Reg. No.:	<b>SMP1375Z</b>	Date of Loss:	25/01/2020 14:00 - :59 [4 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM20D200541C02</b>	Policy/Cover Note No.:	DMPCSN30293519066
Vehicle Reg. No. (Insured):	<b>SJX2297C</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Z-One Automotive Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6634 2112		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 11/02/2020]</b>		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents




































**\*SMP1375Z (SNM20D200541C02)**  
**[SJX2297C]**
















































**TP**  
**SITT WEI HONG LEX**  
**Jan 25 2020 2:00PM**

**[-]**  
**Z-One Automotive Pte Ltd**
















































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)















































[View](#)
[View In Browser ▼](#)


Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/02/20 08:48	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
2	03/02/20 08:48	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
3	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
33	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
34	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
35	03/02/20 08:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/02/20 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/02/20 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/02/20 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/02/20 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/02/20 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
71	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
72	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
73	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
74	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
75	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
76	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
77	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
78	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
79	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
80	03/02/20 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
81	03/02/20 08:51	General View	 Load JPG	<input checked="" type="checkbox"/>
82	03/02/20 08:51	General View	 Load JPG	<input checked="" type="checkbox"/>
83	03/02/20 08:51	General View	Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	03/02/20 08:51	General View	 Load JPG	✓
85	03/02/20 08:51	General View	 Load JPG	✓
86	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
87	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
88	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
89	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
90	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
91	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
92	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
93	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
94	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
95	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
96	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
97	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
98	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
99	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
100	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
101	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
102	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
103	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
104	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
105	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
106	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
107	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
108	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
109	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
110	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
111	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
112	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
113	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
114	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
115	05/02/20 09:01	Reinspection Photo	 Load JPG	✓
116	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
117	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
118	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
119	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
120	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
121	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
122	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
123	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
124	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
125	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
126	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
127	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
128	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
129	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
130	05/02/20 09:02	Reinspection Photo	 Load JPG	✓
131	05/02/20 09:02	Reinspection Photo	Load JPG	✓

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	05/02/20 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
160	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
161	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
162	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
163	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
164	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
165	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
166	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
167	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
168	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
169	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
170	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
171	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
172	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
173	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
174	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
175	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
176	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
177	17/02/20 10:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	03/04/20 09:57	SUPPLEMENTARY		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001685/HSD3S2

Date: 03/04/2020

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30293519066
Claimant Vehicle No :	SMP1375Z	Insured Vehicle No :	SJX2297C
Date of Loss:	25/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200541C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMP1375Z	Engine No:	L13B3936322
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GK33421831
Reg. Date:	12/09/2019 (Man. Year: 2019)	Odometer:	7799 km
Colour:	Grey		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,009.48	5,878.08	4,131.40	41.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,890.00	3,570.00	1,320.00	26.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,899.48</b>	<b>9,448.08</b>	<b>5,451.40</b>	<b>36.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,550.00</b>		
<b>(S\$)</b>	14,899.48	7,550.00	7,349.48	49.33
<b>+ GST 7.00/7.00% (S\$)</b>	1,042.96	528.50	514.46	49.33
<b>Nett Amount (S\$)</b>	<b>15,942.44</b>	<b>8,078.50</b>	<b>7,863.94</b>	<b>49.33</b>

## INSPECTION

Date of Assignment:	31/01/2020	
Date Inspected:	31/01/2020 Inspected At:	Z-One Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, Blk D #01-85, Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	10.0 days	

4/3/2020

Adjuster Report

**Adjuster:** LEE HOCK ANN

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2020)
<b>Parts:</b>	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP1375Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	492.70 FL	*450.30 FL
2	1		*REAR BUMPER CENTRE GARNISH	Cracked	78.70 FL	*78.70 FL
3	1		*REAR BUMPER EXHAUST GARNISH	Cracked	12.50 FL	*12.50 FL
4	2		*REAR BUMPER INNER SPONGE	No such part	74.10 FL	*- FL
5	2		*REAR BUMPER REFLECTOR WITH GARNISH RH / LH	Cracked	176.20 FL	*88.60 FL
6	2		*REAR BUMPER SIDE RETAINER RH / LH	Necessary	38.60 FL	*38.60 FL
7	1		*REAR CROSS MEMBER	Serviceable	891.40 FL	*- FL
8	1		*REAR END PANEL	Bent	373.50 FL	*373.50 FL
9	1		*REAR END PANEL GARNISH	Crushed	127.50 FL	*127.50 FL
10	1		*REAR EXHAUST BOX	Bent	476.60 FL	*390.70 FL
11	1		*REAR EXHAUST BOX HEAT SHIELD	Bent	27.80 FL	*27.80 FL
12	1		*REAR EXHAUST MOUNTING	Serviceable	12.70 FL	*- FL
13	2		*REAR FENDER INNER TRIM RH / LH	Cracked	526.60 FL	*440.60 FL
14	1		*REAR FENDER RH / LH	O/s Bent / N/s Repair	1,377.60 FL	*580.30 FL
15	1		*REAR QUARTER GLASS MOULDING RH / LH	O/s Necessary/N/s Serviceable	39.00 FL	*19.50 FL
16	1		*REAR SPARE TYRE PANEL	Bent	864.80 FL	*780.40 FL
17	1		*REAR SPARE TYRE PANEL CARDBOARD	Crushed	302.30 FL	*240.30 FL
18	2		*REAR SPARE TYRE PANEL SIDE EXTENSION RH / LH	Serviceable	273.20 FL	*- FL
19	1		*REAR TAILGATE	Cut	1,131.10 FL	*900.40 FL
20	1		*REAR TAILGATE CHROME MOULDING	Cracked	223.10 FL	*130.80 FL
21	2		*REAR TAILGATE DAMPER RH / LH	Serviceable	292.60 FL	*- FL
22	1		*REAR TAILGATE EMBLEM FIT	Necessary	35.60 FL	*35.60 FL
23	1		*REAR TAILGATE EMBLEM H	Necessary	24.60 FL	*24.60 FL
24	1		*REAR TAILGATE EMBLEM HYBRID	Serviceable	68.30 FL	*- FL
25	2		*REAR TAILGATE HINGE RH / LH	Repair	96.80 FL	*- FL
26	1		*REAR TAILGATE INNER HANDLE	Bent	15.60 FL	*15.60 FL
27	1		*REAR TAILGATE INNER TRIM	Cracked	124.30 FL	*124.30 FL
28	1		*REAR TAILGATE LOCK	Jammed	204.10 FL	*204.10 FL
29	1		*REAR TAILGATE LOCK KEYLESS SMART	Cracked	87.80 FL	*87.80 FL
30	1		*REAR TAILGATE LOCK KEYLESS BUZZER	Cracked	87.80 FL	*87.80 FL
31	1		*REAR TAILGATE REFLECTOR RH / LH	O/s Cracked / N/s Serviceable	781.80 FL	*280.50 FL
32	1		*REAR TAILGATE RUBBER	Crushed	109.00 FL	*109.00 FL
33	1		*REAR TAILLAMP PANEL HOUSING RH / LH	N/s Repair / O/s Bent	214.60 FL	*88.70 FL
34	1		*REAR WINDSCREEN MOULDING	Necessary	125.50 FL	*110.50 FL
35	1		*SET REAR BUMPER CLIPS	Serviceable	45.00 FS	*- FS
36	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
37	1		*REAR BUMPER STICKER	Not Necessary	250.00 FS	*- FS
38	1		*REAR NUMBER PLATE WITH CASING	Serviceable	50.00 FS	*- FS
39	1		*REAR QUARTER GLASS SEALANT (RH)	Necessary	80.00 FS	*30.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
42	1		*REAR QUARTER GLASS SPONGE TAPE RH	Necessary	20.00 FS	*20.00 FS
43	2		*REAR TAILLAMP RH / LH	N/s Scratched / O/s Cracked	1,045.20 FL	*761.60 FL
44	1		*REAR FENDER ARCH	O/s Crushed / N/s Serviceable	117.60 FL	*58.80 FL
45	1		*SPONGE TOOL BOX	Cracked	198.20 FL	*150.20 FL
46	2		*REAR SPARE TYRE PANEL LOWER BRACKET CENTRE	Bent	331.20 FL	*140.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,305.60</b>	<b>7,270.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,296.12</b>	<b>1,392.02</b>
<b>Total Parts (\$\$)</b>	<b>10,009.48</b>	<b>5,878.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PROVIDE TOWING CHARGE. (KING TROLLEY)	New	200.00	100.00
2	DIAGNOSE, REPLACE AND / OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	100.00	30.00
3	TO REMOVE, REFIX / RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.	New	150.00	30.00
4	TO REMOVE, REFIX / RENEW REVERSE CAMERA ASSY.	New	120.00	50.00
5	TO REMOVE, CHANGE REAR TAILGATE WINDSCREEN.	New	150.00	120.00
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	150.00	80.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,600.00	1,350.00
8	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	New	150.00	80.00
9	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	2,000.00	1,650.00
10	TO REPLACE REAR ALUMINIUM TAILGATE DOOR AND ALIGN.	New	120.00	0.00
11	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL.	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>4,890.00</b>	<b>3,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >