

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T**AAD2001-205**

Not Authorised
U/L Rep B?
Book Valve?

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 202T

VF1ABL15AUC282365

RENAULT

LATITUDE

25.1.2020

FCIL

02-10-15

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Nil</i> 747.20 ✓
1	BUMPER SPOILER FRT	\$	<i>Nil</i> 344.70 —
1	BUMPER ABSORBER FRT	\$	<i>Nil</i> 394.68 —
1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 101.40 —
1	BUMPER SUPPORT FRT	\$	<i>Nil</i> 10.70 —
1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 101.40 —
1	BUMPER SUPPORT FRT	\$	<i>Nil</i> 10.70 —
1	BUMPER UNDERTRAY FRT	\$	<i>Nil</i> 292.50 —
1	BUMPER GRILLE LOWER FRT	\$	<i>Nil</i> 147.00 —
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Nil</i> 207.21 —
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Nil</i> 207.21 —
1	BUMPER BEAM FRT	\$	<i>B</i> 663.70 —
2	BUMPER BEAM PAD FRT	\$	<i>NSD</i> 24.50 X
1	TOW COVER FRT	\$	<i>Nil</i> 60.90 —
1	RADIATOR GRILLE	\$	<i>Nil</i> 969.90 —
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Nil</i> 225.36 —
1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 686.00 —
1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 592.70 —
1	FRAME FULL SUPPORT BRACKET	\$	<i>B</i> 41.60 —
1	FRONT BRACE PANEL	\$	<i>B</i> 177.22 —
1	HORN	\$	<i>SL</i> 449.90 X
1	HORN BRACKET	\$	<i>R</i> 21.90 X
1	HEADLAMP LH	\$	<i>B</i> 743.60 —
1	HEADLAMP RH	\$	<i>B</i> 743.60 —
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 127.70 —

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T

30 JAN 2020

AAD2001-205

1	HEADLAMP PANEL FRT RH	\$	R ₁	128.30	✓
1	HEADLAMP HARNESS	\$		556.10	?
2	HEADLAMP ADJUST MOTOR	\$		313.90	?
1	BONNET	\$	R ₁	1,312.70	✓
1	BONNET INSULATOR	\$	S _L	294.30	X
1	BONNET STRUT LH	\$	S _L	53.30	X
1	BONNET STRUT RH	\$	S _L	53.30	X
1	BONNET HINGE LH	\$	R	236.50	X
1	BONNET HINGE RH	\$	R	237.40	X
1	BONNET LOCK	\$	D.I	152.80	✓
1	BONNET CABLE	\$	S _L	55.20	X
1	BONNET CABLE COVER	\$	S _L	80.60	X
1	BONNET SEAL OUTER	\$	S _L	83.20	X
1	BONNET SEAL INNER	\$	S _L	70.10	X
2	BONNET BUFFER	\$	S _L	26.80	X
1	FENDER PANEL FRT LH	\$	R ₁	414.40	✓
1	WHEELARCH FRT LH	\$	C M	112.30	✓
1	FENDER BRACKET LOWER LH	\$	R ₁	11.80	✓
1	FENDER INSULATOR LH	\$	S _L	65.50	X
1	FENDER BRACKET FRT LH	\$	R ₁	38.90	✓
1	FENDER PANEL FRT RH	\$	R ₁	414.40	✓
1	WHEELARCH FRT RH	\$	C M	191.40	✓
1	FENDER BRACKET LOWER RH	\$	R ₁	21.40	✓
1	FENDER INSULATOR RH	\$	S _L	66.30	X
1	FENDER BRACKET FRT RH	\$	R	106.40	X
1	WIPER RESERVOIR	\$	R ₁	179.60	✓
1	WIPER RESERVOIR NECK	\$	R ₁	29.30	✓
1	WIPER RESERVOIR MOTOR	\$		82.60	?
1	AIR CLEANER LOWER	\$		271.26	?
1	AIR CLEANER HOSE	\$		76.14	?
1	BASE BATTERY TRAY	\$	C M	363.40	✓
1	AIR CLEANER BOX	\$		464.20	?
1	TURBO DUCT	\$		1,027.80	?
1	A/C HEATER VALVE	\$		484.50	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T**AAD2001-205**

1	SUBFRAME OUTER FRT	\$	1,094.20	?
1	SUBFRAME BRACKET OUTER LH	\$	49.00	?
1	SUBFRAME BRACKET OUTER RH	\$	49.00	?
1	ENGINE UNDERTRAY	\$	583.10	?
1	A/C CONDENSER	\$	<i>At/Pu</i> 1,537.80	✓
1	A/C CONDENSER GARNISH LH UPPER	\$	<i>mit</i> 57.30	✓
1	A/C CONDENSER GARNISH RH UPPER	\$	<i>mit</i> 56.70	✓
1	A/C CONDENSER GARNISH LH	\$	<i>mit</i> 67.90	✓
1	A/C CONDENSER GARNISH RH	\$	<i>mit</i> 67.70	✓
1	A/C PIPE CONDENSER TO COMPRESSOR	\$	<i>Sn</i> 187.20	X
1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	<i>Sn</i> 380.20	X
1	A/C PIPE COMPRESSOR	\$	<i>Sn</i> 222.70	X
1	A/C PIPE	\$	<i>Sn</i> 486.50	X
1	A/C COMPRESSOR	\$	<i>Sn</i> 2,142.30	X
1	AIR COOLER	\$	598.90	?
1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	?
1	AIR INTERCOOLER HOSE (Short)	\$	375.14	?
1	TRANSMISSION COOLER	\$	1,219.30	?
1	TRANSMISSION COOLER PAD	\$	9.50	?
1	RADIATOR	\$	<i>Pu</i> 871.20	✓
2	RADIATOR STUD UPPER	\$	<i>Sn</i> 11.10	X
2	RADIATOR BUSH UPPER	\$	<i>Sn</i> 11.10	X
2	RADIATOR MTG LOWER	\$	<i>Sn</i> 30.10	X
1	RADIATOR FAN COWLING	\$	417.00	?
1	RADIATOR FAN MOTOR LH	\$	826.70	?
1	RADIATOR FAN MOTOR RH	\$	821.20	?
1	RADIATOR TANK	\$	174.80	?
1	RADIATOR HOSE UPPER	\$	97.50	?
1	RADIATOR HOSE LOWER	\$	254.10	?
1	RADIATOR TANK HOSE	\$	56.20	?
1	AUTO COMPUTER	\$	<i>CM</i> 1,287.30	✓
1	INJECTION COMPUTER	\$	2,706.30	?
1	STEERING PINION RACK L70Y	\$	3,765.30	?
1	STEERING PUMP ELECTRIC L70Y	\$	2,026.70	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T**AAD2001-205**

1	STEERING HOSE LOW PRESSURE LONG	\$	<i>SL</i>	397.40	X
1	STEERING HOSE LOW PRESSURE	\$	<i>SL</i>	221.90	X
1	FUSE BOX	\$	<i>SL</i>	987.39	X
1	ENGINE MOUNTING RH	\$		153.50	?
1	ENGINE MOUNTING LOWER	\$		149.20	?
1	ENGINE MOUNTING UPPER	\$		592.02	?
1	ENGINE HARNESS L70Y	\$		1,501.60	?
1	SUPPORT ENGINE UPPER	\$		610.37	?
1	ALTERNATOR	\$		1,442.30	?
1	BATTERY	\$	<i>SL</i>	350.00	<i>508.00</i>
1	BATTERY COVER	\$	<i>SL</i>	363.40	X
1	OIL PAN ASSEMBLY	\$	<i>SL</i>	2,283.91	X
1	ENGINE OIL SUMP	\$	<i>SL</i>	97.70	X
1	LOWER ARM LH L70Y	\$	<i>R</i>	192.70	—
1	KNUCKLE ARM LH L70Y	\$	<i>R</i>	481.50	—
1	ABSORBER FRT LH L70Y	\$	<i>R</i>	274.10	—
1	DRIVESHAFT LH	\$	<i>R</i>	1,355.70	—
1	STABILIZER BAR FRT	\$	<i>DR</i>	427.90	—
2	STABILIZER LINK FRT	\$		69.50	?
1	LOWER ARM RH L70Y	\$	<i>R</i>	192.70	—
1	KNUCKLE ARM RH L70Y	\$	<i>R</i>	481.50	—
1	ABSORBER FRT RH L70Y	\$	<i>R</i>	274.10	—
1	DRIVESHAFT RH	\$		1,355.70	?
1	KNUCKLE HUB+BEARING LH	\$	<i>R</i>	272.30	—
1	KNUCKLE HUB+BEARING RH	\$	<i>R</i>	272.30	—
1	ABSORBER MOUNTING KIT LH	\$		212.30	?
1	ABSORBER DUST COVER LH	\$		76.30	?
1	ABSORBER MOUNTING KIT RH	\$		212.30	?
1	ABSORBER DUST COVER RH	\$		76.30	?
1	BRAKE DISC FRT LH	\$		158.80	?
1	BRAKE DISC FRT RH	\$		158.80	?
1	SUBFRAME INNER FRT	\$		746.00	?
1	SUBFRAME SUPPORT INNER	\$		69.50	?
1	SUBFRAME BRACKET INNER FRT LH	\$		101.00	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T**AAD2001-205**

1	SUBFRAME BRACKET INNER FRT RH	\$	SL	101.00	
1	ENGINE TOP COVER 2.0	\$	SL	139.80	
1	BRAKE HOSE FRT LH	\$	SL	80.70	
1	BRAKE HOSE FRT RH	\$	SL	80.70	
1	ABS SENSOR FRT LH	\$	SL	152.50	
1	ABS SENSOR FRT RH	\$	SL	152.50	
1	BRAKE CALIPER FRT RH	\$	SL	536.10	
1	BRAKE CALIPER FRT LH	\$	SL	536.10	
1	BRAKE PAD FRT	\$	SL	146.20	
1	BRAKE CALIPER BRACKET FRT LH	\$	SL	384.00	
1	BRAKE CALIPER BRACKET FRT RH	\$	SL	384.00	
1	WHEEL HOUSING PANEL FRT RH L70Y	\$	SL	2,698.60	
1	WHEEL HOUSING PANEL FRT LH L70Y	\$	SL	2,621.60	X
1	FENDER PANEL INNER FRT LH L70Y	\$	SL	858.30	X
1	FENDER PANEL INNER FRT RH	\$	SL	838.40	X
1	FENDER PANEL SUPPORT FRT RH	\$	SL	432.00	?
1	FENDER PANEL REINFORCEMENT FRT LH L70Y	\$	SL	642.40	?
1	CHASSIS PANEL FRT RH	\$	SL	592.90	X
1	CHASSIS PANEL FRT LH L70Y	\$	SL	655.80	X
1	CHASSIS PANEL SUPPORT FRT RH L70Y	\$	SL	431.70	?
1	CHASSIS PANEL REINFORCEMENT FRT LH L70Y	\$	SL	283.90	?
1	WINDSCREEN FRT L70Y	\$	SL	817.20	
1	RAIN SENSOR L70Y	\$	SL	296.90	?
1	WINDSCREEN LOW GRILLE COVER	\$	SL	310.60	X
1	SHELF ASSY (WINDSCREEN UNDER PANEL)	\$	SL	443.76	?
1	WINDSCREEN INNER GARNISH RH	\$	SL	257.40	?
1	WINDSCREEN INNER GARNISH LH	\$	SL	257.40	?
1	SEATBELT LH L70Y	\$	SL	1,488.70	
1	SEATBELT RH L70Y	\$	SL	1,553.10	
1	SEATBELT BUCKLE LH L70Y	\$	SL	498.70	?
1	SEATBELT BUCKLE RH L70Y	\$	SL	498.70	?
1	PASSENGER AIRBAG L70Y	\$	SL	2,093.60	
1	STEERING AIRBAG L70Y	\$	SL	1,592.90	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T**AAD2001-205**

1	AIRBAG COMPUTER L70Y	\$	<i>Mc</i> 1,213.90	—
1	AIRBAG SENSOR L70Y	\$	<i>Mc</i> 502.90	—
1	AIRBAG SENSOR L70Y	\$	<i>Mc</i> 172.90	—
1	ROTARY SWITCH L70Y	\$	<i>Mc</i> 812.90	—
1	DASHBOARD	\$	<i>Tn</i> 3,102.00	—
1	GLOVE BOX	\$	<i>Sn</i> 526.90	} X
1	GLOVE BOX FLAP	\$	<i>Sn</i> 648.10	
1	FACE CONSOLE	\$	<i>Sn</i> 949.60	
1	DIESEL FILTER	\$	<i>Sn</i> 839.78	
1	COVER HYDR DISTRIBUTOR	\$	<i>Sn</i> 493.35	
1	DOOR PANEL FRT LH	\$	<i>Mc</i> 2,844.66	
1	DOOR HINGE UPPER LH L70Y	\$	<i>Mc</i> 274.50	
1	DOOR HINGE LOWER L70Y	\$	<i>Mc</i> 300.55	
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 90.90	
1	DOOR WHEATHESTRIP FRONT LH	\$	<i>Sn</i> 316.00	
1	DOOR MIRROR ASSY LH	\$	<i>Sn</i> 1,483.40	
1	DOOR SEAL FRONT LH	\$	<i>Sn</i> 69.60	
1	DOOR SEAL LOWER FRONT LH	\$	<i>Sn</i> 93.90	
1	DOOR FINISHER FRT LH	\$	<i>Sn</i> 258.90	
1	DOOR MOULDING FRT LH	\$	<i>Sn</i> 100.50	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	<i>Sn</i> 332.00	
1	DOOR HARNESS WIRE LH	\$	<i>Sn</i> 2,670.00	
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sn</i> 466.51	
1	ROCKER PANEL INNER LH	\$	<i>Mc</i> 1,024.79	
1	ROCKER PANEL OUTER LH	\$	<i>Mc</i> 1,184.99	
1	ROCKER PANEL CENTER LH	\$	<i>Mc</i> 990.25	
TOTAL		\$	100,958.48	
10%		\$	10,095.85	
		\$	90,862.63	

Special Nett

1SET RADIATOR GRILLE FRAME CLIP	\$	<i>Mc</i> 52.00	—
1SET BUMPER CLIP FRT	\$	<i>Mc</i> 66.00	—

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T**AAD2001-205**

1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1SET RADIATOR GRILLE SCREW	\$	na	16.00	
1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1 Windscreen moulding	\$	na	120.00	✓
1 FRONT WINDSCREEN SEALANT	\$	na	253.20	405na
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	305na
1SET Front licence plate with holder	\$	na	80.00	455na
1SET WHEELARCH CLIP FRT LH	\$	na	30.50	✓
1SET WHEELARCH CLIP FRT RH	\$	na	30.50	✓
1 Front left tyre	\$	na	330.00	905na
1 Front left tyre rim	\$	na	380.00	✓
1 Front right tyre	\$	na	330.00	?
1 Front right tyre rim	\$	na	380.00	✓
6 BONNET INSULATOR CLIP L70Y	\$	na	7.30	
2 BONNET CABLE CLIP L70Y	\$	na	6.31	
2 BONNET CABLE COVER SCREW L70Y	\$	na	10.85	
1 FRONT LH DOOR STICKER 'Trans-Cab'	\$	na	80.00	
1 FRONT LH DOOR STICKER 'Classic'	\$	na	80.00	
1 DOOR CHECK BOLT	\$	na	22.69	
1 DOOR GUIDE SCREW	\$	na	10.85	
1 DOOR HINGE BOLT	\$	na	10.85	
1 DOOR HINGE NUT LH	\$	na	14.60	
1 DOOR CHECK BOLT	\$	na	22.69	
1 DOOR CHECK NUT	\$	na	3.75	
1 DOOR LOCK SCREW L70Y	\$	na	6.12	
1 DOOR CATCH SCREW L70Y	\$	na	10.06	
1 DOOR CHECK BOLT	\$	na	22.69	

Trans-cab Auto Services Pte Ltd**AAD2001-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T

4 Can Radiator Coolant

	\$	<i>me</i> 90.00 <i>305n</i>
TOTAL	\$	2,800.99
TOTAL PARTS	\$	93,663.62

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	9,900.00 <i>1500</i>
To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00 <i>250</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>100</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 <i>250</i>
To rust-proofing of the affected areas.	\$	170.00 <i>150</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>40</i>
Putty and spray painting of the affected portion.	\$	9,900.00 <i>1760</i>

Trans-cab Auto Services Pte Ltd**AAD2001-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T

To replace, refix and top up coolant for radiator	\$	170.00	501
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	380.00	501
To lift-up engine with gear box and refit.	\$	440.00	2801
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 350.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	200.00	1201
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	2801
To replace and refill power steering fluid.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 202T

To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 350.00	<i>X</i>
Towing Fees	\$	170.00	<i>501</i>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>Repair</i> 380.00	<i>X</i>
To dismantle and refit engine cross-member and engine mounting.	\$	<i>na</i> 380.00	<i>X</i>
To remove and renew engine and gear box mounting.	\$	<i>na</i> 380.00	<i>X</i>
To conduct and perform a comprehensive engine diagnostic check.	\$	<i>na</i> 380.00	<i>X</i>
TOTAL	\$	28,030.00	
Over All Total	\$	121,693.62	

Repair Days (LUMP SUM)***35 DAYS******21 days***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: