

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9318J**AAD2001-176***Not Authored**Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9318J*81021.75*

JTDKB3FU903081920

TOYOTA

PRIUS

21.1.2020

AIG

27/6/2019

PART	
1	REAR BUMPER
1	REAR BUMPER RE-INFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER LH
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	TAILLAMP LOWER LH
1	TAILLAMP UPPER LH
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO 1
1	COVER, FLOOR UNDER, NO 2
1	COVER, REAR FLOOR

LIST	
\$	<i>N</i> 442.60 <i>✓</i>
\$	<i>B</i> 332.70 <i>✓</i>
\$	<i>L</i> 15.40 <i>✓</i>
\$	<i>W/L</i> 576.30 <i>✓</i>
\$	<i>L</i> 116.50
\$	<i>L</i> 117.70
\$	<i>N</i> 1,147.80
\$	<i>L</i> 925.60
\$	<i>L</i> 372.30
\$	<i>L</i> 650.30
\$	<i>L</i> 502.00
\$	<i>L</i> 451.80
\$	<i>L</i> 123.70
\$	<i>L</i> 123.70
\$	<i>L</i> 502.00
\$	<i>L</i> 443.30
\$	<i>L</i> 126.70
\$	<i>L</i> 175.10
\$	<i>L</i> 241.90
\$	<i>L</i> 229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Trans-cab Auto Services Pte Ltd**AAD2001-176**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9318J**Special Nett**

		Special Net			
1SET	PARKING AID	\$	SH	700.00	} X
1SET	REAR BUMPER CLIP	\$	nn	66.00	
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
1	WINDSCREEN MOULDING	\$	nn	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	
1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
1	REAR BUMPER PROTECTOR	\$	SH	100.00	
1	REAR WHEEL RIM	\$	SH	1,879.40	
1	REAR TYRE 195/65/15	\$	SH	350.00	
1	REAR WHEEL RIM COVER	\$	SH	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	nn	25.00	
1	REAR LH BUMPER RETAINER CLIP	\$	nn	25.00	
TOTAL		\$		3,950.30	

TOTAL PARTS	\$	9,663.28
--------------------	-----------	-----------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	SH	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	SH	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	SH	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	220/

Trans-cab Auto Services Pte Ltd**AAD2001-176**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9318J

To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>1200</i>
To supply and re-do rear end panel insulation padding.	\$	<i>na</i> 380.00	X
TOTAL	\$	14,720.00	
Over All Total	\$	24,383.28	

(PART-BY-PART) Repair Days**20 Days***1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

