

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9692C**AAD2001-171***Not authorized
Refusing B4 painting*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 JAN 2020

SHD 9692C

JTDKB3FU803082105

TOYOTA

PRIUS

20.1.2020

III

27/6/2019

PART		LIST	
1	REAR BUMPER	\$	442.60 X
1	REAR BUMPER RE-INFORCEMENT	\$	332.70 7
1	REAR BUMPER TOWING COVER	\$	15.40 X
1	GUARD, REAR BUMPER, CENTER	\$	576.30 ✓
1	REAR BUMPER SIDE RETAINER LH	\$	116.50
1	REAR BUMPER SIDE RETAINER RH	\$	117.70
1	REAR TAILGATE	\$	1,147.80
1	REAR TAILGATE OUTER GARNISH	\$	925.60
1	REAR TAILGATE WEATHERSTRIP	\$	372.30
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30
1	TAILLAMP LOWER RH	\$	502.00
1	TAILLAMP UPPER RH	\$	451.80
1	REAR BUMPER SIDE RH	\$	123.70
1	REAR BUMPER SIDE LH	\$	123.70
1	TAILLAMP LOWER LH	\$	502.00
1	TAILLAMP UPPER LH	\$	443.30
1	COVER, DECK TRIM, REAR	\$	126.70
1	COVER, FLOOR UNDER, NO 1	\$	175.10
1	COVER, FLOOR UNDER, NO 2	\$	241.90
1	COVER, REAR FLOOR	\$	229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2001-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9692C

1SET	PARKING AID	\$	700.00	} Per X
1SET	REAR BUMPER CLIP	\$	66.00	
2	REAR WINDSCREEN SEALANT	\$	80.00	
1	WINDSCREEN MOULDING	\$	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
1	REAR TAILGATE TOYOTA LOGO	\$	47.00	
1	REAR TAILGATE WORDING 'PRIUS'	\$	52.90	
1	REAR TAILGATE WORDING 'HYBRID'	\$	53.50	
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	80.00	
1	REAR TAILGATE STICKER '6555-3333'	\$	80.00	
1	REAR BUMPER PROTECTOR	\$	100.00	
1	REAR WHEEL RIM	\$	1,879.40	
1	REAR TYRE 195/65/15	\$	350.00	
1	REAR WHEEL RIM COVER	\$	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	25.00	
1	REAR LH BUMPER RETAINER CLIP	\$	25.00	
TOTAL		\$	3,950.30	
TOTAL PARTS		\$	9,663.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9692C**AAD2001-171**

To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>4</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>4</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>801</i>
To supply and re-do rear end panel insulation padding.	\$	<i>na</i> 380.00	X
TOTAL	\$	14,720.00	
Over All Total	\$	24,383.28	

(PART-BY-PART) Repair Days~~20 Days~~*1/2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications, is allowed
- Supplier (e.g. - Bonus) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: