

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5332T**AAD2001-218***Not Authorized
Respray B4 paint**84869.13*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

30 JAN 2020

SHD 5332T

JTDKB3FU403078374

TOYOTA

PRIUS

29.1.2020

CHINA TAIPING

12-12-18

	PART
1	FRONT BUMPER
1	FRONT BUMPER SIDE RETAINER RH
1	REINFORCEMENT, FRONT BUMPER
1	REINFORCEMENT, FRONT BUMPER, NO.2
1	ABSORBER, FRONT BUMPER, LOWER
1	ABSORBER, FRONT BUMPER ENERGY
1	COVER SUB-ASSY, ENGINE, NO.1
1	COVER SUB-ASSY, ENGINE UNDER, NO.2
1	EXTENSION, FRONT BUMPER, RH
1	FRONT LED LAMP (LOWER) RH
1	FRONT HEADLAMP RH
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
1	MOTOR, HEADLAMP LEVELING, RH
1	FRONT FENDER RH
1	LINER, FRONT FENDER, RH
1	COVER SUB ASSY, FRONT PILLAR, UPPER RH
1	FRONT FENDER EMBLEM RH
1	FRONT BONNET
1	PANEL SUB-ASSY, FRONT DOOR, RH
1	TAPE, BLACK OUT, NO.1 FRT RH
1	TAPE, BLACK OUT, NO.2 FRT RH
1	TAPE, BLACK OUT, NO.3 FRT RH
1	RIGHT SIDE VIEW MIRROR
1	WIRE, FRONT DOOR, RH
1	MOULDING ASSY, BODY ROCKER PANEL, RH
1	GRILLE, RADIATOR, LOWER NO.1

	LIST	
\$	<i>Buclum</i> 516.00	✓
\$	<i>Dir</i> 80.10	✓
\$	<i>R</i> 716.60	}
\$	<i>R</i> 246.10	
\$	<i>Sm</i> 132.70	
\$	<i>Sm</i> 79.60	
\$	<i>Sm</i> 472.40	
\$	<i>Sm</i> 241.90	}
\$	<i>Sm</i> 120.10	
\$	<i>W</i> 951.40	
\$	<i>W</i> 2,637.60	✓
\$	<i>Sm</i> 960.50	X
\$	<i>Sm</i> 487.50	X
\$	<i>R</i> 977.80	✓
\$	<i>Sm</i> 206.70	X
\$	<i>Sm</i> 100.40	X
\$	<i>na</i> 54.60	✓
\$	<i>R</i> 983.10	}
\$	<i>R</i> 1,300.70	
\$	<i>na</i> 13.30	
\$	<i>na</i> 43.50	
\$	<i>na</i> 26.30	}
\$	<i>Sm</i> 1,436.60	
\$	<i>Sm</i> 532.80	
\$	<i>Sm</i> 594.80	}
\$	<i>Sm</i> 170.10	
TOTAL	\$ 14,083.20	
25%	\$ 3,520.80	
	\$ 10,562.40	

Trans-cab Auto Services Pte Ltd**AAD2001-218**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5332T**Special Nett**

1 FRONT WHEEL RIM	\$	Sn 1,879.40	X
1 FRONT WHEEL RIM COVER	\$	Sn 211.50	X
1 FRONT TYRE 195/65/15	\$	Sn 350.00	X
1 CLIP, FRONT FENDER LINER	\$	nn 35.00	X
1 FRONT NUMBER PLATE WITH MOULDING	\$	Sn 200.00	X
1 BUMPER CLIP FRT	\$	nn 66.00	✓
1 FRONT DOOR STICKER 'TRANS-CAB'	\$	nn 100.00	X
1SET FRONT BUMPER RETAINER CLIP	\$	nn 35.00	X
1SET ROCKER PANEL MOULDING CLIP	\$	nn 30.00	X
TOTAL	\$	2,906.90	

TOTAL PARTS \$ 13,469.30**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 4001

To transfer of Fender fittings, attachments and perform water seepage test.

\$ nn 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$ 170.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To transfer of Bonnet fittings, attachments and perform water seepage test.

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

AAD2001-218

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5332T

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	44d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2d
To Rust-Proofing Of The Affected Areas.	\$	170.00	3d
TOTAL	\$	14,170.00	
Over All Total	\$	27,639.30	

(PART-BY-PART) Repair Days

20 days

2day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: