

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2977/01/20

Your Ref:

Date: 18th JAN 2020

MR WONG KOK WAI KENNETH
192, Depot Rd, #14-23
Singapore 109690

Estimate cost of repair to MAZDA 6 SP 2.0 (A) Saloon - SDS 275 B

1 pc rear bumper	100/12	\$ 1,231.50	✓
20 pcs rear bumper top & low clips	@ \$ 5.50	110.00	✓
2 pcs rear bumper o/s & n/s tow bar cover	@ \$ 35.00	70.00	?
1 pc rear bumper o/s reflector		53.90	X
1 pc rear bumper lower garnish skirt		315.00	X
10 pcs rear bumper lower garnish clips & stapper	@ \$ 5.50	55.00	?
1 set rear bumper o/s & n/s inner reverse sensor	@ \$ 203.60	407.20	?
1 set rear bumper o/s & n/s outer reverse sensor	@ \$ 203.60	407.20	X
2 pcs rear bumper o/s & n/s top retainer	@ \$ 25.00	50.00	X
2 pcs rear bumper o/s & n/s side retainer	@ \$ 42.00	84.00	X
2 pcs rear bumper o/s & n/s side bracket clips	@ \$ 7.50	15.00	X
1 pc rear bumper reinforcement		583.30	?
2 pcs rear bumper reinforcement o/s & n/s stay	@ \$ 85.30	170.60	?
1 pc rear n/s exhaust bracket		35.00	?
1 pc rear o/s exhaust bracket mounting		35.00	?
1 pc rear end panel		606.70	?
6 pcs rear end panel top garnish clips	@ \$ 5.50	33.00	X
		\$ 4,262.40	
	Less 20%	\$ 852.48	
		\$ 3,409.92	

To wiring check up for accepted wiring system.

50.00 20

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts, to enable repair rear end panel & necessary parts.

120.00 60

To jack, straighten & knocking out rear exhaust & tail pipe.

150.00 ?

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear end panel & necessary parts, to weld, renew & align above parts.

750.00 ?

To putty & respray painting on all affected accident parts,

950.00 600

To respray Tuff-Kote on all affected accident parts.

60.00 ?

Dollars : Five Thousand Four Hundred Eighty Nine and Cents Ninety Two Only.

HUP MOTOR TRADING & SERVICE

LEK Auto Consultants hence notify

the Repairer of the following:

- To rectify before/after spray painting
- To respray damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No further modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$ 5,489.92

Acknowledged by Repairer

Signature:

Date: