

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 03 Feb 2020

**Preliminary Advice**

Vehicle No	: SDS275B	Accident Date	: 17/01/2020
Make	: MAZDA 6	Policy No.	: D19MPC0002896
Assignment Date	: 31/01/2020	Excess	: S\$0.00
Date of Inspection	: 21/1/2020	Est. Duration of Repair	: 4
Inspection At	: HUP MOTOR TRADING & SERVICE		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,489.92
Revised Amount	:S\$	1,797.20
Check Items (Estimated)	:S\$	2,486.24
Total	:S\$	4,283.44

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	47,862.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,138.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :