

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay @ Kaki Bukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST 201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 20/FC/TP-028(01)
Claim Type: Third Party
Accident Date: 20/01/2020
TP Veh Reg No: SHD8588C

Estimate No: EST0005302
Date: 23 Jan 2020
Policy No: P10253261R00
Veh Reg No: SJD9785U
Make/Model: HONDA STREAM
Chassis No: RN61054753
Engine No: R18A1761195
Reg. Date: 11/04/2008

Estimate Repair Cost to Vehicle No :SJD9785U

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1 FRT LH SHOCK ABSORBER	1 PC	329.00	2
2 FRT LH LOWER ARM	1 PC	302.00	2
3 FRT LH KNUCKLE ARM	1 PC	289.00	1
4 FRT LH KNUCKLE BEARING	1 PC	129.00	1
5 STEERING RACK ASSY	1 PC	1,651.00	1
6 FRT LH DRIVE SHAFT	1 PC	966.00	1
7 FRT BUMPER	1 PC	677.00	1
8 FRT BUMPER CLIPS	10 PC	55.00	1
		4,398.00	
	Less 20%	879.60	3,518.40
Labour			
9 WIRE CHECKING	1 UNIT	30.00	20
10 REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	1 UNIT	350.00	300
11 WHEEL ALIGNMENT	1 UNIT	65.00	60
12 LABOUR CHARGE	1 UNIT	200.00	100
13 SPRAY PAINTING	1 UNIT	350.00	300
		995.00	995.00
	Total		SS 4,513.40
	Add GST @ 7%		315.94
	Total Amount Payable		SS 4,829.34

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED TWENTY NINE AND CENTS THIRTY FOUR ONLY

Not Authorized
LHR

30/1/20
L/S # 2950/
3 days
to the photo after repair

For SME Motor Pte Ltd

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey before/after paintwork
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Link Auto Company

Approved by: [Signature]

Link Auto

3666
292
2932.80
3712.80
2970.