

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : SGH 9953 R

Model : Nissan Sunny

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,483.20	\$ 916.80 1,483.20
2	Bootlid logo	1	\$ 108.90	\$ 38.70 108.90
3	Bootlid emblem 'Sunny'	1	\$ 118.60	\$ 36.70 118.60
4	Bootlid emblem 'EX Saloon'	1	\$ 103.60	\$ 56.20 103.60
5	Bootlid emblem 'CVTC'	1	\$ 97.00	\$ 56.20 97.00
6	Bootlid emblem 'E- Throttle'	1	\$ 69.00	\$ 56.30 69.00
7	Bootlid outer chrome garnish	2	\$ 175.80 486.20	\$ 351.60 972.40
8	Bootlid inner trim board	1	\$ 359.20	\$ 359.20
9	Bootlid number plate lamp	2	\$ 86.40	\$ 172.80
10	Bootlid weatherstrip	1	\$ 286.30	\$ 286.30
11	Bootlid hinge LH	1	\$ 110.00 186.90	\$ 110.00 373.80
12	Bootlid lock	1	\$ 356.10	\$ 117.48 356.10
13	Bootlid striker	1	\$ 96.40	\$ 96.40
14	Rear bumper	1	\$ 1,058.60	\$ 565.40 1,058.60
15	Rear bumper side retainer	2	\$ 70.00 208.70	\$ 140.00 417.40
16	Rear bumper reinforcement stopper CUT	2	\$ 168.00	\$ 183.40 336.00
17	Rear end panel	1	\$ 753.90	\$ 467.70 753.90
18	Rear end panel top garnish	1	\$ 196.50	\$ 102.70 196.50
19	Rear fender RH DD ✓ LH R X	1	\$ 894.80 1,086.30	\$ 894.80 2,172.60
20	Rear fender inner trim board	2	\$ 425.70	\$ 851.40
21	Rear fender air vents RH	1	\$ 276.50	\$ 276.50
22	Fuel cover	1	\$ 186.00	\$ 186.00
23	Spare tyre panel	1	\$ 795.30	\$ 795.30
24	Spare tyre top board	1	\$ 486.20	\$ 486.20
25	Taillamp	1	\$ 644.40 976.20	\$ 644.40 1,952.40
26	Taillamp base panel	2	\$ 486.20	\$ 972.40
27	Exhaust pipe	1	\$ 855.00	\$ 855.00
28	Exhaust mounting	1	\$ 79.50	\$ 79.50
			Parts Sub Total :	\$ 4,739.78 15,987.00
			30% Discount	\$ 1,421.93 4,796.10
			PARTS TOTAL :	\$ 3,317.85 11,190.90

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 40.00 -100.00
3	Rear end panel sealant	1	\$ 100.00	\$ 40.00 100.00
4	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
5	Spare tyre panel sealant	1	\$ 100.00	\$ 100.00
6	Rear fender sealant RH	1	\$ 100.00	\$ 40.00 100.00
7	Reverse sensor with module	2	\$ 150.00	\$ 200.00 -300.00
8	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00
9	Taillamp clips	2	\$ 50.00	\$ 60.00 100.00
10	Taillamp base panel sealant	1	\$ 800.00	\$ 30.00 -800.00
11	Bootlid outer chrome garnish clips	1	\$ 50.00	\$ 30.00 50.00
12	Reverse camera	1	\$ 380.00	\$ 380.00
13	Taillamp seal	2	\$ 80.00	\$ 160.00
SPECIAL NETT TOTAL :				\$ 500.00 2,370.00

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 50.00 100.00
2	R&R upholstery	\$ 50.00 200.00
3	R&R reverse sensor and spray paint	\$ 60.00 100.00
4	R&R exhaust pipe assy	\$ 250.00
5	R&R fuel pipe assy	\$ 180.00
6	To disconnect wire harness to facilitate repair, reconnect and test function	\$ 80.00
7	Conduct water leakage test	\$ 60.00
8	Rust proofing	\$ 60.00 200.00
9	Rear Spray painting	\$ 1200.00 1,600.00
10	Rear Panel beat	\$ 1000.00 1,600.00
LABOUR TOTAL :		\$ 2420.00 4,370.00

Survey 30/1/2020
TGTim Lim
1515 hrs

Resurvey 30/1/2020
TGTim Lim
1525 hrs

Repair days 8

PARTS TOTAL : \$3317.85 11,190.90
SPECIAL NETT TOTAL : \$500.00 2,370.00
LABOUR TOTAL : \$2420.00 4,370.00

GRAND TOTAL : \$6237.85 17,930.90

@ 20 % 1247.57
4990.28

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5 5,000/2