



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
 Email: motor@wahhong.sg
 (199806235M)

Page No. 1

Vehicle No. SLM8476Y HONDA VEZEL 1.5A

Vehicle No.		SLM8476Y HONDA VEZEL 1.5A				
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT		
<u>PARTS (LIST ITEMS)</u>						
1	Rear bumper / CUT	Less 20%	420.00			
1	Rear bumper reflector LH X		65.00			
1	Rear bumper reflector RH X		65.00			
1	Rear corner panel LH X		190.00			
1	Rear corner panel RH X		190.00			
1	Tailgate / DT		850.00			
1	Tailgate garnish X		190.00			
1	Tailgate lock assy / DT		120.00			
1	Rear lock stricker X		85.00			
1	Tailgate lamp LH ?		380.00			
1	Tailgate lamp RH ?		380.00			
1	Rear fender lamp LH X		480.00			
1	Rear fender lamp RH X		480.00			
1	Tailgate inner trim board X		230.00			
1	End panel X R		470.00			
1	End panel top cover X		100.00			
1	Tailgate weather stripe X		180.00			
1	Rear windscreen center seal / NL		55.00			
1	Rear windscreen seal LH X		28.00			
1	Rear windscreen seal RH X		28.00			
1	VEZEL emblem / NL		90.00			
1	HONDA badge emblem - NL		120.00			
			5196.00			
			1039.20			
			4156.80			
<u>SPECIAL NETT ITEMS</u>						
1	Rear bumper clips / NL		Total Parts		30.00	200
1	Reverse sensor / SL				220.00	
1	Rear license plate with holder X	55.00				
			4406.80			



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SLM8476Y HONDA VEZEL 1.5A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1600.00 690	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00 400	
3	To remove and re-fix wiring and check all electrical components	120.00 30	
4	To provide anti-rust treatment on affected area	150.00 30	
5	To remove and re-fix rear windscreen	200.00 120	
Labour Total :		3070.00	
TOTAL (PARTS & LABOUR):		7476.80	

Steve (LKK)

83228813

WHL MIL

29/1/29, 10.45am

4 days

L/S

By HL SLJ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: