

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 28-Jan-20

INSURANCE:

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH6224P

DESCRIPTION	QTY	LIST PRICE	AMOUNT
RADIATOR GRILLE NW	1	\$438.00	\$438.00
RADIATOR GRILLE EMBLEM NW	1	\$88.00	\$88.00
FRONT BUMPER COVER <i>distorted / mainly broken</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT NW	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER NW	1	\$115.70	\$115.70
FRONT BUMPER LOWER REINFORCEMENT BRACKET NW	1	\$330.00	\$330.00
FRONT BUMPER SPONGE NW	1	\$78.80	\$78.80
FRONT BUMPER CENTRE GRILLE NW	1	\$301.90	\$301.90
FRONT BUMPER LOWER GRILLE NW	1	\$148.60	\$148.60
LAMP ASSY, FOG, RH <i>mainly broken</i>	1	\$920.00	\$920.00
FRONT BUMPER CLIPS NW	1	\$22.00	\$22.00
FRONT BUMPER SIDE RETAINER NW	1	\$77.00	\$77.00
SUPPORT FR BUMPER, RH NW	1	\$81.70	\$81.70
BRACKET, FRONT BUMPER SIDE, RH NW	1	\$82.30	\$82.30
BRACKET, FRONT BUMPER SIDE, LH NW	1	\$82.30	\$82.30
BRACKET, FRONT BUMPER MOUNTING NW	1	\$29.60	\$29.60
BRACKET, FRONT BUMPER MOUNTING, NO. 2 NW	1	\$97.80	\$97.80
UNIT ASSY, HEADLAMP, RH (LED) <i>Scratches / mainly broken</i>	1	\$3,455.00	\$3,455.00
UNIT ASSY, HEADLAMP, LH (LED) <i>mainly broken</i>	1	\$3,455.00	\$3,455.00
HEAD LAMP PANEL (RH) NW	1	\$240.10	\$240.10
TOP PANEL CENTRE NW	1	\$364.98	\$364.98
TOP PANEL SIDE NW	1	\$145.90	\$145.90
BRACKET, HEADLAMP MOUNTING, RH NW	1	\$25.50	\$25.50
BRACKET, HEADLAMP MOUNTING, LH NW		\$25.50	\$0.00
FRONT FENDER SHIELD NW	1	\$198.50	\$198.50
FRONT FENDER SHIELD CLIP NW	1	\$14.90	\$14.90
FRONT FENDER HYBRID EMBLEM, RH NW	1	\$86.50	\$86.50
BRACKET, FRONT SIDE PANEL, RH NW	1	\$44.50	\$44.50
EXTENSION, FRONT FENDER, RH NW	1	\$47.20	\$47.20
WIPER SPARE TANK NW	1	\$183.75	\$183.75
WIPER SPARE TANK MOTOR NW	1	\$242.70	\$242.70
WIPER SPARE TANK FLOAT (NECK) NW	1	\$55.50	\$55.50
WIRING FRONT NW	1	\$8,450.50	\$8,450.50
SUB TOTAL			\$22,045.83
LESS 20% 25%			\$4,409.17
DISCOUNTED TOTAL			\$17,636.66
FRONT BUMPER LOGO NW	Nett 1	\$87.10	\$87.10

SUB TOTAL			\$87.10
Labour Charge			
Panel Beating	1	\$1,200.00	\$1,200.00
Spray Painting Charge	1	\$1,000.00	\$1,000.00
Wiring Charge	1	\$120.00	\$120.00
Tuff Kote	1	\$120.00	\$120.00
Towing Charge	1	\$50.00	\$50.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$150.00	\$150.00
Remove/Refix Fuse Box	1	\$180.00	\$180.00
TOTAL LABOUR			\$2,910.00
ESTIMATE TOTAL			\$20,633.76
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance			

400/-
300/-
30/-
24
12
12
12
12

30/01/2020 @ 1600hrs
NA Antenna
2/sum 3 days.

9
yan
LKK Auto

9

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: