

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 28-Jan-20

INSURANCE: Arg

MODEL: HYUNDAI I40

VEHICLE NO.: SHA3550J

DESCRIPTION	QTY	LIST PRICE	AMOUNT
RADIATOR GRILLE H EMBLEM NH	1 X	\$39.50	\$39.50
RADIATOR GRILLE NH	1 X	\$1,480.00	\$1,480.00
FRONT BUMPER COVER <i>destroyed / cut / internally cracked</i>	1 X	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE NH	1 X	\$99.20	\$99.20
FRONT BUMPER REINFORCEMENT NH	1 X	\$438.40	\$438.40
FRONT BUMPER GRILLE (RH) NH	1 X	\$49.20	\$49.20
FRONT BUMPER BRACKET TOP (RH) NH	1 X	\$44.80	\$44.80
FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40) NH	1 X	\$32.00	\$32.00
FRONT BUMPER BRACKET (RH) NH	1 X	\$49.20	\$49.20
FRONT BUMPER SIDE BRACKET <i>broken o/s</i>	1 X	\$4.60	\$4.60
FRONT BUMPER RETAINER MOUNTING NH	1 X	\$8.00	\$8.00
FRONT BUMPER GRILLE AIR DUCT NH	1 X	\$26.20	\$26.20
HEADLAMP SUPPORT PANEL ASSY <i>broken</i>	1 X	\$907.40	\$907.40
HEADLAMP (RH) <i>mainly broken</i>	1388.00 X	\$2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER NH	1 X	\$222.60	\$222.60
FRONT FENDER (RH) <i>Destroyed</i>	1 X	\$566.30	\$566.30
FRONT FENDER APRON PANEL (RH) NH	1 X	\$637.00	\$637.00
FRONT FENDER SHIELD (RH) NH	1 X	\$174.90	\$174.90
FRONT FENDER MUDFLAP (RH) NH	1 X	\$13.50	\$13.50
FRONT FENDER RETAINER NH	1 X	\$3.00	\$3.00
FRONT WHEEL RIM (RH) <i>destroyed / Destroyed</i> NH	X 1 <i>4mm</i>	\$650.60	\$650.60
FRONT WHEEL HUB CAP (RH) <i>cut</i>	107.10 X	\$214.20	\$214.20
FRONT WHEEL NUT NH	1 X	\$5.70	\$5.70
FRONT WHEEL BEARING <i>Don</i>	1 X	\$301.80	\$301.80
FRONT WHEEL HUB ASSY NH	1 X	\$153.60	\$153.60
FRONT SHOCK ABSORBER ASSY (RH) <i>destroyed</i>	1 X	\$217.60	\$217.60
FRONT SHOCK ABSORBER MOUNTING (RH) NH	1 X	\$217.60	\$217.60
FRONT DRIVE SHAFT NH	1 X	\$2,061.60	\$2,061.60
RACK & PINION ASSY NH	1 X	\$1,820.00	\$1,820.00
STG TIE ROD NH	1 X	\$135.00	\$135.00
STG TIE END NH	1 X	\$125.20	\$125.20
STG BALL JOINT NH	1 X	\$73.10	\$73.10
STABILIZER BAR NH	1 X	\$252.30	\$252.30
STABILIZER BAR BUSH NH	1 X	\$16.40	\$16.40

STABILIZER BAR LINK <i>NH</i>	1 ☒	\$68.10	\$68.10
STABILIZER BRACKET <i>NH</i>	2 ☒	\$24.00	\$48.00
FRONT SUSPENSION LOWER ARM (RH) <i>checked</i>	1 ☒	\$595.90	\$595.90
KNUCKLE ARM (RH) <i>checked</i>	1 ☒	\$1,104.00	\$1,104.00
			\$16,684.70
SUB TOTAL			\$3,336.94
LESS 20%			\$13,347.76
DISCOUNTED TOTAL			
	SN 1 ☒	\$216.00	\$216.00
FRONT TYRE (RH) <i>NH</i>			\$216.00
SUB TOTAL			
Labour Charge	560/-	1	\$800.00
Panel Beating	580/-	1	\$800.00
Spray Painting Charge	30/-	1	\$120.00
Wiring Charge	30/-	1	\$100.00
Tuff Kote	NH	1	\$50.00
Towing Charge	150/-	1	\$400.00
Remove/Refix Undercarriage (Frt)	60/-	1	\$120.00
Front/Four Wheel Alignment	NH	1	\$90.00
Remove/Refix Radiator	NH	1	\$130.00
Remove/Refix Aircon & Refill Gas			
			\$ 2,610.00
TOTAL LABOUR			\$ 16,173.76
ESTIMATE TOTAL			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

30/01/2020 @ 1600hrs

NA Antimal

2/5m 4⁵ days.

Ryan

LKK Auto

5824.32
supp 121.28
5945.60

4/5 4750/-

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 4-Feb-20

INSURANCE: _____

MODEL: HYUNDAI I40

VEHICLE NO.: SHA3550J

DESCRIPTION	QTY	LIST PRICE	AMOUNT
WIPER CONTAINER WITH MOTOR <i>CXKX</i>	1	\$151.60	\$151.60 ✓
			\$151.60
SUB TOTAL			\$30.32
LESS 20%			\$121.28
DISCOUNTED TOTAL			
			\$121.28
ESTIMATE TOTAL			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

mya

LKK And

9

Phone Number:
Fax Number:

Date: 31/1/2020 8:58 AM - 31/1/2020 9:02

Customer:
Company:
License NO: SHA3550J
Odometer:

VIN
Technician:
Order NO:

VEHICLE ALIGNMENT REPORT

HYUNDAI, i40 G 1.6 GDI, 11-11 (Customized)

VEHICLE ALIGNMENT							
HYUNDAI, i40 G 1.6 GDI, 11-11 (Customized)							
Primary Angles				Initial	Specifications		Final
					Min.	Max.	
Front	Caster	Left	4°05'	4°12'	5°12'	4°11'	
		Right	4°12'	4°12'	5°12'	4°17'	
	Camber	Left	-0°43'	-1°00'	0°00'	-0°39'	
		Right	0°00'	-1°00'	0°00'	-0°01'	
	Toe	Left	-0°21'	0°00'	0°12'	-0°16'	
		Right	-0°50'	0°00'	0°12'	-0°56'	
	Rear	Camber	Left	-0°26'	-1°30'	-0°30'	-0°23'
			Right	-0°31'	-1°30'	-0°30'	-0°30'
Toe		Left	0°14'	-0°03'	0°09'	0°14'	
		Right	0°18'	-0°03'	0°09'	0°18'	
		Total	0°32'	-0°06'	0°18'	0°32'	
		Thrust Angle	0°02'	99°59'		0°02'	
Secondary Angles				Initial	Specifications		Final
					Min.	Max.	
SAI	Left		10°34'	13°18'	14°18'	10°34'	
	Right		15°06'	13°18'	14°18'	15°06'	
Included Angle	Left		9°51'	99°59'	99°59'	9°55'	
	Right		15°06'	99°59'	99°59'	15°04'	
Toe Out On Turns	Left		----	99°59'	99°59'	----	
	Right		----	99°59'	99°59'	----	
Max Turn Inside	Left		----	99°59'	99°59'	----	
	Right		----	99°59'	99°59'	----	
Toe Curve Change	Left		----	0°00'	199°59'	----	
	Right		----	0°00'	199°59'	----	
Setback	Front		-0.14"	99.99"	99.99"	-0.14"	
	Rear		-0.30"	99.99"	99.99"	-0.30"	
Track Width Diff.			0.06"			0.06"	
Wheel Base Diff.			0.17"			0.17"	
Front Ride Height	Left		----	99.99"	99.99"	----	
	Right		----	99.99"	99.99"	----	
Rear Ride Height	Left		----	99.99"	99.99"	----	
	Right		----	99.99"	99.99"	----	
Frame Angle							