



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

MOHD FITRAS BIN BAKARAM
BLK 306 CANBERRA ROAD #08-71
SINGAPORE 750306

Attention : THE OWNER
Contact : 90293458

Estimate : ES006910

Date : 03/02/2020
Vehicle Num. : SJG574E
Make/Model : TOYOTA PREMIO-2008
Chassis/Eng# : NZT2603028643/1NZD099327
Accident Date : 22/01/2020
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

		LIST ITEMS :			
1.	1	BOOT LID		964.20	X
2.	1	BOOT LID LOCK		371.30	X
3.	1	PRIMO EMBLEM		78.00	—
4.	1	EMBLEM R/H		75.00	—
5.	1	TOYOTA LOGO		67.20	—
6.	2	BOOT LID REFLECTOR		336.00	X
7.	2	TAIL LAMP	415	483.00	X
8.	2	TAIL LAMP CLIP		6.50	X
9.	1	REAR END PANEL	508.20	644.20	X
10.	1	REAR END PANEL TOP GARNISH	233.85	281.00	X
11.	1	REAR BUMPER		855.00	—
12.	1	REAR BUMPER REINFORCEMENT		431.00	X
13.	1	REAR BUMPER SPONGE		197.00	X
14.	6	REAR BUMPER CLIP		6.00	—
15.	2	REAR BUMPER BRACKET		92.20	X
16.	2	REAR BUMPER SIDE RETAINER		187.20	X
17.	1	BOOT WEATHERSTRIP		316.00	X
18.	1	REAR END PANEL IMMOBILIZER SENSOR		263.00	X
		List Total S\$:		6,788.70	
		20.00% Discount S\$:		1,357.74	
				5,430.96	
		SPECIAL NETT ITEMS :			
1.	1	REVERSE SENSOR		280.00	X
		Special Nett Total S\$:		280.00	
		LABOUR :			
		RUST PROOFING TREATMENT		100.00	X

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

MOHD FITRAS BIN BAKARAM
BLK 306 CANBERRA ROAD #08-71
SINGAPORE 750306

Attention : THE OWNER
Contact : 90293458

Estimate : ES006910

Date : 03/02/2020
Vehicle Num. : SJG574E
Make/Model : TOYOTA PREMIO-2008
Chassis/Eng# : NZT2603028643/1NZD099327
Accident Date : 22/01/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		CHANGE TAIL LAMP AND CHECK WIRING	75.00	151. 75.00
		SPRAY PAINT DAMAGED AREA AFFECTED	1,100.00	504. 1,100.00
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR		
		CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	1,100.00	504. 1,100.00
		Labour Total S\$:		2,375.00

SingDollars : Eight Thousand Eighty-Five & Cents Ninety-Six Only

Total S\$: 8,085.96
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun