TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510

Company Reg. No. : 200714616M GST Registration No. : 200714616M

Our Ref: Your ref: SLF 9285 L SKE 3774 Z

30 January 2020

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER FOUR SINGAPORE 038986 Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: CHONG HANWEI

VEHICLE NUMBER: SLF 9285 L

YOUR INSURED VEHICLE NUMBER: SKF 3774 Z

ACCIDENT ON 20 Jan 2020 ALONG JUNC KEPPEL RD & TANJONG PAGAR RD

AT ABOUT 17:40 HOURS

We refer to your email / fax dated 30 Jan 2020 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair

BY EMAIL motorclaims.sg@fwd.com ONLY

inspection. Thank you! Appointed surveyor

(Name & Signature)

Date & Time of Inspection: