

ASS. REC. BY:

REF: CS3/CT120001781 / G14 f307

Special Instruction:

Supervisor: G14

ASSIGNMENT (Office)

From (Person): Ben Tang

of CT1

Date/Time: 32. 2020 2.22p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 917L

Insured: SJC 9595G

at Workshop m/s Lian Hong Seng

Tel: 94279394

of AMK Industri | Park 2 Block 5035 # 01-345

Policy No:

Claim No: SNM20D200569/SJC9595G/BEN

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

*my*

H.O.D. Endorsement:

Date/Time: 31/2/2020 4.04p.M

Person Contacted: MS Apple

Vehicle: IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLE 917L - X
	SJC 9595G - CS/CT1 19016590 / Etd 302 PRA. 17/09/2019
	Dismantle: 4/2/2020.
	After repair: 7/2/2020

**ASSIGNMENT**

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD /  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Lian Hong Seng  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SUE917L yr Regn: - /  
 Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Estima <sup>24A</sup> C.C. 2362  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 181664 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ACR 50 007 8835  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225 / 45 R 18  
 R: 11

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes or No**  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes or No**  
 Est. Repairs: 4 days Res.: **Yes or No**  
 Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes or No**  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: **IN / OUT**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental

Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm Rear 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 03-02-20  
 Survey held at w/s 5230 pm  
 Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<del>\$2000</del> \$3000 - \$4000
	RECEIVED 11 FEB 2020

Date/Time, File Pass to?  : **Preli. Report**  
 : **Final Report**

Days Of Repair: 4  
 Resurvey No. of Trip: 2

Survey Fee:	190
Transportation:	
3 + RS: SI	
Photos	
Other:	
TOTAL	190

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Insp (\$)  
 : Meet end (\$)

Report Form: PRS

Emp. Sum / A.B. No: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2020		11 Feb 2020 13:32 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by insurer]							
Insured:									
Main Claimant:	<b>CHAN KIT LEONG</b>								
Vehicle Reg. No.:	<b>SLE917L</b>	Date of Loss:	30/01/2020 08:00 - :59						
Claim Type:	<b>TP / SNM20D200569/SJC9595G/BEN</b>	Policy/Cover Note No.:	DMPCSN3056891901 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJC9595G</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Lian Hong Seng Motor Works (HQ) 5034 ANG MO KIO INDUSTRIAL PARK 2, #01-339, 569537 Ang Mo Kio - Tel: 64825439</b>								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]</b>								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/02/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Ben Tang <Ben.Tang@sg.cntaiping.com>  
**Sent:** Monday, 3 February 2020 2:22 PM  
**To:** 'Jenny'  
**Cc:** Claims Dept of CTI; 'Derrick Tan'; 'Ling Leong Hui'; Rachel Ling; 'tcmg backup'; assignments@lkkauto.com  
**Subject:** RE: OUR REF: SNM20D200569/SJC9595G/BEN & YR REF: SLE917L - NOTICE OF PRE-REPAIR INSPECTION FOR MOTOR VEHICLE No. SLE 917 L

Dear Jenny

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards  
Ben Tang  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6175 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Jenny <jenny@tcmg.com.sg>  
**Sent:** Monday, February 3, 2020 11:49 AM  
**To:** Ben Tang <Ben.Tang@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; 'Derrick Tan' <derrick21tan@hotmail.com>; 'Ling Leong Hui' <lhling@tcmg.com.sg>; Rachel Ling <jin@tcmg.com.sg>; 'tcmg backup' <tcmg.backup@gmail.com>  
**Subject:** RE: OUR REF: SNM20D200569/SJC9595G/BEN & YR REF: SLE917L - NOTICE OF PRE-REPAIR INSPECTION FOR MOTOR VEHICLE No. SLE 917 L  
**Importance:** High

**IMMEDIATE ATTENTION**

Your ref: SNM20D200569/SJC9595G/BEN  
Our ref: TCMG/SLE 917 L/0220/ADG

Dear Ben

We refer to the above matter and to your email of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.



*Our team wishes you and your staff a very Happy and Prosperous Chinese New Year.*

(P/S : Please acknowledge receipt of this e-mail. Thank you.)

Regards

Jenny Tham  
TOMMY CHOO, MARK GO LLC  
151 Chin Swee Road  
#14-15/16 Manhattan House  
Singapore 169876  
Tel: 6532 2455 - Fax: 6538 9850  
Email Address: [jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)

---

**From:** Ben Tang [<mailto:Ben.Tang@sg.cntaiping.com>]

**Sent:** 03 February 2020 11:38

**To:** [jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)

**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** RE: OUR REF: SNM20D200569/SJC9595G/BEN & YR REF: SLE917L - NOTICE OF PRE-REPAIR INSPECTION FOR MOTOR VEHICLE No. SLE 917 L

**WITHOUT PREJUDICE**

Dear Sir,

We refer to your email dated 03 February 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards  
Ben Tang  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6175 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Monday, February 3, 2020 10:52 AM  
**To:** Ben Tang <[Ben.Tang@sg.cntaiping.com](mailto:Ben.Tang@sg.cntaiping.com)>; [jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)  
**Subject:** OUR REF: SNM20D200569/SJC9595G/BEN & YR REF: SLE917L - NOTICE OF PRE-REPAIR INSPECTION FOR MOTOR VEHICLE No. SLE 917 L  
**Importance:** High

Dear Ben,

Please conduct PRS-SLE917L -soonest possible.

Office in charge -Ben Tan -DID 6389 6175

Dear Jenny,

\*\*\* kindly quote our reference number when replying. \*\*\*

Thank you.

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website:[www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Jenny <[jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)>

**Sent:** Monday, February 3, 2020 9:54 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** 'Derrick Tan' <[derrick21tan@hotmail.com](mailto:derrick21tan@hotmail.com)>; 'Ling Leong Hui' <[lhling@tcmg.com.sg](mailto:lhling@tcmg.com.sg)>; Rachel Ling <[jlin@tcmg.com.sg](mailto:jlin@tcmg.com.sg)>; 'tcmg backup' <[tcmg.backup@gmail.com](mailto:tcmg.backup@gmail.com)>

**Subject:** NOTICE OF PRE-REPAIR INSPECTION FOR MOTOR VEHICLE No. SLE 917 L [ Your ref: SJC 9595 G ]

**Importance:** High

**IMMEDIATE ATTENTION**

Your ref: (CHINA TAIPING) SJC 9595 G

Our ref: TCMG/SLE 917 L/0220/ADG

Dear Sirs

We refer to the above matter.

We attached herein copy of our Notice of Pre-Repair Inspection for your attention.

Thank you.



*Our team wishes you and your staff a very Happy and Prosperous Chinese New Year.*

*(P/S : Please acknowledge receipt of this e-mail. Thank you.)*

Regards

Jenny Tham  
TOMMY CHOO, MARK GO LLC  
151 Chin Swee Road  
#14-15/16 Manhattan House  
Singapore 169876  
Tel: 6532 2455 - Fax: 6538 9850  
Email Address: [jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)

# TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169878  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref : TCMG/SLE 917 L/0220/ADG

Your Ref : SJC 9595 G

3 February 2020

**BY E-MAIL ONLY**  
claimsdept@sg.cntaiping.com

M/s China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909

## Attn: Motor Claims Department

Dear Sirs,

### PRE-REPAIR INSPECTION NOTICE

We act for **Chan Kit Leong**, the owner and/or driver of motor vehicle no. **SLE 917 L**, which was involved in an accident along PIE expressway towards Changi on 30<sup>th</sup> January 2020 at 08:40 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SJC 9595 G** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at Ang Mo Kio Industrial Park 2 Block 5035 #01-345, Singapore 569538 – Ms Apple – 9427 9394 or Mr Derrick Tan – 9833 4443).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully



LING LEONG HUP (MR)

cc. M/s Aden Garage Pte Ltd  
(Your ref: SLE 917 L)

BY E-MAIL derrick21tan@hotmail.com

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2020		11 Feb 2020 13:32 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>CHAN KIT LEONG</b>								
Vehicle Reg. No.:	<b>SLE917L</b>	Date of Loss:	30/01/2020 08:00 - :59						
Claim Type:	<b>TP / SNM20D200569/SJC9595G/BEN</b>	Policy/Cover Note No.:	DMPCSN3056891901 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJC9595G</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Lian Hong Seng Motor Works (HQ)</b> 5034 ANG MO KIO INDUSTRIAL PARK 2, #01-339, 569537 Ang Mo Kio - Tel: 64825439								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ben Tang</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 20/02/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLE917L (SNM20D200569/SJC9595G/BEN)  
 [SJC9595G]  
 TP  
 CHAN KIT LEONG  
 Jan 30 2020 8:00AM  
 [-]  
 Lian Hong Seng Motor Works

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
<b>Photos/Images</b>			3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
2	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
3	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
4	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
5	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
6	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
7	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
8	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
9	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
10	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
11	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
12	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
13	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
14	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
15	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
16	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
17	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
18	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
19	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
20	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
21	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
22	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
23	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
24	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
25	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
26	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
27	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
28	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
29	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
30	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
31	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
32	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
33	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
34	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
35	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
36	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>
37	11/02/20 14:51	General View	 Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	11/02/20 14:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
54	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
55	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
56	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
57	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
58	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
59	11/02/20 14:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI20001781/GYF3E2  
**Date:** 12/02/2020

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3056891901
Claimant Vehicle No :	SLE917L	Insured Vehicle No :	SJC9595G
Date of Loss:	30/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200569/SJC9595G/BEN

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE917L	Engine No:	HIDDEN
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500078835
Reg. Date:	(Man. Year: )	Odometer:	181664 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	11/02/2020		
Date Inspected:	03/02/2020	Inspected At:	Lian Hong Seng Motor Works (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537
Estimated Period of Repair:	4.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2020)	
<b>Parts:</b> M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE917L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >