

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9952C

AAD2001-228

*Not Authored
C/Smp & 170dp*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

31 JAN 2020

SHD 9952C
VF1ABL15AUC277547
RENAULT
LATITUDE
30.1.2020
LONPAC
5/6/2014

PART	LIST	Price	Status
1 BUMPER COVER REAR	Pr	\$ 561.70	✓
1 BUMPER LOWER REAR	Ad/Wr	\$ 411.90	✓
1 BUMPER BRACKET CTR REAR	Sm	\$ 98.10	X
1 BUMPER BRACKET SIDE RH REAR	Sm	\$ 82.10	X
1 BUMPER RETAINER RH REAR	Sm	\$ 59.80	✓
1 BUMPER REFLECTOR RH	CM	\$ 16.60	✓
1 BUMPER BRACKET SIDE LH REAR	Sm	\$ 80.80	} X
1 BUMPER RETAINER LH REAR	Sm	\$ 54.20	
1 BUMPER REFLECTOR LH	Sm	\$ 16.60	
1 BUMPER BEAM REAR	R	\$ 547.80	
1 BUMPER BEAM BRACKET LH REAR	R	\$ 114.50	
1 BUMPER BEAM BRACKET RH REAR	R	\$ 100.90	
1 OUTER PANEL REAR (End Panel)	R	\$ 745.80	
1 OUTER PANEL REAR (End Panel) TRIM	Sm	\$ 404.56	
1 TAILLAMP RH	Sm	\$ 313.10	
1 TAILLAMP PANEL RH	R	\$ 401.40	
1 TAILLAMP LH	Sm	\$ 401.40	
1 TAILLAMP PANEL LH	R	\$ 401.40	
1 BOOT REAR	R	\$ 1,677.20	
1 BOOT FINISHER	Sm	\$ 344.70	
1 BOOT WHEATERSTRIP	Sm	\$ 178.20	
1 BOOT REFLECTOR LAMP LH	Sm	\$ 277.70	
1 BOOT REFLECTOR LAMP RH	Sm	\$ 277.70	
1 BOOT BADGE 'RENAULT'	Me	\$ 82.40	✓
1 BOOT BADGE	Me	\$ 95.80	✓
1 BOOT STRUT LH	Sm	\$ 145.10	X

Trans-cab Auto Services Pte Ltd

AAD2001-228

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9952C

1	BOOT STRUT RH	\$	Sm	145.10	}	
1	BOOT HINGE LH	\$	R	254.20		
1	BOOT HINGE RH	\$	R	253.80		
2	BOOT RUBBER PLUG	\$	Sm	139.90		
1	SPARE TYRE BOARD	\$	Sm	680.90		
1	BOOT LOCK LINKAGE HOLDER	\$	Sm	99.50		
1	BOOT INNER TRIM BOARD	\$	Sm	611.00		
1	BOOT SWITCH	\$	Sm	113.00		
1	BOOT LOCK	\$	R	246.60		
1	BOOT LOCK CATCH	\$	R	41.70		
1	EXHAUST CAP REAR	\$	Sm	125.40		
TOTAL		\$		10,602.56		
	10%	\$		1,060.26		
		\$		9,542.30		

Special Nett

1SET PARKING AID	\$	Sm	700.00	X
1SET REAR BUMPER CLIP	\$	na	66.00	—
1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	—
1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
1 BOOT STICKER "6555-3333"	\$	na	30.00	—
1 Rear Bumper Protector	\$	na	100.00	805A
1 REAR LICENCE PLATE WITH HOLDER	\$	Sm	80.00	X
1 BOOT INNER TRIM CLIP	\$	na	45.00	X
1SET BOOT FINISHER CLIP	\$	na	24.20	X
1 TAILLAMP CLIP LH	\$	na	5.00	X
1 TAILLAMP CLIP RH	\$	na	5.00	X
TOTAL		\$		1,266.20

Trans-cab Auto Services Pte Ltd

AAD2001-228

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9952C

TOTAL PARTS	\$	10,808.50
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>300</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>60</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>440</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9952C

AAD2001-228

TOTAL \$ 14,170.00

Over All Total \$ 24,978.50

LUMP SUM (REPAIR DAY)

~~20 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: