



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE20001784/Aba3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 28-05-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 8783X	Veh. Inspected	SGW 2721K
Policy No.	8-V0024092-MVA	Coverage (\$)	0.00
Claim No.	V0024092	Excess (\$)	0.00
Assign From		Assign Date	31/01/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMRB18508C200223	Colour	GREY
Odometer	394072	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/01/2020	Inspection Date	31/01/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------