

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 309U**AAD2001-232***Not Authorised
C/Smp & Sodr*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 309U

VF1ABL15AUC282340

RENAULT

LATITUDE

30.1.2020

AIG

4/3/2016

PART	
1	FENDER PANEL REAR RH
1	FENDER PANEL INNER TRIM REAR RH
1	WHEELARCH REAR RH
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR RH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET RH REAR
1	TAILLAMP RH
1	BOOT REFLECTOR LAMP RH
1	ROCKER PANEL INNER GARNISH RH
1	ROCKER PANEL INNER RH
1	ROCKER PANEL OUTER RH
1	ROCKER PANEL CENTER RH

LIST	
\$	1,933.20 X
\$	671.45 X
\$	275.40 X
\$	561.70 ✓
\$	411.90
\$	98.10
\$	82.10
\$	59.80
\$	16.60
\$	547.80
\$	100.90
\$	313.10
\$	277.70
\$	466.51
\$	1,024.79
\$	1,184.99
\$	990.25

TOTAL	\$	9,016.29
10%	\$	901.63
	\$	8,114.66

Special Nett

1	FENDER INNER TRIM CLIP RH	\$	28.00 X
1	TAILLAMP CLIP RH	\$	5.00 X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00 X

Trans-cab Auto Services Pte Ltd**AAD2001-232**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 309U

1	REAR RIGHT TYRE	\$	300.00	} X In
1	REAR RIGHT TYRE RIM	\$	380.00	
1SET	PARKING AID	\$	700.00	
1SET	REAR BUMPER CLIP	\$	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	66.00	
1	Rear Bumper Protector	\$	100.00	
2	REAR WINDSCREEN SEALANT	\$	80.00	
1	WINDSCREEN MOULDING	\$	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
TOTAL		\$	2,045.00	
TOTAL PARTS		\$	10,159.66	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	2001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪ 380.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	↪ 380.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-232**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 309U

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nu</i> 380.00	<i>X</i>
To rust-proofing of the affected areas.	\$	<i>7</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>7</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>7</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>69</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2201</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>7</i> 170.00	<i>X</i>
TOTAL	\$	14,590.00	
Over All Total	\$	24,749.66	

LUMP SUM (REPAIR DAY)*20 DAYS**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: