

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9211H**AAD2001-200***Not Notion
Resurvey B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

31 JAN 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9211H

JTDKB3FU203079670

TOYOTA

PRIUS

25.1.2020

III

29/3/2019

PART

- 1 REAR BUMPER
- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO 1
- 1 COVER, FLOOR UNDER, NO 2
- 1 COVER, REAR FLOOR
- 1 FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY

LIST

\$	Bul/cm	442.60	✓
\$		332.70	7
\$	SL	15.40	X
\$	Not/cm	576.30	✓
\$	SL	116.50	X
\$	SL	117.70	X
\$	R	1,147.80	X
\$	cm	925.60	✓
\$	SL	372.30	X
\$	SL	650.30	
\$	SL	502.00	
\$	SL	451.80	
\$	SL	123.70	
\$	SL	123.70	
\$	SL	502.00	
\$	SL	443.30	
\$	SL	126.70	
\$	SL	175.10	
\$	SL	241.90	
\$	SL	229.90	
\$	R	516.00	
\$	R	716.60	
\$	R	246.10	
\$	SL	132.70	
\$	SL	79.60	

Trans-cab Auto Services Pte Ltd**AAD2001-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9211H

1	FRONT BUMPER SIDE RETAINER RH	\$	80.10	}	X
1	FRONT BUMPER SIDE RETAINER LH	\$	82.30		
1	COVER SUB-ASSY, ENGINE, NO.1	\$	472.40		
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	241.90		
1	FRONT LED LAMP (LOWER) LH	\$	951.40		
1	FRONT HEADLAMP LH	\$	2,637.60		
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	960.50		
1	MOTOR, HEADLAMP LEVELING, LH	\$	487.50		
1	FRONT LED LAMP (LOWER) RH	\$	951.40		
1	FRONT HEADLAMP RH	\$	2,637.60		
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	960.50	}	✓
1	MOTOR, HEADLAMP LEVELING, RH	\$	487.50		
1	GRILLE SUB-ASSY, RADIATOR	\$	346.00	}	X
1	GRILLE, RADIATOR, LOWER NO.1	\$	170.10		
1	EMBLEM ASSY, RADIATOR GRILLE	\$	90.80		
1	FRONT FENDER RH	\$	977.80		
1	LINER, FRONT FENDER, RH	\$	206.70		
1	EMBLEM, SIDE PANEL RH	\$	54.60		
1	FRONT FENDER LH	\$	977.80		
1	LINER, FRONT FENDER, LH	\$	202.50		
1	EMBLEM, SIDE PANEL LH	\$	54.60		
1	FRONT BONNET	\$	983.10		
1	HINGE ASSY, HOOD, LH	\$	58.90		
1	HINGE ASSY, HOOD, RH	\$	58.90		
1	JAR ASSY, WINDSHIELD WASHER	\$	219.10		
1	INLET SUB ASSY, WASHER	\$	67.00		
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	292.40		
1	COVER, RADIATOR SUPPORT OPENING	\$	235.30		

TOTAL	\$	25,254.60
25%	\$	6,313.65
	\$	18,940.95

Trans-cab Auto Services Pte Ltd**AAD2001-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9211H**Special Nett**

1SET	PARKING AID	\$	<i>Pr</i>	700.00	X
1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	✓
1	REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i>	47.00	—
1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i>	52.90	—
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i>	53.50	✓
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i>	80.00	<i>301n</i>
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i>	80.00	<i>301n</i>
1	REAR BUMPER PROTECTOR	\$	<i>nn</i>	100.00	<i>301n</i>
1	REAR WHEEL RIM	\$	<i>Pr</i>	1,879.40	}
1	REAR TYRE 195/65/15	\$	<i>Pr</i>	350.00	
1	REAR WHEEL RIM COVER	\$	<i>Pr</i>	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	<i>nn</i>	35.00	
1	REAR LH BUMPER RETAINER CLIP	\$	<i>nn</i>	35.00	
1SET	FRNT RH BUMPER RETAINER CLIP	\$	<i>nn</i>	35.00	
1	CLIP, FRONT FENDER LINER LH	\$	<i>nn</i>	35.00	
1SET	FRONT BUMPER CLIP	\$	<i>nn</i>	66.00	
1	CLIP, FRONT FENDER LINER RH	\$	<i>nn</i>	35.00	
1SET	FRNT LH BUMPER RETAINER CLIP	\$	<i>nn</i>	35.00	
1	REAR NUMBER PLATE WITH HOLDER	\$	<i>Pr</i>	200.00	}
1	FRONT WHEEL RIM	\$	<i>Pr</i>	1,879.40	
1	FRONT TYRE 195/65/15	\$	<i>Pr</i>	350.00	
1	FRONT WHEEL RIM COVER	\$	<i>Pr</i>	211.50	
1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>Del</i>	200.00	
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	100.00	X
1	WINDSCREEN MOULDING	\$	<i>nn</i>	120.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	X
TOTAL		\$		7,057.20	

TOTAL PARTS \$ 25,998.15**LABOUR**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9211H**AAD2001-200**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>Nn</i> 170.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>6601</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>301</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>301</i>

Trans-cab Auto Services Pte Ltd**AAD2001-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9211H

To transfer of Bonnet fittings, attachments and
perform water seepage test.

\$ *nn* 170.00 X

To transfer of Front Bumper fittings, attachments and
perform water seepage test.

\$ *nn* 170.00 X

To transfer of Front Fender fittings, attachments and
perform water seepage test.

\$ *nn* 170.00 X**TOTAL \$ 16,350.00****Over All Total \$ 42,348.15****(PART-BY-PART) Repair Days**~~20 Days~~*3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: