

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9211H****AAD2001-200***Not Notion**Resurvey B4 pain***P/P = \$3,112.28**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD 9211H**

JTDKB3FU203079670

TOYOTA

PRIUS

25.1.2020

**III**

29/3/2019

**PART****LIST**

1	REAR BUMPER	\$	<i>Bul/cm</i> 442.60	✓
1	REAR BUMPER RE-INFORCEMENT	\$	332.70	✗ SVC
1	REAR BUMPER TOWING COVER	\$	<i>SL</i> 15.40	✗
1	GUARD, REAR BUMPER, CENTER	\$	<i>Not/cm</i> 576.30	✓
1	REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i> 116.50	✗
1	REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i> 117.70	✗
1	REAR TAILGATE	\$	<i>R</i> 1,147.80	✗
1	REAR TAILGATE OUTER GARNISH	\$	<i>cm</i> 925.60	✓
1	REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i> 372.30	} ✗
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>SL</i> 650.30	
1	TAILLAMP LOWER RH	\$	<i>SL</i> 502.00	
1	TAILLAMP UPPER RH	\$	<i>SL</i> 451.80	
1	REAR BUMPER SIDE RH	\$	<i>SL</i> 123.70	
1	REAR BUMPER SIDE LH	\$	<i>SL</i> 123.70	
1	TAILLAMP LOWER LH	\$	<i>SL</i> 502.00	
1	TAILLAMP UPPER LH	\$	<i>SL</i> 443.30	
1	COVER, DECK TRIM, REAR	\$	<i>SL</i> 126.70	
1	COVER, FLOOR UNDER, NO 1	\$	<i>SL</i> 175.10	
1	COVER, FLOOR UNDER, NO 2	\$	<i>SL</i> 241.90	
1	COVER, REAR FLOOR	\$	<i>SL</i> 229.90	
1	FRONT BUMPER	\$	<i>R</i> 516.00	
1	REINFORCEMENT, FRONT BUMPER	\$	<i>R</i> 716.60	
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	<i>R</i> 246.10	
1	ABSORBER, FRONT BUMPER, LOWER	\$	<i>SL</i> 132.70	
1	ABSORBER, FRONT BUMPER ENERGY	\$	<i>SL</i> 79.60	

**Trans-cab Auto Services Pte Ltd****AAD2001-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9211H**

1	FRONT BUMPER SIDE RETAINER RH	\$	80.10	}	X
1	FRONT BUMPER SIDE RETAINER LH	\$	82.30		
1	COVER SUB-ASSY, ENGINE, NO.1	\$	472.40		
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	241.90		
1	FRONT LED LAMP (LOWER) LH	\$	951.40		
1	FRONT HEADLAMP LH	\$	2,637.60		
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	960.50		
1	MOTOR, HEADLAMP LEVELING, LH	\$	487.50		
1	FRONT LED LAMP (LOWER) RH	\$	951.40		
1	FRONT HEADLAMP RH	\$	2,637.60		
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	960.50	}	✓
1	MOTOR, HEADLAMP LEVELING, RH	\$	487.50		
1	GRILLE SUB-ASSY, RADIATOR	\$	346.00	}	X
1	GRILLE, RADIATOR, LOWER NO.1	\$	170.10		
1	EMBLEM ASSY, RADIATOR GRILLE	\$	90.80		
1	FRONT FENDER RH	\$	977.80		
1	LINER, FRONT FENDER, RH	\$	206.70		
1	EMBLEM, SIDE PANEL RH	\$	54.60		
1	FRONT FENDER LH	\$	977.80		
1	LINER, FRONT FENDER, LH	\$	202.50		
1	EMBLEM, SIDE PANEL LH	\$	54.60		
1	FRONT BONNET	\$	983.10		
1	HINGE ASSY, HOOD, LH	\$	58.90		
1	HINGE ASSY, HOOD, RH	\$	58.90		
1	JAR ASSY, WINDSHIELD WASHER	\$	219.10		
1	INLET SUB ASSY, WASHER	\$	67.00		
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	292.40		
1	COVER, RADIATOR SUPPORT OPENING	\$	235.30		

<b>TOTAL</b>	<b>\$</b>	<b>25,254.60</b>
<b>25%</b>	<b>\$</b>	<b>6,313.65</b>
	<b>\$</b>	<b>18,940.95</b>

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9211H****AAD2001-200****Special Nett**

1SET	PARKING AID	\$	<i>Pr</i> 700.00	X
1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00	✓
1	REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i> 47.00	—
1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i> 52.90	—
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i> 53.50	✓
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	<i>301n</i>
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i> 80.00	<i>301n</i>
1	REAR BUMPER PROTECTOR	\$	<i>nn</i> 100.00	<i>301n</i>
1	REAR WHEEL RIM	\$	<i>Pr</i> 1,879.40	}
1	REAR TYRE 195/65/15	\$	<i>Pr</i> 350.00	
1	REAR WHEEL RIM COVER	\$	<i>Pr</i> 211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	
1	REAR LH BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	
1SET	FRNT RH BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	
1	CLIP, FRONT FENDER LINER LH	\$	<i>nn</i> 35.00	
1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00	
1	CLIP, FRONT FENDER LINER RH	\$	<i>nn</i> 35.00	
1SET	FRNT LH BUMPER RETAINER CLIP	\$	<i>nn</i> 35.00	
1	REAR NUMBER PLATE WITH HOLDER	\$	<i>Pr</i> 200.00	}
1	FRONT WHEEL RIM	\$	<i>Pr</i> 1,879.40	
1	FRONT TYRE 195/65/15	\$	<i>Pr</i> 350.00	
1	FRONT WHEEL RIM COVER	\$	<i>Pr</i> 211.50	
1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>Del</i> 200.00	<i>455n</i>
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 100.00	X
1	WINDSCREEN MOULDING	\$	<i>nn</i> 120.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	X
<b>TOTAL</b>		<b>\$</b>	<b>7,057.20</b>	

**TOTAL PARTS \$ 25,998.15****LABOUR**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9211H****AAD2001-200**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>Nn</i> 170.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>6601</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>301</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>3001</i>

**Trans-cab Auto Services Pte Ltd****AAD2001-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9211H**

To transfer of Bonnet fittings, attachments and  
perform water seepage test.

\$ *nn* 170.00 X

To transfer of Front Bumper fittings, attachments and  
perform water seepage test.

\$ *nn* 170.00 X

To transfer of Front Fender fittings, attachments and  
perform water seepage test.

\$ *nn* 170.00 X**TOTAL \$ 16,350.00****Over All Total \$ 42,348.15****(PART-BY-PART) Repair Days**~~20 Days~~*3 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: