

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5963C**AAD2001-220***Not Authorised
11 Bny & 2650h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

31 JAN 2020

SHC 5963C

VF1ABL15AUC281165

RENAULT

LATITUDE

29.1.2020

~~FCIL~~ *W*

24/12/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER BRACKET FRT RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT RH

	LIST	
\$	<i>CM</i>	747.20 ✓
\$	<i>SL</i>	344.70 X
\$	<i>SL</i>	394.68 X
\$	<i>DI</i>	101.40 ✓
\$	<i>SL</i>	10.70 X
\$	<i>SL</i>	292.50 X
\$	<i>SL</i>	147.00 X
\$	<i>RU</i>	207.21 ✓
\$	<i>R</i>	663.70 X
\$	<i>ngcm</i>	743.60 ✓
\$	<i>R</i>	128.30 X
\$	<i>B</i>	437.10 ✓
\$	<i>DI</i>	191.40 ✓
\$	<i>SL</i>	11.80
\$	<i>SL</i>	106.40
\$	<i>SL</i>	66.30
\$	<i>SL</i>	60.90
\$	<i>R</i>	177.22
\$	<i>SL</i>	969.90
\$	<i>SL</i>	225.36
\$	<i>SL</i>	686.00
\$	<i>SL</i>	592.70
\$	<i>R</i>	41.60
\$	<i>R</i>	1,312.70
\$	<i>SL</i>	294.30
\$	<i>SL</i>	53.30

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5963C**AAD2001-220**

1	BONNET HINGE RH	\$	<i>R</i>	237.40	
1	BONNET LOCK	\$	<i>R</i>	152.80	
1	BONNET CABLE	\$	<i>Sn</i>	55.20	
1	BONNET CABLE COVER	\$	<i>Sn</i>	80.60	}
1	BONNET SEAL OUTER	\$	<i>Sn</i>	83.20	
1	BONNET SEAL INNER	\$	<i>Sn</i>	70.10	
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i>	82.60	
1	WIPER RESERVOIR	\$	<i>R</i>	179.60	
1	WIPER RESERVOIR NECK	\$	<i>Sn</i>	29.30	X
1	DOOR PANEL FRT RH	\$	<i>R</i>	2,844.66	X
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i>	1,483.40	X
1	DOOR HARNESS WIRE RH	\$	<i>Sn</i>	2,670.00	X

TOTAL	\$	16,976.82
10%	\$	1,697.68
	\$	15,279.14

Special Nett

1	BUMPER CLIP FRT	\$	<i>na</i>	66.00	
1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	}
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i>	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i>	30.00	
1	WHEELARCH CLIP FRT RH	\$	<i>na</i>	30.50	
1	FRONT RIGHT TYRE	\$	<i>Sn</i>	300.00	
1	FRONT RIGHT TYRE RIM	\$	<i>Sn</i>	380.00	
1	FRONT RIGHT TYRE RIM COVER	\$	<i>Sn</i>	60.00	
1SET	Front licence plate with holder	\$	<i>Sn</i>	80.00	}
1SET	RADIATOR GRILLE SCREW	\$	<i>na</i>	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i>	52.00	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>na</i>	80.00	
1	FRONT DOOR STICKER 'Classic'	\$	<i>na</i>	80.00	

Trans-cab Auto Services Pte Ltd**AAD2001-220**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5963C

TOTAL	\$	1,356.00
--------------	-----------	-----------------

TOTAL PARTS	\$	16,635.14
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
To transfer of door fittings, attachment and perform water seepage test.	\$	na 170.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-220**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5963C

To rust-proofing of the affected areas.	\$	170.00	<i>30%</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20%</i>
TOTAL	\$	14,170.00	
Over All Total	\$	30,805.14	

LUMP SUM (REPAIR DAY)~~**20 DAYS**~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: