

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/91254449 Fax 6484 1482

Email:slpmotoring@gmail.com

Asker

NOT Authorized

6/1 Rm 85200/- max
Resurvey After Repair

M/s MS First Capital Insurance Limited

DATE

12.02.2020

36 Robinson Road #16-01

CAR NO

SGF 8684 J

City House S068877

MAKE

Toyota Corolla 1.6

16 days

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : SHD 6788 E

Pc	Pcs	MR053ZEC107118317	UNIT PRICE	AMOUNT	
1	pcs	Rear boot lid		\$685.00	—
1	pc	Rear boot lid "1.6 "		\$35.49	—
1	pc	Rear boot lid "Corolla"		\$54.47	—
1	pc	Rear boot lid "Altis"		\$45.20	—
1	pc	Rear boot lid top lock		\$61.00	—
1	pc	Rear boot rubber		\$165.00	508m
2	pcs	Rear boot lid left & right side reflector	\$233.80	\$467.60	4
1	pc	Rear boot lid top cover board		\$162.00	X
1	pcs	Rear boot lid outer chrome handle		\$246.00	X
1	pcs	Rear end panel		\$486.80	—
1	pcs	Rear end panel lock garnish		\$177.73	—
8	pcs	Rear end panel lock garnish clips	\$5.00	\$40.00	—
1	pcs	Rear end panel joint sealant		\$80.00	—
2	pcs	Tail lamp (left & right)	\$315.00	\$630.00	4
2	pcs	Tail lamp apron (left & right)	\$55.00	\$110.00	—
1	pcs	Rear bumper		\$435.00	—
10	pcs	Rear bumper clips	\$5.00	\$50.00	—
1	pcs	Rear bumper centre reinforcement		\$232.00	X
1	pcs	Rear bumper sponge		\$125.00	X
2	pcs	Rear bumper top bracket	\$79.00	\$158.00	—
2	pcs	Rear bumper side retainer (left & right)	\$59.50	\$119.00	—
2	pcs	Rear bumper left & right side lower retainer	\$47.64	\$95.00	—
1	set	Rear reverse sensor		\$350.00	200m
1	pcs	Rear exhaust silencer		\$728.00	—
1	pcs	Rear spare tyre tank floor panel		\$757.00	—
2	pcs	Rear spare tyre tank left & right side panel	\$249.00	\$498.00	4
1	pcs	Rear number plate with casing		\$100.00	X
2	pcs	Rear left & right side mudguard	\$860.10	\$1,720.20	4
2	pcs	Rear left & right side mudguard inner trim cover	\$295.80	\$591.60	4
2	pcs	Rear left & right side mudguard lower air duct	\$115.00	\$230.00	X
2	pcs	Rear left & right side mudguard inner cowling	\$119.80	\$239.60	X
8	pcs	Rear right side mudguard inner cowling clips	\$3.90	\$31.20	X
8	pcs	Rear left side mudguard inner cowling clips	\$3.90	\$31.20	X
1	pc	Rear wind screen moulding		\$85.00	—
			Total		

Page 1 of 2

SLP Motoring Services.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/91254449 Fax 6484 1482


Email:slpmotoring@gmail.com

M/s MS First Capital Insurance Limited DATE 12.02.2020
36 Robinson Road #16-01 CAR NO SGF 8684 J
City House S068877 MAKE Toyota Corolla 1.6

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : SHD 6788 E

Pc	Pcs	MR053ZEC107118317	UNIT PRICE	AMOUNT
		Continue from page one.		\$10,022.09
		To remove and replace rear windscreen.		\$180.00 120k
		To apply silicon onto rear windscreen.		\$90.00 40k
		To apply anti-rust on the accident affected area.		\$120.00 ✓
		To check electrical wiring for proper functionality and test rear reverse sensor.		\$120.00 70k
		To conduct water leakage test.		\$50.00 30k
		To remove and replace rear exhaust assy.		\$120.00 60k
		Straightening, repairing and realigning on the affected area, cutting rear two side mudguard, rear end panel, dismantle and replace the above mentioned parts.		\$2,000.00 180k
		Spray painting for all accident affected parts. Rear bumper, rear end panel, rear boot lid, rear left and right side mudguard panels.		\$1,500.00 130k
Total				\$14,202.09

Page 2 of 2


SLP Motoring Services.