



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMK 5203 L

Parts	(a) Cost / List Price Items	\$	1,097.00
	Plus/Less 20%	\$	219.40
	Total of Cost / List	\$	877.60
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	877.60
Labour		\$	1,350.00
Total		\$	2,227.60

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 21/3/20 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De

Date: 21/3/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMK 5203 L**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP72003397**

Submit By : **SERENCE**
Year Manufacture : **2018**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Buc / cm</i>	1	\$480.00		✓
2	Front bumper clip <i>cm</i>	10	\$20.00		✓
3	Front bumper side retainer LH <i>SL</i>	1	\$6.00		X
4	Front bumper side retainer RH <i>SL</i>	1	\$6.00		X
5	RH front fender <i>BH</i>	1	\$130.00		✓
6	RH front fender undershield <i>SL</i>	1	\$70.00		X
7	RH front fender undershield clip <i>cm</i>	10	\$20.00		X
8	RHF fender wording "HYBRID" <i>cm</i>	1	\$35.00		✓
9	RH front rim <i>SL</i>	1	\$150.00		X
10	RH front tyre <i>SL</i>	1	\$85.00		✓
11	RH front hup cap <i>SL</i>	1	\$95.00		X
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

