

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE LIMITED	<b>Document No.</b>	: SQT20000490	<b>Page</b>	1
	36 ROBINSON ROAD	<b>Date</b>	: 31. Jan 2020		
	#16-01 CITY HOUSE	<b>Customer No.</b>	: WZF002		
	SINGAPORE 068877	<b>Svc Advisor</b>	: RUEBEN THOMAS		
<b>Registration No</b>	: SMR6388T	<b>Engine No</b>	: L15B35000191		
<b>Chassis No</b>	: JHMGK5850LS200867	<b>Date   Time</b>	: 31. Jan 2020 8:04:13 AM		
<b>Model</b>	: JAZZ 1.5VTIR CVT 20YM (EURO 6)	<b>Surveyor Name</b>	:		
<b>Owner's Name</b>	: WONG SHEE NAM	<b>Survey Date</b>	:		
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	: 30/1/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER: WONG SHEE NAM						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 30/01/2020						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED						
	TP VEH: SHC8539A						
04715-T5B-J50ZZ	FACE,RR.BUMPER <i>Deep Cut</i>	1	515.50	25	386.62	27.06	413.68
91505-TM8-003	CLIP,BUMPER <i>net</i>	9	2.30	25	15.52	1.09	16.61
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>11</i>	1	17.30	25	12.97	0.91	13.88
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>11</i>	1	17.30	25	12.97	0.91	13.88
71507-T5A-J60	COVER,L.RR.BUMPER <i>11</i>	1	21.20	25	15.90	1.11	17.01
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6 <i>CU</i>	1	792.40	25	594.30	41.60	635.90
42200-T5B-N52	BEARING ASSYRR.HUB	1	295.00	25	221.25	15.49	236.74
42100-T5A-J75	BEAM ASSYRR.AXLE <i>11</i>	1	934.70	25	701.02	49.07	750.09
	<b>Sum Item</b>				<b>1960.55</b>	<b>137.24</b>	<b>2,097.79</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	<b>Sum Ext. Service</b>				<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
BOSUN	SUNDRIES <i>net</i>	1	50.00	20	50.00	3.50	53.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	130	180.00	12.60	192.60
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS. (N)	1	680.00	?	680.00	47.60	727.60
BKFE21K	STRAIGHTEN RR L FENDER & RENEW RR BUMPER	1	1500.00	560	1500.00	105.00	1605.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1500.00	900	1500.00	105.00	1605.00

Printed on 31/1/2020 8:14:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

**Registration No** : SMR6388T

**Chassis No** : JHMGK5850LS200867

**Model** : JAZZ 1.5VTIR CVT 20YM (EURO 6)

**Owner's Name** : WONG SHEE NAM

**Ins Policy No.** :

**Date of Accident** : 30/1/2020

**Document No.** : SQT20000490 **Page** 2

**Date** : 31. Jan 2020

**Customer No.** : WZF002

**Svc Advisor** : RUEBEN THOMAS

**Engine No** : L15B35000191

**Date | Time** : 31. Jan 2020 8:04:13 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					3910.00	273.70	4,183.70

Survey By Mercy LLL

Date & Time 31/1/20

Excess not stated

Status not stated

Signature To be signed before repair, 4 days.

**Total Amount** 6,050.55 423.54 6,474.09

**Total (Inclusive of GST)** 6,474.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Printed on 31/1/2020 8:14:42 AM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.