

First Capital
3/2/2020



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 6196 U

*Not Authorized
Resurvey By Repair*

Parts	(a) Cost / List Price Items	\$	<u>3,381.95</u>
	Plus/Less 25%	\$	<u>845.49</u>
	Total of Cost / List	\$	<u><u>2,536.46</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items	\$	<u>200.00</u>
Total Parts Cost		\$	<u><u>2,736.46</u></u>
Labour		\$	<u><u>1,570.00</u></u>
Total		\$	<u><u>4,306.46</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 3/2/20 at 11:30am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 3/2/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SMA 6196 U Submit By : Carmen Lim
 Make & Model : TOYOTA PRIUS Year Manufacture : 2016
 Chassis No : ZVW508037188 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	1	\$200.00	S.N	X
2	Rear bumper <i>Bu</i>	1	\$497.50		✓
3	Rear bumper clip <i>nc</i>	10	\$40.00		—
4	Rear bumper side retainer LH <i>Dis</i>	1	\$112.70		✓
5	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90	NN	?
7	Rear bumper lower garnish centre <i>Red</i>	1	\$582.60		—
8	Rear bumper lower garnish LH <i>ngcm</i>	1	\$149.70		—
9	Rear bumper under cover <i>Sn</i>	1	\$355.20		X
10	Tail lamp LH - UPPER <i>Rh</i>	1	\$498.75		X
11	Tail lamp LH - LOWER <i>cm</i>	1	\$511.60		✓
12	LH rear fender undershield	1	\$92.30	NN	?
13	LH rear fender undershield clip	10	\$30.00	NN	?
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

