55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 28622

#### **Telefax**

Estimate : Accident Repairs
Workshop : Ubi Road 1

Contact No : 6366 2323 Fax No : 6841 1183

Reference : PA/TP/0144/2020/NS

Date : 6-Feb-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLJ 4929 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tan Hwee Lim
Address : 29 east Coast Terrace

Singapore 458940

 Telephone
 : (HP) +65 90489970

 Type of Claim
 op : Third Party Claims

 Policy No.
 : 1900164915

Vehicle No : SKX 9512 ¥Z

Model Code : Audi A4 2.0 TFSI 8W

Model / Year : 27/9/2019 Engine No : CVK 082516

Chassis No : WAUZZZF4XKA076654

Mileage : Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 1-Feb-20

Place of Accident : Cross Junction Traffic Light Kampong Java

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

## Estimated Labour Charges for Accident Vehicle. SKX 9512 X/Z

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 /	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	00	\$ 1,050.00 76	of 500
3	To respray rear bumper. 700		\$ 900.00 74	+ 550
4	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 2,502.00	

Steve 7/2/20

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SKX 9512 ¥2

C/N	Doubs Description			Damaged Parts & Prices S/Nett Remarks	
S/N	Parts Description			3/ Nett	Kemarks
1	REAR BUMPER / 00		\$	2,570.00	
2	REAR BUMPER FIXING PARTS		\$	433.00	
3	REAR BUMPER SECURING STRIP / MC		\$	210.00	
4	REAR BUMPER SPOILER /		\$	234.00	
5	REAR BUMPER TRIM / (M)		\$	275.00	
6	REAR BUMPER BRACKET - LH / RH $ imes$ NN	2	\$	220.00	
7	REAR LIGHT REFLECTOR - LH / RH $ imes$ NN	2	\$	78.00	
8	REAR BUMPER CARRIER		\$	845.00	
9	REAR BUMPER SEAL / NC	2	\$	26.00	
10	REAR BUMPER GUIDE SECTION - LH / RH $ imes$ NN	2	\$	42.00	
11	REAR BUMPER HOLDING STRAP - LH / RH ×NN	2	\$	156.00	
12	REAR PARKING AID SENSOR - INNER / OUTER $ imes$	2	NN	TBC	
13	REAR PARKING AID SEAL RING / M	4	\$	14.00	
14	SUNDRIES ?		\$	200.00	
	TOTAL SPARE PARTS CHARGES	:	Ś	5,303.00	
	TOTAL LABOUR CHARGES			2,502.00	
	GRAND TOTAL	:	\$	7,805.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Steve (LKK) WL M/L 7/2/20, 1.10 pm : 3 dys

P/P MBLM

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo Body Repair Manager Allan Wu Claims Consultant