

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001819/T1PA3Q2

Date: 08/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMN7554U	Insured Vehicle No :	SHA1813P
Date of Loss: 30/01/2020	Nature of Claim: TP	Claim No: MCT20010719

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7554U		
Make & Model:	BMW 420I, 2.0 Gran Coupe (A)	Engine No:	F3323415B48B20A
Reg. Date:	28/08/2019 (Man. Year: 2019)	Chassis No:	WBA4H32090BX80719
Colour:	Blue	Odometer:	11082 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40.00	40.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,530.00	1,974.00	556.00	21.98
+ GST 7.00/7.00% (S\$)	177.10	138.18	38.92	21.98
Nett Amount (S\$)	2,707.10	2,112.18	594.92	21.98
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
Nett Liability (S\$)		2,497.38		

INSPECTION

Date of Assignment:	03/02/2020	
Date Inspected:	31/03/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Apr 2020)	
Parts:	N/A	BMW 420I 2.0 Gran Coupe (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN7554U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett.
Total Parts (S\$)					40.00	40.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR BUMPER	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >