

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

03 FEB 2020

E S T I M A T E

Estimate No. : b1 54304
Date Estimated : 31/01/2020
Prepared By : Shukhaizi Bin Misbah

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Eric Lee Aik Phong (Li YiPeng)
10 Hougang Street 11
#12-29

Singapore 534080

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMN7554U	WBA4H32090BX80719	28/08/2019	420i GC	0

DESCRIPTION

To repair rear bumper

850 1,275.00

Painting rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

sundries

rec ✓ 40.00

Total Labour 1: 2,530.00

1974
03 days



Labour 1	:	2,530.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	177.10
Grand Total	:	2,707.10

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **