


PROGRESSIVE
CAR CARE PTE LTD
Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

TP INSURER:

India International Insurance Pte Ltd (HQ)

NA

Singapore

Claimant Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
 Policy No:
 Vehicle Reg. No.: **SKJ660L**
 Party At Fault: UNKNOWN
 Driver (TP): LI ZHI DEREK

Ref. No: TP 0120-5851
 Date of Loss: 25/01/2020
 Driveable?

Make/Model: BMW X3, 2.0 SDRIVE 20I LED SR NAV (A)
 Vehicle Colour: BLACK
 Engine No: B5691283N20B20A
 Odometer: 63302 KM

Vehicle Reg. Date: 27/02/2016
 Chassis No: WBAWY920200J00232

Paint Type:
 Total Loss?
 Est. Duration of Repair (day)

NO
5

Description of Accident/Loss: REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Remarks: VEHICLE IS NOT IN WORKSHOP

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	4,573.20
Miscellaneous Items	11.00
Labour	1,060.00
Paintwork Labour	700.00
Towing	0.00

Gross Total (S\$)	6,344.20
+ GST 7.00% (S\$)	444.09
Nett Amount (S\$)	6,788.29

This claim is handled by: **NG PEI WEN**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Feb 2020)

Parts: M1-SUV BMW X3 2.0 SDRIVE 20i LED SR NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SKJ660L/01/02/2020 13:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT FENDER OUTER ARCH GARNISH - LH <i>Torn</i>	0.00	0.00	*180.70 F ✓
2	1	NA	*FRONT FENDER - LH <i>Bad 600</i>	0.00	0.00	*808.05 F ✓
3	1	NA	*FRONT FENDER CHROME - LH <i>11</i>	0.00	0.00	*71.75 F X
4	10	NA	*FRONT FENDER COWLING CLIPS - LH <i>all</i>	0.00	0.00	*50.00 F ✓
5	1	NA	*FRONT FENDER COWLING (FRONT) - LH	0.00	0.00	*134.70 F ✓
6	1	NA	*FRONT FENDER COWLING (REAR) - LH	0.00	0.00	*134.70 F ✓
7	1	NA	*FRONT MUDFLAP - LH <i>11</i>	0.00	0.00	*-F X
8	1	NA	*FRONT FOG LAMP COVER - LH	0.00	0.00	*75.45 F ✓
9	1	NA	*FRONT FOG LAMP	0.00	0.00	*453.25 F ✓
10	1	NA	*FRONT BUMPER <i>cut</i>	0.00	0.00	*1,580.60 F ✓
11	10	NA	*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*50.00 F ✓
12	1	NA	*FRONT BUMPER PROTECTOR /LOWER SPOILER - LH <i>scr</i>	0.00	0.00	*290.50 F ✓
13	4	NA	*FRONT BUMPER SENSOR	0.00	0.00	*952.20 F ?
14	4	NA	*FRONT BUMPER SENSOR RUBBER	0.00	0.00	*32.00 F ?
15	1	NA	*FRONT BUMPER SENSOR WIRE <i>11</i>	0.00	0.00	*-F X
Sub Total (\$\$)						4,813.90
- Add. Disc. on L,N Items 5.00% (\$\$)						240.70
Total Parts (\$\$)						4,573.20

Progressive Car Care Pte Ltd/SKJ660L/01/02/2020 13:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2/1/2020

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TO RESPRAY PAINT ON ACCIDENT PORTIONS

New

400

700.00

Labour Items

2 TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS

New

300

700.00

3 TO CHECK WIRING

New

20

20.00

4 TO TUFF-KOTE

New

30

120.00

5 TO 4 WHEEL ALIGNMENT

New

60

120.00

6 TO REMOVE; REPLACE/REFIX REAR BUMPER SENSOR

New

40

100.00

Gross Labour Cost (\$)

1,760.00

Progressive Car Care Pte Ltd/SKJ660L/01/02/2020 13:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.