



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMH 7234 A

Not Authorized
Running B4 paint

Parts	(a) Cost / List Price Items	\$	4,705.00
	Plus/Less 10%	\$	470.50
	Total of Cost / List	\$	4,234.50
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	970.00
Total		\$	5,204.50

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Hennrich
Company : LKK
Survey conducted on : 31/2/2020 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : L Date: 31/2/2020



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMH 7234 A**
Make & Model : **BMW 420i**
Chassis No : **WBA4H32040BP28866**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>RM</i>	1	\$1,037.00		<i>✓</i>
2	Front bumper clip <i>RM</i>	10	\$50.00		<i>✓</i>
3	Front bumper reinforcement <i>R</i>	1	\$447.00		<i>X</i>
4	Front bumper side retainer LH <i>RM</i>	1	\$48.00		<i>X</i>
5	Front bumper side retainer RH	1	\$48.00		<i>7</i>
6	Front bumper bracket LH <i>R</i>	1	\$35.00		<i>X</i>
7	Front bumper bracket RH <i>R</i>	1	\$35.00		<i>X</i>
8	Front bumper sponge <i>RM</i>	1	\$55.00		<i>X</i>
9	Front bumper sensor RH	1	\$268.00		<i>7</i>
10	Headlamp RH	1	\$2,682.00		<i>7</i>
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

