



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003562  
INV Date 29/04/2020  
Reference CC3/CTI20001836/Fea3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 4489S  
Insured Veh. SJH 9215C  
Claim No. SNM20D200502  
Policy No. DMPCSN3055961901  
Accident Date 23/01/2020  
Inspection Date 24/01/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20001836/Fea3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-04-2020



Code : CTI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 9215C	Veh. Inspected	SHB 4489S
Policy No.	DMPCSN3055961901	Coverage (\$)	0.00
Claim No.	SNM20D200502	Excess (\$)	0.00
Assign From		Assign Date	24/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMHU097720	Colour	BLUE
Odometer	368925	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	6 mm
L/H Front Tyre	205/60 R16	HANKOOK	6 mm
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND FRONT PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	23/01/2020	Inspection Date	24/01/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4489S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	BROKEN	544.50	544.50
1	FRONT BUMPER SIDE BRACKET -RH	NOT NECESSARY	24.60	-
1	FRONT BUMPER TOP BRACKET -RH	NOT NECESSARY	22.40	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER GRILLE -RH	NOT NECESSARY	41.60	-
1	HEADLAMP -RH	BROKEN	1,388.00	1,388.00
1	HEADLAMP SUPPORT PANEL	NOT NECESSARY	907.40	-
1	FRONT FENDER -RH	BUCKLED	566.30	566.30
1	FRONT FENDER SHIELD -RH	NOT NECESSARY	174.90	-
1	FRONT WHEEL COVER -RH	SCRATCHED	107.10	107.10
1	BONNET	TO REPAIR SEE LABOUR	2,265.90	-
1	BONNET HINGE -RH	NOT NECESSARY	41.00	-
1	STEERING TIE ROD END -RH	NOT NECESSARY	62.60	-
	LESS 20% DISCOUNT		-1,233.66	-525.58
			4,934.64	2,102.32
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	ADVERTISEMENT -LHF FENDER (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET .		600.00	560.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	TUFF KOTE.		50.00	30.00
	WIRING CHARGE.		50.00	50.00
	FRONT WHEEL ALIGNMENT.		120.00	80.00
			1,320.00	1,120.00
	<b>GRAND TOTAL</b>		<b>6,354.64</b>	<b>3,322.32</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,650.00</b>

Report Ref No. CC3/CTI20001836/Fea3n2



Report Ref No. CC3/CTI20001836/Fea3n2

A handwritten signature in black ink, appearing to be 'Parasuram' with a stylized flourish.

**PARASURAM S/O SHANMUGAM**

**Asst. Automotive Assessor**

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan' with a stylized flourish.

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**